

requested

NPDES Permit required

☐ Phased Constr.

 $\bowtie$ 

Permit #:

E & S Permit required ☐ ESCGP Permit required

☐ Non-Phased Constr.

Exp. Date:

#### COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION **BUREAU OF WATERWAYS ENGINEERING AND WETLANDS**

Permit No.	ESG0300015002	
Report No.	1	

#### EARTH DISTURBANCE INSPECTION REPORT Project Name PA Pipeline Project/Mariner East 2 Inspection Date 8/25/2017 Inspection Time 1145 Weather Conditions Partly cloudy, warm, light winds. Total Project Area Total Disturbed Area \_\_\_\_\_ Location Immediately south of the PA Turnpike Bridge Municipality\_Fairview TWP/Highspire Boro & Lower Swatara TWP\_ County\_York/Dauphin Receiving Water(s) Susquehanna River Designated/Existing Use WWF Precision Pipeline, LLC - David Bell Responsible Party(s) Sunoco Pipeline, L.P. - Matthew Gordon 3314 56th Street 525 Fritztown Road (name & address) Sinking Spring, PA 19608 Eau Claire, WI 54703 Site Representative (name) Adam Fisher Inspector (name) Ron Eberts (title) Lead Environmental Inspector Compliance Specialist Photographs Taken Yes No 🗌 Type of Inspection (check only one) Routine partial X Follow-up Routine complete Complaint Final Site Description & Observations Present during this inspection were Ron Eberts of PA Department of Environmental Protection ("Department") and Adam Fisher, Lead Environmental Inspector. The areas inspected ("Site") were the HDD pads on the west side (Fairview Township, York County) and east side (Highspire Borough, Dauphin County) of the Susquehanna River "River"), and the Inadvertent Return ("IR") that occurred in the River (Lower Swatara Township, Dauphin County). Neither HDD was in operation at the time of the inspection. Both HDD operators told me that they resumed drilling operations on August 23, 2017 and shut down at approximantely 1500 hours on Aug. 24, 2017. After inspecting the HDD sites, I proceeded out on the River to inspect the IR. The IR was found approximately 200 feet from the west shoreline, and approximately 75-feet downstream from the projected drill path. This was the same location that a previously IR had occurred. The previous IR was discovered on August 17, 2017, with a reported release of approximately 495 gallons of bentonite drilling mud. The new IR was estimated to be 50 gallons (v). □ Continued on page 3 of 3 □. Permit and Plan Requirements Type of Activity (check as many as appropriate) Other Υ N Pvt. Road/Residence (PRRS) Written Erosion & Sediment Plan required П Pub. Road Constr./Maint. (PRC) $\boxtimes$ Written Post Construction Stormwater Management Res. Subdivision (RSBD) Comm./Indust. Dev. (CMIN) Plan required Erosion & Sediment Plan requested Govmt. Facilities (GOV) Recreation Facilities (RECF) $\bowtie$ Post Construction Stormwater Management Plan Utilities Facilities (UTL) Agricul. Activities (AGA) $\boxtimes$

Sewer/Water Systems (SWS)

Remediation/Restoration (RRES)

 $\bowtie$ 

Pipeline (PL)

Silviculture (SILV)

### 3150-FM-BWEW0092 Rev. 1/2016 pennsylvania DEPARTMENT OF ENVIRONMENTAL PROTECTION

#### COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF WATERWAYS ENGINEERING AND WETLANDS

Permit No.	ESG0300015002		
Report No.	1		

## EARTH DISTURBANCE INSPECTION REPORT

Project Name PA Pipeline Project/Mariner East 2 Inspection Date 8/25/2017			n Date <u>8/25/2017</u>	7 Inspection Time 1145		
Inspe	ectio	on Findings			Reference	
	No	violations observed at this time.			☐ (N/A)	
					П и оо и	
		Failure to develop a written Erosion and Sediment (E&S)	Plan.		(102.4)	
	b.	Failure to have an E&S Plan available onsite.			(102.4)	
	C.	Failure to submit an E&S Plan as requested.			☐ (102.4)	
	d.	Failure to implement effective E&S Best Management Pra	ctices (BMPs).			
	e.	Failure to maintain effective E&S BMPs.			(102.4)	
	f.	Failure to use Antidegradation Best Available Combinati for discharges to High Quality or Exceptional Value Water	S.		(102.4)	
	g.	Failure to obtain an NPDES Permit for Stormwater Discl Activities.	narges Associated with	Construction	(102.5)	
	h.	Failure to obtain an E&S Permit.			(102.5)	
	i.	Failure to prepare and implement a Preparedness, Preven	ntion, and Contingency (	PPC) Plan.	(102.5)	
	j.	Failure to submit a Notice of Termination (NOT).			(102.7)	
	k.	Failure to develop a written Post Construction Plan/Restoration Plan.	Stormwater Manageme	ent (PCSM)	(102.8)	
	1.	Failure to have PCSM Plan/Restoration Plan available on	site.		(102.8)	
×	m.	Failure to submit PCSM Plan/Restoration Plan as request	ed.		☐ (102.8)	
	n.	Failure to implement effective PCSM BMPs.			(102.8)	
	Ο.	Failure to maintain effective PCSM BMPs.			☐ (102.8)	
	p.	Failure to perform reporting and recordkeeping as require	d.		(102.8)	
	q.	Failure to implement riparian buffer or riparian forest buffer	er.		(102.14)	
	r.	Failure to meet regulatory requirements for riparian forest			☐ (102.14)	
	S.	Failure to provide temporary stabilization of the earth dist		2	☐ (102.22)	
	t.	Failure to provide permanent stabilization of the earth dist			(102.22)	
	u.	Failure to comply with permit conditions.				
	٧.	Sediment or other pollutant was discharged into waters of	f the Commonwealth.			
	W.	Site conditions present a potential for pollution to waters of	of the Commonwealth.		☐ (402 CSL)	
	Χ.	Failure to comply with a Department Order.			(402, 611 CSL	
	у.	Failure to comply with PCSM long-term operation and ma	intenance requirements	1	(102.8)	
	Z.	Failure to conduct a preconstruction meeting.			(102.5)	
	aa.	Failure to provide proof of consultation with the Peni regarding the presence of a State or Federal threatened site requiring a Chapter 102 permit.	nsylvania Natural Herita or endangered species	age Program on a project	☐ (102.6)	
	bb.	earth disturbance activities, which require a Department conservation district has approved/acknowledged the Characteristics.	ent permit, until the D	or conducting epartment or	□ (102.43)	

Inspection of this project has revealed site conditions which constitute violations of 25 Pa. Code Chapters 92a  $\boxtimes$ and/or 102 and the Clean Streams Law, the act of June 22, 1937, P.L. 1987, 35 P.S. §691.1 et seq.

Additional information regarding these violations can be found on the back of this page.

# 3150-FM-BWEW0092 Rev. 1/2016 pennsylvania DEPARTMENT OF ENVIRONMENTAL PROTECTION

#### COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF WATERWAYS ENGINEERING AND WETLANDS

Permit No.	ESG0300015002		
Report No.	1		

EARTH DISTURBANCE INSPECTION REPORT			
Project Name PA Pipeline Project/Mariner East 2 Inspection Date 8/25/2017 Inspection Time 1145			
Site Description & Observations The original IR was never contained, nor successfully recovered (u, v). The IR has naturally stayed in place on the riverbed and is approximately 35-feet X 20-feet in size. At the time of my inspection, the Responsible Parties had not installed any Best Mangement Practices to try to contain or recover the IR (d). A voicemail message notifying me of the IR was left for me on August 24, 2017 at 5:22 p.m. after I had left the office for the day. The PA DEP Southcentral Regional Office Emergency Response team was never notified (u). The Department received the Inadvertent Return Form on August 25, 2017. The Department did not approve the restart of drilling operations.  The Site is also associated with Permit No. E22-619.			
Compliance Assistance Measures			
DEP requests that the responsible parties complete the following actions:			
<ul> <li>Follow the approved HDD Inadvertent Return Assessment, Prepardness, Prevention and Contingency Plan</li> </ul>			
("HDD IR PPC Plan"), revised August 8, 2017. As stated on page 7 of the HDD IR PPC Plan,			
If the inadvertent return is 50 gallons or greater, or of unknown quantity, or is a second or subsequent inadvertent return at an HDD location, drilling operations will be suspended until PADEP inspects the site, concludes that further drilling will not result in additional returns of 50 gallons or greater, and approves a restart of drilling operations. Periods of contractor downtime and the contractor's drilling fluid pumping rate will also be documented to estimate inadvertent return volumes.			
<ul> <li>Suspend HDD operations until DEP approves as restart of drilling operations.</li> </ul>			
Submit any additional or final IR reporting form(s) as required by the HDD IR PPC Plan.			
<ul> <li>Submit a containment and restoration plan providing for the remediation of the current extent of the IR and any furture IRs that may reoccur at this location through the completion of HDD activities. The plan should be submitted to Ronald Eberts of DEP at reberts@pa.gov by 9/6/2017.</li> </ul>			
<ul> <li>Submit drilling logs for the Susquehanna River HDD, for both the east and west shore drill pits, covering the time period from initiation of the drill through August 30, 2017. The logs should document the following for each day of activity: start and top times of drill, stage of HDD process, approximate progress along the drill alignment, drill pressure, depth of cover, any loss of pressure and/or mud (including volumes), and whether water visibility conditions in the Susquehanna River would have allowed for the river survey crew to observe any IRs that may have occurred.</li> </ul>			
Follow-up Inspection will occur on or about (date)  Written in the office  Mass needed  mailed/emailed to RPs on 8/30/17  8/30/2017			

(Signature of Site Representative) (Date) (Inspector's Signature) (Date)
The Site Representatives' signature acknowledges that they have read the report and received a copy and that they were given an opportunity to discuss it with the inspector. The signature does not necessarily mean the signee agrees with the report.

This report is official notification that a representative of the Department of Environmental Protection has conducted an inspection of your earth disturbance activity to determine compliance with Title 25, Chapter 92a, National Pollutant Discharge Elimination System, Title 25, Chapter 102, Erosion and Sediment Control, and the Pennsylvania Clean Streams Law. This representative may be an employee of the local County Conservation District, which by delegation agreement with the Department of Environmental Protection, is authorized to investigate complaints, inspect earth disturbance activities and conduct compliance actions. Any violations observed by the Department/Conservation District have been noted on this report form and constitute unlawful conduct as defined in Section 611 of the Clean Streams Law.

There will be no written confirmation of those violations from the Department. Failure to take corrective actions to resolve the violations may result in administrative, civil and/or criminal penalties being instituted by the Department of Environmental Protection as defined in Section 602 of the Clean Streams Law of Pennsylvania. The Clean Streams Law provides for up to \$10,000 per day in civil penalties, up to \$10,000 in summary criminal penalties, and up to \$25,000 in misdemeanor criminal penalties for each violation.

This report does not constitute an Order or appealable action of the Department. Nothing contained herein shall be deemed to grant or imply immunity from legal action for any violation noted herein.

For further information or assistance please contact:

Ronald Eberts PA DEP-SCRO 909 Elmerton Avenue Harrisburg, PA 17110 reberts@pa.gov 717.705.4819 Project Name: PA Pipeline Project, ME2 Inspection Date: August 25, 2017

Municipality: Fairview Township/Highspire Borough and Lower Swatara Township

County: York/Dauphin
Photos Take by: Ron Eberts

Inspection Report: No. 1



East Shore HDD Mud Pit (Highspire Borough, Dauphin County)



IR on riverbed approximately 35' X 20' (Lower Swatara Township, Dauphin County)



Edge of IR on riverbed (Lower Swatara Township, Dauphin County)



Above view of IR on riverbed (Lower Swatara Township, Dauphin County)

