

Commonwealth of Penns.

DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF SURFACE MINE RECLAMATION
INSPECTION
REPORT

Minir it No. 733-585(A)
Drainage Permit No. 7974SM1
Mine Inspection No. 5-54
Reinspection No. 2-79

Company <u>General Gashed Stone Co</u>	Mine Location: County <u>Bucks</u>	Township <u>E. Pechhill</u>
Mining Permit Acres Affected <u>48</u>	Drainage Permit Acres Affected <u>68</u>	
Status of Operation: Active <u>X</u>	Inactive	Not Started

- 1. Is this operation in compliance with the Safety Rules and Regulations? YES ___ NO ___ NOTED X
- 2. Is this mine operating in compliance with the conditions of the mining permit? YES ___ NO ___ NOTED X
- 3. Is the mine operating in compliance with the conditions of the mine drainage permit? YES ___ NO ___ NOTED X

REMARKS AND RECOMMENDATIONS: Repair windshield on utility pick up truck.

Discharge located near railroad switch is clear.

File request for an exception to mine a 90 foot highwall within 30 days. 90 foot highwall located between access road to quarry and the access road to the explosives magazine.

Note: Operator is re-reflecting an area mined prior to 1-1-72.

Sedimentation control facilities needed near the East end "dump" site.

The number 6 basin is to be cleaned out - promptly.

Loose rock on E side HW has been removed.

Company Official Contacted <u>Don Costanzo</u>	Title
Mine Inspector <u>Paul T. Surfass</u>	Inspection Date <u>8-15 & 16-79</u>

INSPECTORS' RECOMMENDATIONS TO BUREAU: No action necessary at this time.

The Operator is in the process of making corrections.