

1988 thru 2014 FATAL HISTORY

COMPANY	DATE OF ACCIDENT	MINE	ACCIDENT CLASSIFICATION	DIVISION	SHORT DESCRIPTION OF ACCIDENT	AGE
AMFIRE MINING CO						
	2/25/2008	NOLO	POWERED HAULAGE	BITUMINOUS	VICTIM WAS SETTING UP SURVEY STATION IN THE SHUTTLE CAR ROADWAY WHEN HE WAS STRUCK AND RAN OVER BY A SHUTTLE CAR.	50
	7/11/2008	NOLO	MACHINERY	BITUMINOUS	VICTIM WAS PINNED AGAINST COAL RIB BY A BELT FEEDER.	62
BETHENERGY MINES INC						
	11/3/1988	BETH 33B	MACHINERY	BITUMINOUS	VICTIM WAS PERFORMING MINE EXAMINER DUTIES, RIDING IN JEEP AND FOR SOME UNKNOWN REASON RAN INTO TAIL OF ROCK LOADER, SUSTAINING CRUSHING INJURIES OF THE CHEST.	36
	6/10/1990	BETH 33B	MACHINERY	BITUMINOUS	PORTAL BUS WAS TRAVELING ALONG NO 4 TRACK WHEN VEHICLE DERAILED AT THE NO 6 CHUTE NORTH MANUAL TRACK SWITCH. VICTIM WAS THROWN OUT OF PORTAL BUS AND PINNED BETWEEN BUS AND CEMENT BLOCK WALL CAUSING FATAL CRUSHING INJURIES.	46
	5/19/1992	BETH 33 PREP PLNT	MACHINERY	BITUMINOUS	DOZER OPERATOR WAS PUSHING COAL INTO NO 4 FEEDER. OPERATOR WAS BACKING UP AND DOZER FELL CAB END FIRST INTO A VOID AT THE NO 2 FEEDER.	61

COMPANY	DATE OF ACCIDENT	MINE	ACCIDENT CLASSIFICATION	DIVISION	SHORT DESCRIPTION OF ACCIDENT	AGE
BIRD COAL CO	4/29/1988	BIRD #2 MINE	OTHER (NATURAL DEATH)	BITUMINOUS	VICTIM FOUND UNRESPONSIVE UNDERGROUND. VICTIM DIED OF HEART ATTACK.	61
COMMERCIAL STONE CO INC	4/26/1993	SPRINGFIELD PIKE	EXPLOSION/IGNITION	INDUSTRIAL MINERALS	VICTIM WAS AIR ARC WELDING, HE SHUT OFF TORCH AND PLACED IT IN THE TANK COMPARTMENT. ACETYLENE GAS LEAKED FROM TORCH INTO TANK COMPARTMENT. VICTIM WAS BLOWN 16 FEET BY THE FORCE OF THE EXPLOSION.	38

COMPANY	DATE OF ACCIDENT	MINE	ACCIDENT CLASSIFICATION	DIVISION	SHORT DESCRIPTION OF ACCIDENT	AGE
CONSOL	11/16/1994	MINE 84	FALL OF FACE-RIB	BITUMINOUS	VICTIM WAS PERFORMING HIS DUTIES WHEN A LARGE PORTION OF THE MINE WALL SEPARATED AND FELL, STRIKING VICTIM IN THE BACK CAUSING FATAL INJURIES.	45
	2/7/1997	BAILEY	MACHINERY	BITUMINOUS	CO-WORKER JOGGED STAGELoader CONVEYOR CHAIN, VICTIM WAS PULLED THROUGH THE STAGELoader AND UNDERNEATH THE CRUSHER, CAUSING VICTIM TO RECEIVE CRUSHING INJURIES.	42
	3/28/1997	MINE 84	MACHINERY	BITUMINOUS	POSITIONED BETWEEN CONTINUOUS MINER AND RIB OBSERVING DIAGNOSTIC INDICATORS. WHILE USING REMOTE CONTROL UNIT, VICTIM CAUSED THE MINING MACHINE TO MOVE ENTRAPPING HIMSELF.	44
	10/29/2000	BAILEY	MACHINERY	BITUMINOUS	WELD HOLDING EYELET TO STEEL BEAM IMBEDDED IN CONCRETE STRUCTURE FAILED, CAUSING FATAL INJURIES TO VICTIM.	50
	5/11/2002	MINE 84	ELECTRICAL	BITUMINOUS	VICTIM EXITED COAL HAULER WHILE MACHINE FRAME WAS ENERGIZED.	46
	4/5/2007	MINE 84	SLIP OR FALL	BITUMINOUS	STANDING BEHIND BOLTING MACHINE, AS HE STEPPED BACK TO CHECK THE TRAILING CABLE, HE SLIPPED ON WET UNEVEN BOTTOM, INJURING LEFT ANKLE. VICTIM PASSED AWAY ON 4-28-07 DUE TO COMPLICATIONS RELATED TO HIS INJURY.	50
	6/23/2009	BAILEY	FALL OF ROOF	BITUMINOUS	VICTIM WAS STRUCK BY PIECE OF ROCK, CAUSING FATAL CRUSHING INJURIES.	54

COMPANY	DATE OF ACCIDENT	MINE	ACCIDENT CLASSIFICATION	DIVISION	SHORT DESCRIPTION OF ACCIDENT	AGE
COOLSPRING	8/18/2008	COOLSPRING	MACHINERY	INDUSTRIAL MINERALS	CHAIN BEING USED TO LIFT COUNTERWEIGHT FAILED, CAUSING COUNTERWEIGHT TO STRIKE VICTIM.	28
DOVERSPIKE BROS COAL CO INC	7/20/1994	DORA 6	OTHER (POWERED HAULAGE)	BITUMINOUS	VICTIM WAS RUN OVER AND PINNED UNDER AND BETWEEN TWO P-242 TRACTORS.	55
DYNAMIC RECOVERY INC	9/25/1990	PITT GAS	FALL OF ROOF	BITUMINOUS	UNINTENTIONAL ROOF FALL, TRAPPED, VICTIM DIED OF CRUSHING INJURIES.	57
FOUNDATION COAL	4/10/1996	CUMBERLAND	MACHINERY	BITUMINOUS	MOVING STAGELoader FROM FACE WHEN DUKE JACK CAME LOOSE AND STRUCK THE VICTIM CAUSING FATAL INJURIES.	41
GENESIS INC (PARKWOOD)	6/27/2001	SOLAR 7	FALL OF ROOF	BITUMINOUS	OPERATING A CONTINUOUS MINER VIA REMOTE CONTROL WHEN FATALLY INJURED BY A ROOF FALL.	29
GRAYMONT (PA) INC	2/8/2004	GRAYMONT	SLIP OR FALL	INDUSTRIAL MINERALS	VICTIM SLIPPED/TRIPPED FROM THE TOP OF A TRAILER.	57
HELEN MINING CO	11/4/1989	HOMER CITY	MACHINERY	BITUMINOUS	OPERATING MINE LOCOMOTIVE, CRUSHED BETWEEN TOP OF LOCOMOTIVE AND RAILS ON ROOF.	39

COMPANY	DATE OF ACCIDENT	MINE	ACCIDENT CLASSIFICATION	DIVISION	SHORT DESCRIPTION OF ACCIDENT	AGE
JEDDO COAL CO						
	10/1/2004	JEDDO #8 PLNT	FIRE	ANTHRACITE	OPERATING A HAUL TRUCK, NOTICED AN OIL LEAK SPRAYING INTO THE ENGINE COMPARTMENT AND CAB AREA. BEFORE THE OPERATOR HAD GOTTEN OUT OF THE LOADER, THE LIQUID BURST INTO FLAMES TRAPPING THE VICTIM INSIDE THE CAB.	51
MAPLE CREEK MINING INC						
	10/26/1996	MAPLE CREEK	OTHER (POWERED HAULAGE)	BITUMINOUS	MOTOR OPERATED BY VICTIM WAS PULLED UNDER A SKID STRIKING HIM CAUSING FATAL INJURIES.	42
	7/1/1997	MAPLE CREEK	FALL OF FACE-RIB	BITUMINOUS	VICTIM WAS WORKING AS BELT REPAIRMAN UNDERGROUND WHEN HE WAS STRUCK BY A FALLING SECTION OF THE MINE ENTRY WALL.	43
MEARS ENTERPRISES INC						
	11/5/1993	PENN RUN	MACHINERY	BITUMINOUS	SERVICING CONTINUOUS MINING MACHINE WHEN THE AUGER WAS ACCIDENTLY STARTED, DRAGGING VICTIM UNDER THE AUGER BY THE CUTTING BITS.	40
MON VIEW MINING CO						
	6/17/1995	MATHIES	OTHER (POWERED HAULAGE)	BITUMINOUS	VICTIM RECEIVED CRUSHING INJURIES AS THE RESULT OF BEING CAUGHT BETWEEN A STATIONARY AND MOVING OBJECT.	56
MT SPRING COAL CO						
	6/13/2003	MINE NO 1	ELECTRICAL	BITUMINOUS	SUBSTATION WAS NOT DE-ENERGIZED, VICTIM WAS ELECTROCUTED.	41

COMPANY	DATE OF ACCIDENT	MINE	ACCIDENT CLASSIFICATION	DIVISION	SHORT DESCRIPTION OF ACCIDENT	AGE
NEW WARWICK MINING CO						
	7/28/1992	WARWICK	MACHINERY	BITUMINOUS	VICTIM FAILED TO SEEK REFUGE IN A PLACE OF SAFETY AND WAS IN THE MIDDLE OF THE TRACK ENTRY WHILE A TRIP OF LONGWALL SHIELDS WERE BEING TRANSPORTED.	41
PENN COAL INC						
	7/15/1997	SARAH	FALL OF ROOF	BITUMINOUS	VICTIM WAS KNEELING INBY THE REAR BUMPER OF CONTINUOUS MINER WHEN THE SUPPORTED ROOF ABOVE HIM FELL.	44
QUEMAHONING COLLIERIES						
	7/19/1993	QUEMAHONING NO 1	MACHINERY	BITUMINOUS	PERFORMING MAINTENANCE WORK ON CONTINUOUS MINER. CO-WORKER LEFT AREA, LEAVING VICTIM ALONE. WHEN SECTION FOREMAN WAS MAKING HIS PRE-SHIFT EXAM HE FOUND VICTIM CRUSHED BETWEEN COAL RIB AND CUTTER HEAD OF THE CONTINUOUS MINER.	40
R&D COAL COMPANY INC						
	10/23/2006	BUCK MT SLOPE	EXPLOSION/IGNITION	ANTHRACITE	VICTIM WAS FATALLY INJURED FROM FORCES OF A METHANE GAS EXPLOSION.	43
RAMPSIDE COLLIERIES						
	10/11/1989	MINE NO 1	ELECTRICAL	BITUMINOUS	VICTIM WAS ATTEMPTING TO STEAL COOPER WIRE FROM DE-ENERGIZED OVERHEAD LINE LEADING TO THE MINE. VICTIM WAS ELECTROCUTED.	19

COMPANY	DATE OF ACCIDENT	MINE	ACCIDENT CLASSIFICATION	DIVISION	SHORT DESCRIPTION OF ACCIDENT	AGE
ROSEBUD MINING CO						
	6/10/2005	TRACY LYNNE	FALL OR ROOF	BITUMINOUS	INSTALLING ROOF BOLTS WHEN THE ROOF COLLAPSED ON THE ROOF BOLTING MACHINE AND VICTIM.	26
	12/12/2005	LOGANSPORT	FALL OF ROOF	BITUMINOUS	ROOF ABOVE INTERSECTION COLLAPSED ON THE CONTINUOUS MINING MACHINE, CAUSING FATAL CRUSHING INJURIES.	37
	4/18/2008	LITTLE TOBY	MACHINERY	BITUMINOUS	AS THE MOBILE OPERATOR ADVANCED TOWARD THE CONTINUOUS MINER HE NOTICED THE MINER OPERATOR PINNED BETWEEN THE INBY END OF THE # 1 BRIDGE AND THE COAL RIB.	43
SUMMIT ANTHRACITE INC						
	7/16/1998	TRACY SLOPE MINE	EXPLOSION/IGNITION	ANTHRACITE	UNPLANNED DETONATION OF EXPLOSIVES CAUSING FATAL INJURIES TO THE VICTIM.	23
UAE COAL CORP ASSOC						
	9/27/1994	HARMONY	STRUCK BY	ANTHRACITE	ROOF FALL	0
	6/16/2008	HARMONY	FALL OF ROOF	ANTHRACITE	STRUCK AND PINNED AGAINST RIB BY FALLING ROCK.	0