

**APPENDIX L-3 – TABLE 1
 STREAMBANK STABILIZATION TABLE**

Resource ID	County	Milepost	Stream Bank Stabilization BMP^a
WW-T10-001	Lancaster	0.25	SBR with SC150 fabric
WW-T10-003	Lancaster	M-0147 0.59	SBR with SC150 fabric
WW-T10-003A	Lancaster	M-0147 0.59	SBR with SC150 fabric
WW-T10-004	Lancaster	M-0184 0.85	SBR with SC150 fabric
WW-T62-001	Lancaster	5.34	SBR with SC150 fabric
WW-T10-100	Lancaster	7.15	SBR with SC150 fabric
WW-T20-002	Lancaster	7.5	SBR with SC150 fabric
WW-T31-002A	Lancaster	8	SBR with SC150 fabric
WW-T31-002	Lancaster	8	SBR with SC150 fabric
WW-T65-001	Lancaster	8.11	SBR with SC150 fabric
WW-T31-003	Lancaster	8.2	SBR with SC150 fabric
WW-T25-1001	Lancaster	M-0405 1.45	SBR with SC150 fabric
WW-T65-1002	Lancaster	M-0417 0.06	SBR with SC150 fabric
WW-T10-1003	Lancaster	10.1	SBR with SC150 fabric
WW-T35-1002	Lancaster	10.88	SBR with SC150 fabric
WW-T35-1002A	Lancaster	11	SBR with SC150 fabric
WW-T49-1001	Lancaster	M-0248 0.16	SBR with SC150 fabric
WW-T93-1001	Lancaster	13.62	SBR with SC150 fabric
WW-T92-1002	Lancaster	M-0434 0.10	SBR with SC150 fabric
WW-T36-1004	Lancaster	M-0434 0.16	SBR with SC150 fabric
WW-T92-1003	Lancaster	13.88	SBR with SC150 fabric
WW-T36-1006	Lancaster	13.88	SBR with SC150 fabric
WW-T36-1007	Lancaster	14.64	SBR with SC150 fabric
WW-T20-1005	Lancaster	15.33	SBR with SC150 fabric
WW-T24-1001	Lancaster	17.01	SBR with SC150 fabric
WW-T11-2001	Lancaster	18.1	SBR with SC150 fabric
WW-T11-2002	Lancaster	18.85	SBR with SC150 fabric
WW-T24-2001	Lancaster	M-0389 0.14	SBR with SC150 fabric
WW-T10-2005	Lancaster	20.81	SBR with SC150 fabric
WW-T10-2004	Lancaster	22.36	SBR with SC150 fabric
WW-T10-2002	Lancaster	23.02	SBR with SC150 fabric
WW-T49-2001	Lancaster	M-0209 0.30	SBR with SC150 fabric
WW-T42-2003	Lancaster	23.89	SBR with SC150 fabric
WW-T31-3003	Lancaster	30.13	SBR with SC150 fabric

**APPENDIX L-3 – TABLE 1
 STREAMBANK STABILIZATION TABLE**

Resource ID	County	Milepost	Stream Bank Stabilization BMP^a
WW-T31-3004	Lancaster	M-0308 0.06	SBR with SC150 fabric
WW-T31-3009	Lancaster	30.63	SBR with SC150 fabric
WW-T31-3008	Lancaster	31.18	SBR with SC150 fabric
WW-T31-3006	Lancaster	32.27	SBR with SC150 fabric
WW-T31-3005	Lancaster	32.99	SBR with SC150 fabric
WW-T31-3002A/ WW-T31-3002	Lancaster	33.57	SBR with SC150 fabric
WW-T31-3001	Lancaster	34	SBR with SC150 fabric
WW-T24-3001A	Lancaster	34.4	SBR with SC150 fabric
WW-T24-3001	Lancaster	34.47	SBR with SC150 fabric
WW-T30-4001	Lancaster	36.04	SBR with SC150 fabric
^a BMP (Best Management Practices) Streambank Restoration Details (SBR) are located in Attachment 2 of Transco's Environmental Construction Plan (Attachment M).			