

**APPENDIX L-3 – TABLE 1
 STREAMBANK STABILIZATION TABLE**

Resource ID	County	MP	Stream Bank Stabilization BMP^a
WW-T44-10002C	Northumberland	83.37	SBR with SC150 fabric
WW-T01-10001	Northumberland	83.39	SBR with SC150 fabric
WW-T04-10002	Northumberland	85.45	SBR with SC150 fabric
WW-T04-10001	Northumberland	M-0240 0.20	SBR with SC150 fabric
WW-T18-10002	Northumberland	86.60	SBR with SC150 fabric
WW-T68-11001B	Northumberland	M-0372 0.11	SBR with SC150 fabric
WW-T68-11001	Northumberland	M-0372 0.13	SBR with SC150 fabric
WW-T58-11001	Northumberland	M-0235 1.15	SBR with SC150 fabric
WW-T44-11002	Northumberland	88.89	SBR with SC150 fabric
WW-T47-11002	Northumberland	91.76	SBR with SC150 fabric
WW-T44-11001A	Northumberland	M-0271 .03	SBR with SC150 fabric
^a BMP (Best Management Practices) Streambank Restoration Details (SBR) are located in Attachment 2 of Transco's Environmental Construction Plan (Attachment M).			