

### COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF CLEAN WATER

### **CHAPTER 102 INSPECTION REPORT**

Permit No.: PAD510225
Report No.:

PA Dept of Environmental Protection

	GENERAL INFO	RMATION			
Project/Site Name:	Alliance 51st Street, Philadelphia	Permit Issuance D	ate: 9/5/2023	3	
Site Address:	1656 South 51st Street	Permit Expiration [	Date: 9/4/2028	3	
Site City, State, ZIP:	Philadelphia, PA	Permit Type:	NPDES		
RP/Permittee Name:	Eric Carlson	Site Municipality(ie	es): Philadel	phia	
RP/Permittee Address:	40 Morris Avenue; Suite 230	Site County(ies):	Philadel	phia	
RP/Permittee City, State, 2	ZIP: Bryn Mawr, PA 19010	Earth Disturbance:	11.54	acres	
RP/Permittee Email:	Ecarlson@alliancehp.com	Site Latitude:	39.9352	78	
Surface Water(s):	Schuylkill River	Site Longitude:	- 75.2092	236	
Special Protection?	☐ Yes ☑ No	Complaint Inspecti	ion?	Yes No	
Construction Stage:	Bulk Earthwork	Activity:	Construc	ction ≥ 1 ac	
Operator Name	Operator Company	Operato	or Email	Approved	
Bruce Price	Arco Design/Build				
	INSPECTION INFO	ORMATION			
Inspection Date:	7/29/2024			□ AM □ PM	
Lead Inspector Name:	Carol Canigiani	Inspector Email:	Ccanigiani@	pa.gov	
Inspector Title:	Aquatic Biologist	Inspector Phone:	484-250-5118	8	
Other Inspector(s):	Phila Water Dept	Weather:	clear		
Was a representative of the project on-site during the inspection? ☑ Yes ☐ No					
Representative Name: Sean Gallagher		Email:	arcodb.com		
Representative Company: Arco Design/Build		Phone:	610-417-0045		
Type of Inspection:	☐ Initial ☑ Follow-up (Previous Rep	oort #:	) 🗸	Photographs attached	
Brief description of the site and summary of observations:					
from 1646 South 51st Str Specialist Linda Mackey; Sean Gallagher, Gernot site were evaluated across include additional filter so along the drainage chann	eet site onto Bartram Gardens trail. I was Philadelphia Water Department Inspectors Jobst, Bruce Brice, and Nick Bello, all from state entire site. The southeast corner of the lock, silt screen, and rock filters to improve stall have had rock channels added to them tail has been removed. The open trench lock	joined on site for today is Bao Nguyen and Sar is Arco Design/Build. P the site which is the low sediment-trapping of s is. The sediment that he	y's inspection ra Anderson; a Anderson; a erimeter contivest elevation tormwater rurad been obse	by PADEP Compliance and site representatives trols and berms within the has been modified to n-off. The earthen berms	

		INSPECTION FINDINGS
		No violations observed at this time.
a.		Failure to implement and/or maintain E&S BMPs for earth disturbance (§§ 102.4(b)(1), 102.22(a)(1)).
b.		Failure to develop and/or implement a written E&S Plan (§ 102.4(b)(2)).
C.		Failure to have a person trained and experienced in E&S control methods develop an E&S Plan (§ 102.4(b)(3)).
d.		Failure to have the E&S Plan and/or inspection/monitoring reports on-site and available for review (§ 102.4(b)(8)).
e.		Failure of permittee to obtain all necessary approvals/permits from DEP/CCD prior to commencing earth disturbance (§ 102.4(d)).
f.		Failure to hold a pre-construction meeting and/or invite DEP/CCD staff and/or provide at least 7 days' notice (§ 102.5(e)).
g.		Failure of an operator to submit a co-permittee acknowledgement form (§ 102.5(h)).
h.		Failure to prepare and/or implement and/or provide upon request a PPC Plan when required (§ 102.5(I)).
i.	V	Failure to temporarily stabilize areas where there will be a cessation of earth disturbance activities for at least 4 days (§ 102.22(b)).
j.		Failure to complete or accurately complete visual site inspections as required by the permit (CSL § 402(b)).
k.		Failure to implement PCSM BMPs as specified in the approved PCSM Plan (§ 102.8(a)).
l.		Failure to operate and maintain PCSM BMPs as specified in an approved PCSM Plan or deed (§ 102.8(a)).
m.		Failure to have the PCSM Plan, inspection reports, and/or monitoring records available for review (§ 102.8(j)).
n.		Failure to have a licensed professional or a designee present on-site during critical stages of PCSM BMPs (§ 102.8(k)).
0.		Failure to record an instrument for PCSM BMPs (§ 102.8(m)(2)).
p.		Failure to meet riparian forest buffer criteria (§ 102.14(b)).
q.		Failure to permanently stabilize a project site or any phase or stage thereof (§ 102.22(a)).
r.		Failure to remove temporary E&S BMPs once permanent stabilization has been established (§ 102.22(a)(1)).
S.		Failure to obtain NPDES permit prior to commencing earth disturbance activity with at least one acre of disturbance (§ 102.5(a)).
t.		Failure to obtain E&S permit prior to commencing earth disturbance activity with at least 25 acres of disturbance for timber harvesting and road maintenance (§ 102.5(b)).
u.		Failure to obtain E&S permit prior to commencing earth disturbance activity with at least 5 acres of disturbance for oil and gas activities (§ 102.5(c)).
٧.		Failure of activity not requiring a permit to comply with Chapter 102 requirements (§ 102.5(k)).
w.		Failure to follow the approved construction sequence in an E&S or PCSM Plan (CSL § 402(b)).
Χ.		Failure to submit a Notice of Termination (NOT) (§ 102.7(a)).
у.		Unauthorized discharge of polluting substances to waters of the Commonwealth resulting in pollution (CSL § 401).
Z.		Failure to comply with the terms and conditions of a permit or order (CSL § 402(b)).

3800-FM-BCW0271g	Rev. 11/2022		
Chanter 102 Increation	Papart		

Permit No.: PAD510225
Report No.:

		INSPECTION FINDINGS
aa.		Failure to remove building materials and/or wastes from the site for recycling or disposal in accordance with DEP regulations as required by the permit (CSL § 402(b)).
bb.		Failure to comply with DEP regulations or the Clean Streams Law (CSL § 611).
cc.		Failure to take necessary measures to prevent pollutants from reaching waters of the Commonwealth (§ 91.34(a)).
dd.		Failure to notify DEP of new or expanded earth disturbance not identified in an NPDES permit application (§ 92a.24(b)).
ee.		Failure to notify and/or obtain authorization from DEP/CCD for changes to NPDES permitted activities (§ 92a.41(a)(12)).
ff.		Other:
		During the inspection violations of Chapter 105 were observed and are identified in a separate Chapter 105 inspection report.
		E&S BMPs were evaluated and appear to be functioning as designed.
		PCSM BMPs were evaluated and appear to be functioning as designed.
		Form 3800-FM-BCW0531a was used to document the PCSM BMP evaluation.
		There is a need for modifications to the E&S Plan, PCSM Plan, or permit coverage.
		Describe:
		COMPLIANCE ASSISTANCE RECOMMENDATIONS
This ca	n be do ent. A d	nded that the large pile of dirt that has been recently graded be stabilized if it will not be disturbed in the next 4 days, one with decomposeable erosion control blanket, as discussed on site. Monitor and repair all E&S BMPs after every drainage pipe on southwestern area of the site, and with unknown origin, should be further evaluated to determine

3800-FM-BCW0271g Rev. 11/2022		Perm	nit No.:	PAD510225
Chapter 102 Inspection Report		Rep	ort No.:	
	ADDITION	AL COMMENTS		
THE A PERSON LA				
	NOTICE AN	D SIGNATURES		
Streams Law. Failure to take corrective action specified at Section 602 of the Clean Streams criminal penalties, and up to \$25,000 in misder Nothing contained herein shall be deemed to g the DEP/CCD inspector.	is to resolve the violations may Law. The Clean Streams Law meanor criminal penalties for ea trant or imply immunity from leg	n this report and constitute unlawful conduct as define result in administrative, civil and/or criminal penalties provides for up to \$10,000 per day in civil penalties, u ch violation. This report does not constitute an Order al action for any violation noted herein. For further info	being ass up to \$10, or appeal ormation o	essed by DEP as as 000 in summary lable action of DEP. or assistance contact
	signee agrees with the report. A	d the report and were given an opportunity to discuss All comments by the inspector are based on visual sit		
☐ Violations are documented in	this report and this repor	t serves as a Notice of Violation (NOV).		
☐ A follow-up inspection will occ	cur on or about:	ORDER DOS - 100 CONTROL OF THE PARTY OF THE		
		0.0		./ /
Copy emailed to Eric Carlson Site Representative Signature	8/5/2024 Date	Inspector Signature	8	15/24

cc: Philadelphia Water Department

Arco Design/Build

# 3800-FM-BCW0271g Rev. 11/7 Pennsylvania DEPARTMENT OF ENVIRONMENTAL PROTECTION

#### COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF CLEAN WATER

#### **CHAPTER 102 INSPECTION REPORT**

Permit No.: Report No.:

PAD510225

CLEAR REPORT

PA Dept of Environmental Protection

SAVE AS PDF

Project/Site Name:	Alliance 51st Street, Philadelphia	Permit Issuance Date:	9/5/2023	
Site Address:	1656 South 51st Street	Permit Expiration Date:	9/4/2028	
Site City, State, ZIP:	Philadelphia, PA	Permit Type:	NPDES IP	
RP/Permittee Name:	Eric Carlson	Site Municipality(ies):	Philadelphia	
RP/Permittee Address:	40 Morris Avenue; Suite 230	Site County(ies):	Philadelphia	
RP/Permittee City, State, ZIP:	Bryn Mawr, PA 19010	Earth Disturbance:	11.54	acres
RP/Permittee Email:	Ecarlson@alliancehp.com	Site Latitude:	39.935278	
Surface Water(s):	Schuylkill River	Site Longitude: -	-75.209238	
Special Protection?	☐ Yes ☑ No	Complaint Inspection?	▼ Yes  No	
Construction Stage:	Bulk Earthwork	Activity:	Construction ≥ 1 ac	





## COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF CLEAN WATER

#### **CHAPTER 102 INSPECTION REPORT**

Permit No.: Report No.: PAD510225

CLEAR REPORT

Special Protection?

#### PA Dept of Environmental Protection

GENERAL INFORMATION

SAVE AS PDF

Project/Site Name:	Alliance 51st Street, Philadelphia	Permit Issuance Date:	9/5/2023	
Site Address:	1656 South 51st Street	Permit Expiration Date:	9/4/2028	
Site City, State, ZIP:	Philadelphia, PA	Permit Type:	NPDES IP	
RP/Permittee Name:	Eric Carlson	Site Municipality(ies):	Philadelphia	
RP/Permittee Address:	40 Morris Avenue; Suite 230	Site County(ies):	Philadelphia	
RP/Permittee City, State, ZIP:	Bryn Mawr, PA 19010	Earth Disturbance:	11.54	acres
RP/Permittee Email:	Ecarlson@alliancehp.com	Site Latitude:	39.935278	
Surface Water(s):	Schuvlkill River	Site Longitude: -	-75.209236	

 Schuylkill River
 Site Longitude: - -75.209236

 Yes
 No

 Complaint Inspection?
 ✓ Yes

 No

 Bulk Earthwork
 Activity:

 Construction ≥ 1 ac

