

Lee Park, Suite 6010 555 North Lane Conshohocken, PA 19428 May 5, 2000

Southeast Regional Office

610-832-5949 Fax 610-832-6143

CERTIFIED MAIL NO. P 092 246 622

Alloy Steel Corporation 21 Seneca Street Oil City, PA 16301

Re: Bishop Tube Site

East Whiteland Township

Chester County

Dear Sir or Madam:

This letter serves as notification that the Pennsylvania Department of Environmental Protection has investigated a release or threat of release of a contaminant or hazardous substance from the site, and has determined that further response action is appropriate.

The site is located at Route 30 and Malin Road, in Frazier, Chester County, Pennsylvania. The release concerns soil and groundwater contamination discovered during investigations conducted on behalf of Christiana Metals, a former site owner. Levels of trichloroethene (TCE) in the groundwater are indicative of a source of groundwater contamination. The extent of offsite groundwater contamination has not been determined. The Department has decided to conduct further investigation activities at the site.

Pursuant to Section 501(a) of the Pennsylvania Hazardous Sites Cleanup Act, Act 108 of October 18, 1988, (P.L. 756, No. 108), 35 P.S. Section 6020.501(a), the Department is required to notify the owner, operator, or other known responsible persons of such releases or threatened releases. Our information indicates that you operated at or owned this site. If so, you could be responsible under state or federal law for the cost or performance of any environmental investigations or cleanup actions this site may require.

Sincerely,

Bruce D. Beitler Regional Manager

Environmental Cleanup

cc:

Mr. Armstrong

Mr. Hartzell

Mr. Danyliw

Mr. Sheehan

Ms. Tremont

Re. 30 (DAF00)125-10A



Lee Park, Suite 6010 555 North Lane Conshohocken, PA 19428 May 5, 2000

Southeast Regional Office

610-832-5949 Fax 610-832-6143

CERTIFIED MAIL NO. P 092 246 620

Mr. Craig Fuller Christiana Metals Corporation 125 Strafford Avenue, Suite 100 Wayne, PA 19087

Re: Bishop Tube Site

East Whiteland Township

Chester County

Dear Mr. Fuller:

This letter serves as notification that the Pennsylvania Department of Environmental Protection has investigated a release or threat of release of a contaminant or hazardous substance from the site, and has determined that further response action is appropriate.

The site is located at Route 30 and Malin Road, in Frazier, Chester County, Pennsylvania. The release concerns soil and groundwater contamination discovered during investigations conducted on behalf of Christiana Metals. Levels of trichloroethene (TCE) in the groundwater are indicative of a source of groundwater contamination. The extent of offsite groundwater contamination has not been determined. The Department has decided to conduct further investigation activities at the site.

Pursuant to Section 501(a) of the Pennsylvania Hazardous Sites Cleanup Act, Act 108 of October 18, 1988, (P.L. 756, No. 108), 35 P.S. Section 6020.501(a), the Department is required to notify the owner, operator, or other known responsible persons of such releases or threatened releases. Our information indicates that you have operated at or owned this site. If so, you could be responsible under state or federal law for the cost or performance of any environmental investigations or cleanup actions this site may require.

Sincerely,

Bruce D. Beitler

Regional Manager

Environmental Cleanup

cc:

Mr. Armstrong

Mr. Hartzell

Mr. Danyliw

Mr. Sheehan

Ms. Tremont

Re. 30 (DAF00)125-10B



Lee Park, Suite 6010 555 North Lane Conshohocken, PA 19428 May 5, 2000

Southeast Regional Office

610-832-5949 Fax 610-832-6143

CERTIFIED MAIL NO. P 092 246 624

Johnson Matthey, Inc. 460 East Swedesford Avenue Wayne, PA 19087

Re: Bishop Tube Site

East Whiteland Township

Chester County

Dear Sir or Madam:

This letter serves as notification that the Pennsylvania Department of Environmental Protection has investigated a release or threat of release of a contaminant or hazardous substance from the site, and has determined that further response action is appropriate.

The site is located at Route 30 and Malin Road, in Frazier, Chester County, Pennsylvania. The release concerns soil and groundwater contamination discovered during investigations conducted on behalf of Christiana Metals, a former site owner. Levels of trichloroethene (TCE) in the groundwater are indicative of a source of groundwater contamination. The extent of offsite groundwater contamination has not been determined. The Department has decided to conduct further investigation activities at the site.

Pursuant to Section 501(a) of the Pennsylvania Hazardous Sites Cleanup Act, Act 108 of October 18, 1988, (P.L. 756, No. 108), 35 P.S. Section 6020.501(a), the Department is required to notify the owner, operator or other known responsible persons of such releases or threatened releases. Our information indicates that you have operated at or owned this site. If so, you could be responsible under state or federal law for the cost or performance of any environmental investigations or cleanup actions this site may require.

Sincerely,

Bruce D. Beitler Regional Manager Environmental Cleanup

cc:

Mr. Armstrong

Mr. Hartzell

Mr. Danyliw

Mr. Sheehan

Ms. Tremont

Re. 30(DAF00)125-10C



Lee Park, Suite 6010 555 North Lane Conshohocken, PA 19428 May 5, 2000

Southeast Regional Office

610-832-5949 Fax 610-832-6143

CERTIFIED MAIL NO. P 092 246 621

Marcegaglia USA Damascus Division 795 Reynolds Industrial Park Road Greenville, PA 16125

Re: Bishop Tube Site

East Whiteland Township

Chester County

Dear Sir or Madam:

This letter serves as notification that the Pennsylvania Department of Environmental Protection has investigated a release or threat of release of a contaminant or hazardous substance from the site, and has determined that further response action is appropriate.

The site is located at Route 30 and Malin Road, in Frazier, Chester County, Pennsylvania. The release concerns soil and groundwater contamination discovered during investigations conducted on behalf of Christiana Metals. Levels of trichloroethene (TCE) in the groundwater are indicative of a source of groundwater contamination. The extent of offsite groundwater contamination has not been determined. The Department has decided to conduct further investigation activities at the site.

Pursuant to Section 501(a) of the Pennsylvania Hazardous Sites Cleanup Act, Act 108 of October 18, 1988, (P.L. 756, No. 108), 35 P.S. Section 6020.501(a), the Department is required to notify the owner, operator, or other known responsible persons of such releases or threatened releases. Our information indicates that you have operated at or owned this site. If so, you could be responsible under state or federal law for the cost or performance of any environmental investigations or cleanup actions this site may require.

Sincerely,

Bruce D. Beitler Regional Manager

Environmental Cleanup

cc: Mr. Armstrong

Mr. Hartzell

Mr. Danyliw

Mr. Sheehan

Ms. Tremont

Re. 30 (DAF00)125-10D



Lee Park, Suite 6010 555 North Lane Conshohocken, PA 19428 May 5, 2000

Southeast Regional Office

610-832-5949 Fax 610-832-6143

CERTIFIED MAIL NO. P 092 246 623

Whittaker Corporation 1955 North Surveyor Avenue Simi Valley, CA 93063

Re: Bishop Tube Site

East Whiteland Township

Chester County

Dear Sir or Madam:

This letter serves as notification that the Pennsylvania Department of Environmental Protection has investigated a release or threat of release of a contaminant or hazardous substance from the site, and has determined that further response action is appropriate.

The site is located at Route 30 and Malin Road, in Frazier, Chester County, Pennsylvania. The release concerns soil and groundwater contamination discovered during investigations conducted on behalf of Christiana Metals. Levels of trichloroethene (TCE) in the groundwater are indicative of a source of groundwater contamination. The extent of offsite groundwater contamination has not been determined. The Department has decided to conduct further investigation activities at the site.

Pursuant to Section 501(a) of the Pennsylvania Hazardous Sites Cleanup Act, Act 108 of October 18, 1988, (P.L. 756, No. 108), 35 P.S. Section 6020.501(a), the Department is required to notify the owner, operator, or other known responsible persons of such releases or threatened releases. Our information indicates that you have operated at or owned this site. If so, you could be responsible under state or federal law for the cost or performance of any environmental investigations or cleanup actions this site may require.



Sincerely,

Bruce D. Beitler Regional Manager

Environmental Cleanup

cc:

Mr. Armstrong

Mr. Hartzell

Mr. Danyliw

Mr. Sheehan

Ms. Tremont

Re. 30 (DAF00)125-10E

PS Form 3811, December 1994

Domestic Return Receipt

		·		