

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL PROTECTION  
BUREAU OF MINING AND RECLAMATION

INSPECTION REPORT  
NONCOAL

Date 1/7/89

On Site Times AM

Mine Name Rochhill Quarry  
Weather Sunny - 25°F

PERMITTEE <u>Milestone Materials Inc.</u>	TOWNSHIP <u>E. Rochhill</u>	COUNTY <u>Bucks</u>	PERMIT NO. <u>79745M1</u>
ADDRESS <u>P.O. Box 231 Easton, PA 18044 610-253-4271</u>	VIOLETION HISTORY <input checked="" type="checkbox"/> NOV'S <input checked="" type="checkbox"/> CO'S <u>2 infra</u>	VIOLETIONS NOTED <input type="checkbox"/> FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> PREVIOUS VIOLATIONS: COMPLIANCE ORDER <input type="checkbox"/> CORRECTED <input type="checkbox"/> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/> UNCORRECTED <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/>	LICENSE NO. & EXP. DATE <u>3-00679 9/30/88</u> OPERATIONAL STATUS <u>Active</u>

GENERAL MINING INFORMATION: Large Noncoal  Small Noncoal  Complete  Partial or Followup

a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: Dipbase - Open pit quarry  
~1500' (457.2m) x ~900' (274.32m) x ~250' (76.2m) - 5 lifts  
[103.2 (41.77ha)]

b. Acreage (total):  Bonded 103.2 Affected 103 (41.68ha) Regraded  Reclaimed

c. Equipment-Use & Conditions: Processing plant - does not appear operational.

d. Contract Miner  yes  no e. Blasting at Site  yes  no (Explain yes answers) No recent blasting

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	700 Unauthorized Mining				<input checked="" type="checkbox"/>	730 Concurrent Reclamation			
<input checked="" type="checkbox"/>	701 Signs and Markers				<input checked="" type="checkbox"/>	731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat.			
<input checked="" type="checkbox"/>	703 Topsoil-Rem/Sto/Hndng				<input checked="" type="checkbox"/>	735 Revegetation			
<input checked="" type="checkbox"/>	704 Effluent Standard					742 Permanent Mining Cessation			
<input checked="" type="checkbox"/>	706 Diversions and Conveyance				<input checked="" type="checkbox"/>	743 Haul Roads/Restoration			
<input checked="" type="checkbox"/>	707 Sediment Control Measures				<input checked="" type="checkbox"/>	745 Support Facilities			
	708 Treatment Facilities				<input checked="" type="checkbox"/>	749 General Safety			
<input checked="" type="checkbox"/>	709 Sedimentation Ponds				<input checked="" type="checkbox"/>	753 Permit Conditions			
<input checked="" type="checkbox"/>	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Forming Spoil					755 Closing Underground Mine Openings			
	712 Impoundments				<input checked="" type="checkbox"/>	756 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const./Maint.				<input checked="" type="checkbox"/>	757 Bench Development			
<input checked="" type="checkbox"/>	715 Water Monitoring-Ground/Surface				<input checked="" type="checkbox"/>	758 Permit Line Setback			
	717 Water Rights and Replacement					759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
<input checked="" type="checkbox"/>	723 Blasting Requirement					761 Postmining Land Use			
<input checked="" type="checkbox"/>	727 Disposal of Solid Wastes					762 Cleanup			
<input checked="" type="checkbox"/>	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: ① This inspection was conducted "solo".  
② The quarry was not operating at the time of this inspection.  
③ An operation I'd never complete with permit # was observed by gate at west entrance to the quarry. This gate was locked.

Person Contacted <u>None</u>	Title	Discharge/Seeps <input type="checkbox"/> yes <input type="checkbox"/> no Samples Collected <input type="checkbox"/> yes <input type="checkbox"/> no Range of Samples Collected _____ to _____
Signature <u>To be mailed</u>	Investigator Signature & I.D. No. <u>Christian Kula</u>	<u>Nothing present from pit - Possible flow of ground water.</u> <u>4556</u>

Rec'd. 9/15/88

COMMENTS AND RECOMMENDATIONS

Mine Name Rockhill Quarry

Date 1/7/99

PERMITEE <u>Milestone Materials Inc.</u>	TOWNSHIP <u>E. Rockhill</u>	COUNTY <u>Bucks</u>	PERMIT NO. <u>79745m1</u>

- (4) The gate, located at the North entrance to the quarry, was open, however, vehicles blocked access further up this entrance.
- (5) The elevation of water in the pit appears to be as though it is being monitored. A wooden stake ~~has been~~ is located at the entrance next to the pit. The stake appears to mark the water elevation for the month of November 1998. The water level appears to be down a few inches since November 1998. The pit is full of water.
- (6) I walked the trail that surrounds the quarry. There was evidence of foot prints and heavy tire tracks. Hand of trespassers are still causing access to the site. Due to the location of the quarry, this is not really preventable however, better preparation of the pickwall still needs to be posted. This should be done before April 1, 1999.
- (7) Three pictures of the steep hills area were taken during this inspection. The pictures were taken to help keep track of the steep hills on-site (see letter from milestone materials dated 1/10/21/1998).

Person Contacted <u>None</u>	Title	Investigator Signature & I.D. No. <u>Christina Kula</u>	<input checked="" type="checkbox"/> 4 <input checked="" type="checkbox"/> 5 <input checked="" type="checkbox"/> 5 <input checked="" type="checkbox"/> 6
Signature <u>T. be mailed</u>			

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.