

2735459



COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF MINING PROGRAMS

INSPECTION REPORT
NONCOAL

Date: 5/4/2018

Mine Name Rock Hill Quarry

Weather Overcast 70 F

Complete [] Partial [x]

On Site Times 0900 - 1050

PERMITTEE Hanson Aggregates Pennsylvania, LLC
TOWNSHIP East Rockhill
COUNTY Bucks
PERMIT NO. 7974SM1
ADDRESS: 7660 Imperial Way
Allentown PA 18195
VIOLATION HISTORY: 0 NOV'S, 0 CO'S
VIOLATIONS NOTED: [] PREVIOUS VIOLATIONS: [] CORRECTED [] UNCORRECTED []
FOLLOW-UP INSP. REQUIRED: [] COMPLIANCE ORDER [] FTC ORDER [] CEASE ORDER []
LICENSE NO. & EXP. DATE: 24143 12/31/2018
OPERATIONAL STATUS: Active

GENERAL MINING INFORMATION: Large [x] Small 10,000 [] 2,000 [] GP 105 [] GP 103 [] Expiration Date:

a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: Argillite open pit- water filled pit- ~1500' x ~900' x ~250'

b. Equipment-Use & Conditions: portable crushers; FELs; track excavators; grader; haul trucks - good condition

c. Contract Miner: Yes [x] No [] Name: R. E. Pierson d. Approved Blast Plan: Yes [x] No [] Is there blasting today? Yes [] No [x]

Table with columns: Approved Acres, Approved Pit Volume, Progress of Reclamation, Liability. Rows include Mining Area, Disturbed not planted, Affected acres, Selective Grading of Highwall, and Meeting Stage 1 criteria.

Highwall Bond (Blasting to achieve reclamation) Approved/Affected
Table with columns: <20 ft., >20<30 ft., >30<40 ft., >40<50 ft., >50 ft.

PERFORMANCE STANDARDS NONCOAL

Table with columns: Obs., STANDARD, PC or Reg., Viol., Comp. Date. Lists various standards such as Unauthorized Mining, Air Resources Protection, Concurrent Reclamation, etc.

COMMENTS AND RECOMMENDATIONS:

This partial inspection was conducted in the company of Mr. Joe Blyler (P.E./DEP), Mr. Mike Fling (P.E./ERG/Hanson), Mr. Andrew Gutshall (P.G./Hanson), and Mr. Richard Pierson Jr. (Pres./Diamond Materials). On site to review E&S construction. The portable crushers were running. One track excavator and one haul truck were working on the pond near the railroad crossing. Construction on the primary crushing was continuing. The sediment basin near the outfall needs to have the overflow moved above the final check berm. Sound levels were taken at the swale on Rockhill Road and in the backyard of neighbor (Mr. Ryan Gottshall). The sound levels in both areas were about 58 dB.

Person Contacted Mr. Charlie Elwell Title Pierson Discharge/Seeps: [x] yes [] no Range of Samples Collected Samples Collected: [] yes [x] no Collector ID No. 4519 Employee ID No. 608058

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.