COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF MINING AND RECLAMATION

Mine Name Rock Hill Quarry Weather Clear 45 F

INSPECTION REPORT

Page 1 of 1 Date 11/3/2010 On Site Times AM

| weather <u>Clear 45 F</u> | 14 do 14 do do 2 dos | | | | | | | 11100 / 1111 |
|---|---|----------|---|----------|--|--------------------------------------|--|--------------|
| PERMITTEE Hanson Aggregates of Pa., Inc. | TOWNSHIP East Rockhill | | | | COUNTY Bucks | PERMIT NO. 7974SM1 | | |
| ADDRESS 7660 Imperial Way Allentown PA 18195 610-366-4828 | VIOLATION HISTORY <u>0</u> NOV'S <u>0</u> CO'S | PREV | IOUS VI | OLATI | D FOLLOW-UP INSP. REQUIRED ONS: COMPLIANCE ORDER TC ORDER CEASE ORDER OUTSTANDING ENFORCEMENT | 24143 12/31/20 OPERATIONAL STATUS | | 31/2010 |
| GENERAL MINING INFORMATION: | Large No | ncoal 🔯 | Sn | nall N | Ioncoal 🗌 Complete 🛛 Pa | rtial or Fol | | |
| a. Areas-Minerals-Pit Dimensions (L/V | V/H) – Meth | od: Dial | oase | (| Open Pit <u>~ 1500' (457m) x 900'</u> | (274m) x 2 | 50' (7 | 76m) |
| b. Acreage (total): 103.3 (41.77ha) Bonded 103.2 Affected ~103 Regraded 0 Reclaimed 0 | | | | | | | | |
| c. Equipment-Use & Conditions: No equipment on site | | | | | | | | |
| d. Contract Miner yes no e. Blasting at Site yes no (Explain yes answer) No recent blasting | | | | | | | | |
| PERFORMANCE STANDARDS NONCOAL | | | | | | | | |
| Obs. STANDARD | PC or Reg. V | iol. Com | p. Date | Obs. | STANDARD | PC or Reg. | Viol. | Comp. Date |
| X 700 Unauthorized Mining | | | | NΑ | 730 Concurrent Reclamation | | | |
| X 701 Signs and Markers | | | | | 731 Backfilling and Grading | | | |
| NA 702 Casing and Sealing Drilled Holes | | | | | 733 Covering Coal and Acid/Toxic Mat. | | | |
| X 703 Topsoil-Rem/Sto/Hning | | | | | 735 Revegetation | <u> </u> | | |
| X 704 Effluent Standard | | | | | 742 Permanent Mining Cessation | | | |
| NA 706 Diversions and Conveyance | | | | | 743 Haul Roads/Restoration 745 Support Facilities | _ | | |
| X 707 Sediment Control Measures | | | | | 749 General Safety | | | |
| NA 708 Treatment Facilities X 709 Sedimentation Ponds | | | | X | | | <u> </u> | |
| X 710 Discharge Structures | | - | | | 754 Temporary Mining Cessation | | *************************************** | |
| NA 711 Acid and Toxic Forming Spoil | | | | NA | 755 Closing Underground Mine Openings | 3 | | |
| NA 712 Impoundments | | | | Х | | | | |
| NA 713 Dams, Ponds-Design/Const./Maint. | | | | Х | 757 Bench | | | |
| NA 715 Water Monitoring-Ground/Surface | | | *************************************** | Х | | | | |
| NA 717 Water Rights and Replacement | | | | | 759 Stability Analysis | | | |
| NA 718 Water Discharge-Underground Mine | : | | | | 760 Post Mining Renovation 761 Postmining Land Use | | | <u> </u> |
| X 723 Blasting Requirement | | | | | 761 Postmining Land Use 762 Cleanup | | | 1 |
| X 727 Disposal of Solid Wastes X 728 Air Resources Protection | | | | INA | 702 Gleanup | | | |
| COMMENTS AND RECOMMENDATIONS: This complete inspection was conducted solo. The gate was locked. No activity was observed. Material was removed from near the garage (500 tons). | | | | | | | | |
| was observed. Material was removed | , nominour | ino gare | .90 100 | <u> </u> | <u></u> | | , | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| Violation History: None | | | | | • | | | |
| | | | | | | | | |
| | | | | | | | | |
| Person Contacted | Title | | | | scharge/Seeps | | | |
| None | | | | | nge of Samples Collected | | | |
| Signature | | | | | estigator Signature | Sampler I.D. No. 4519 | | |
| | | | | | a n l | • | | |
| Mailed | | | | Am | niee Bollinger / fa | Emple | oyee | #608058 |