

Commonwealth of Pennsylvania

DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF SURFACE MINE RECLAMATION
INSPECTION
REPORT

Min permit No. 733-5
Drainage Permit No. 7974 SM1
Mine Inspection No. 54
Reinspection No. 2-78

Company <u>General Crushed Stone Co</u>		Mine Location: County <u>Bucks</u>	Township <u>E. Pothkill</u>
Mining Permit Acres Affected <u>15</u>		Drainage Permit Acres Affected <u>30</u>	
Status of Operation: Active <input checked="" type="checkbox"/>	Inactive <input type="checkbox"/>	Not Started <input type="checkbox"/>	

- 1. Is this operation in compliance with the Safety Rules and Regulations? YES ___ NO ___ NOTED X
- 2. Is this mine operating in compliance with the conditions of the mining permit? YES ___ NO ___ NOTED X
- 3. Is the mine operating in compliance with the conditions of the mine drainage permit? YES ___ NO ___ NOTED X

REMARKS AND RECOMMENDATIONS: Water clear at point of discharge - near the RR switch.
(1) Corrected property maps were submitted by the operator showing the addition to the storage yard.
(2) The sediment control pond located adjacent to "Pond 6" has been cleaned out - depth unknown.
(3) Waste dump - dumping has not been discontinued. I question the reason.
Broken window on Mack B42 (#10056) left side (driver side) is to be replaced immediately.
Broken windshield on Cat 988 end loader (left side of split windshield) to be replaced promptly.

Company Official Contacted <u>James Fryer</u>	Title <u>Supt.</u>
Mine Inspector <u>Paul T. Sarfass</u>	Inspection Date <u>9-7-78</u>

INSPECTORS' RECOMMENDATIONS TO BUREAU:
No action necessary.
Correction work will be checked by the Inspector.