

DATE: 2/2/90

**RECEIVED**

FEB - 2 1990

ENVIRONMENTAL CONTROL

TO: DAN POWELL

WIN: 272-2466

OUTSIDE: \_\_\_\_\_

FROM: TED KASPER

WIN: 222-1785

OUTSIDE: \_\_\_\_\_

NO. OF SHEETS 2 (INCLUDING COVER SHEETS)

UPON RECEIPT OF THIS, PLEASE NOTIFY SHELLY ASAP ON WIN 222-1668  
OR OUTSIDE (412) 773-1688

5410N/6

WPL 005 0467

132/ 6121743

WESTINGHOUSE ELECTRIC CORP. - BEAVER  
 ANALYTICAL RESULTS FOR BONDORIZER TANK REMOVAL  
 Date Received: 02/02/90

Parameter	SAMPLES		
	Sludge	Rinse water	#1 Soil
Lead, Total	2,300 mg/kg	18 mg/l	97 mg/kg
Benzene	<250 ug/g	<1,000 ug/l	<1 ug/g
Toluene	<250 ug/g	1,100 ug/l	<1 ug/g
Meta Xylene	12,000 ug/g	38,000 ug/l	<1 ug/g
Ortho Xylene	6,200 ug/g	23,000 ug/l	<1 ug/g
Para Xylene	5,000 ug/g	12,000 ug/l	<1 ug/g
Total Petroleum Hydrocarbons	58,000 ug/g	300 ug/l	63 mg/kg

Parameter	SAMPLES		
	#2 Soil	#3 Soil	Composite Soil
Lead, Total	15 mg/kg	16 mg/kg	85 mg/kg
Benzene	<1 ug/g	<1 ug/g	<1 ug/g
Toluene	<1 ug/g	<1 ug/g	<1 ug/g
Meta Xylene	<1 ug/g	<1 ug/g	<1 ug/g
Ortho Xylene	<1 ug/g	<1 ug/g	<1 ug/g
Para Xylene	<1 ug/g	<1 ug/g	<1 ug/g
Total Petroleum Hydrocarbons	<20 mg/kg	<20 mg/kg	<20 mg/kg

WPL 005 0468

132/ 6121744