

**APPENDIX L-3 – TABLE 1
 STREAMBANK STABILIZATION TABLE**

Resource ID	County	MP	Stream Bank Stabilization BMP ^a
CPL North			
WW-T91-15001	Columbia	0.21	SBR with SC150 fabric
WW-T02-15002	Columbia	0.59	SBR with SC150 fabric
WW-T02-15004	Columbia	0.93	SBR with SC150 fabric
WW-T02-15006	Columbia	1.16	SBR with SC150 fabric
WW-T92-15001B	Columbia	1.26	SBR with SC150 fabric
WW-T02-15007	Columbia	1.31	SBR with SC150 fabric
WW-T02-15008	Columbia	1.99	SBR with SC150 fabric
WW-T91-15004	Columbia	M-0086 0.21	SBR with SC150 fabric
WW-T02-15009	Columbia	2.29	SBR with SC150 fabric
WW-T02-15010	Columbia	2.87	SBR with SC150 fabric
WW-T92-15001	Columbia	2.88	SBR with SC150 fabric
WW-T02-15011	Columbia	2.92	SBR with SC150 fabric
WW-T02-15013	Columbia	3.35	SBR with SC150 fabric
WW-T02-15014	Columbia	3.82	SBR with SC150 fabric
WW-T02-15012C	Columbia	4.12	SBR with SC150 fabric
WW-T02-15012	Columbia	4.13	SBR with SC150 fabric
WW-T92-15002	Columbia	4.22	SBR with SC150 fabric
WW-T93-15001	Columbia	4.80	SBR with SC150 fabric
CPL South			
WW-T45-11001	Columbia	90.99	SBR with C125 fabric
WW-T51-11001	Columbia	91.01	SBR with SC150 fabric
WW-T47-11001	Columbia	91.74	SBR with SC150 fabric
WW-T44-11001	Columbia	M-0437 0.06	SBR with C125 fabric
WW-T31-11001	Columbia	94.13	SBR with C125 fabric

*Atlantic Sunrise Project – PA DEP Chapter 105 Joint Permit Application
 Transcontinental Gas Pipe Line Company, LLC
 Columbia County
 Attachment L – Environmental Assessment
 Enclosure D – Description of Impacts*

Resource ID	County	MP	Stream Bank Stabilization BMP^a
WW-T04-11001 WW-T04-11001A	Columbia	94.43	SBR with SC150 fabric
WW-T04-11002	Columbia	94.96	SBR with SC150 fabric
WW-T28-12005	Columbia	95.29	SBR with SC150 fabric
WW-T28-12004	Columbia	95.44	SBR with SC150 fabric
WW-T35-11001	Columbia	95.85	SBR with SC150 fabric
WW-T04-12001	Columbia	99.66	SBR with SC150 fabric
WW-T04-12002	Columbia	101.61	SBR with SC150 fabric
WW-T04-12003	Columbia	101.61	SBR with SC150 fabric
WB-T04-12007	Columbia	101.62	SBR with SC150 fabric
WW-T04-12004	Columbia	101.62	SBR with SC150 fabric
WW-T04-12005	Columbia	101.65	SBR with SC150 fabric
WW-T04-12005A	Columbia	101.68	SBR with SC150 fabric
WW-T04-12006	Columbia	102.02	SBR with SC150 fabric
WW-T70-12003	Columbia	M-0423 1.48	SBR with SC150 fabric
WW-T70-12011	Columbia	M-0423 3.00	SBR with SC150 fabric
WW-T70-12006	Columbia	M-0423 3.07	SBR with SC150 fabric
WW-T70-12010-1	Columbia	M-0423 3.28	SBR with SC150 fabric
WW-T70-12010	Columbia	M-0423 3.58	SBR with SC150 fabric
WW-T70-12012	Columbia	M-0423 3.83	SBR with SC150 fabric
WW-T01-12005	Columbia	M-0423 4.77	SBR with C125 fabric
WW-T52-13001C	Columbia	M-0214 0.17	SBR with SC150 fabric
WW-T52-13001	Columbia	M-0214 0.17	SBR with SC150 fabric
WW-T01-13002	Columbia	108.67	SBR with SC150 fabric
WW-T01-13003	Columbia	108.75	SBR with SC150 fabric
WW-T01-13004	Columbia	109.17	SBR with SC150 fabric
WW-T06-13001	Columbia	109.93	SBR with SC150 fabric

*Atlantic Sunrise Project – PA DEP Chapter 105 Joint Permit Application
 Transcontinental Gas Pipe Line Company, LLC
 Columbia County
 Attachment L – Environmental Assessment
 Enclosure D – Description of Impacts*

Resource ID	County	MP	Stream Bank Stabilization BMP^a
WW-T06-13002	Columbia	110.20	SBR with SC150 fabric
WW-T35-13002	Columbia	111.23	SBR with SC150 fabric
WW-T35-13001	Columbia	111.59	SBR with SC150 fabric
WW-T90-14003	Columbia	113.37	SBR with SC150 fabric
WW-T21-13001	Columbia	113.43	SBR with SC150 fabric
WW-T21-13001A	Columbia	113.54	SBR with SC150 fabric
WW-T16-14003	Columbia	115.44	SBR with SC150 fabric
WW-T16-14001	Columbia	116.01	SBR with SC150 fabric
WW-T16-14002	Columbia	118.06	SBR with SC150 fabric
WW-T15-14003	Columbia	119.26	SBR with SC150 fabric
WW-T15-14005	Columbia	119.90	SBR with SC150 fabric
WW-T15-14006	Columbia	119.90	SBR with SC150 fabric
WW-T15-14007	Columbia	120.11	SBR with SC150 fabric
WW-T15-14007A	Columbia	120.12	SBR with SC150 fabric
WW-T15-14008	Columbia	121.28	SBR with SC150 fabric
WW-T17-14001	Columbia	122.62	SBR with SC150 fabric
WW-T17-14002	Columbia	123.12	SBR with SC150 fabric
WW-T17-14003	Columbia	123.20	SBR with SC150 fabric
WW-T06-14002	Columbia	124.60	SBR with SC150 fabric
WW-T06-14001	Columbia	124.67	SBR with SC150 fabric
^a	BMP (Best Management Practices) Streambank Restoration Details (SBR) are located in Attachment 2 of Transco's Environmental Construction Plan (Attachment M).		