

**APPENDIX L-3 – TABLE 1  
 STREAMBANK STABILIZATION TABLE**

<b>Resource ID</b>	<b>County</b>	<b>MP</b>	<b>Stream Bank Stabilization BMP<sup>a</sup></b>
WW-T64-4001	Lebanon	36.95	SBR with SC150 fabric
WW-T30-4003	Lebanon	37.25	SBR with SC150 fabric
WW-T30-4002	Lebanon	37.54	SBR with SC150 fabric
WW-T53-4001	Lebanon	M-0300 0.32	SBR with SC150 fabric
WW-T13-4002	Lebanon	41.07	SBR with SC150 fabric
WW-T13-4002A	Lebanon	41.06	SBR with SC150 fabric
WW-T13-4005	Lebanon	41.13	SBR with SC150 fabric
WW-T13-4004	Lebanon	M-0436 0.07	SBR with SC150 fabric
WW-T13-4003	Lebanon	41.92	SBR with SC150 fabric
WW-T33-4001	Lebanon	42.03	SBR with SC150 fabric
WW-T64-5001	Lebanon	42.58	SBR with SC150 fabric
WW-T43-5003	Lebanon	M-0183-1.32	SBR with SC150 fabric
WW-T43-5001	Lebanon	M-0183-1.60	SBR with SC150 fabric
WW-T14-5003	Lebanon	48.14	SBR with SC150 fabric
WW-T14-5004	Lebanon	48.55	SBR with SC150 fabric
WW-T14-5005	Lebanon	48.78	SBR with SC150 fabric
WW-T14-5006	Lebanon	49.30	SBR with SC150 fabric
WW-T14-5006A	Lebanon	49.34	SBR with SC150 fabric
WW-T14-5007	Lebanon	50.06	SBR with SC150 fabric
WW-T99-5008A	Lebanon	50.50	SBR with SC150 fabric
WW-T14-5008	Lebanon	50.53	SBR with SC150 fabric
WW-T14-5009A	Lebanon	51.21	SBR with SC150 fabric
WW-T44-5001	Lebanon	M-0423 0.12	SBR with SC150 fabric
WW-T14-5010	Lebanon	52.65	SBR with SC150 fabric
WW-T14-5011	Lebanon	52.77	SBR with SC150 fabric
WW-T14-5011A	Lebanon	52.78	SBR with SC150 fabric
WW-T14-5013	Lebanon	53.04	SBR with SC150 fabric
WW-T10-6002	Lebanon	53.68	SBR with SC150 fabric
WW-T40-6004	Lebanon	M-0388 0.03	SBR with SC150 fabric
W-T69-6001	Lebanon	54.95	SBR with SC150 fabric
WW-T69-6002	Lebanon	54.99	SBR with SC150 fabric
WW-T69-6001	Lebanon	55.05	SBR with SC150 fabric
WW-T40-6003	Lebanon	M-0168-0.06	SBR with SC150 fabric

**APPENDIX L-3 – TABLE 1  
 STREAMBANK STABILIZATION TABLE**

<b>Resource ID</b>	<b>County</b>	<b>MP</b>	<b>Stream Bank Stabilization BMP<sup>a</sup></b>
WW-T30-6004	Lebanon	55.49	SBR with SC150 fabric
WW-T30-6005	Lebanon	55.68	SBR with SC150 fabric
WW-T32-6001	Lebanon	56.28	SBR with SC150 fabric
WW-T67-6001	Lebanon	56.62	SBR with SC150 fabric
WW-T40-6001A	Lebanon	56.89	SBR with SC150 fabric
WW-T40-6001	Lebanon	M-0205 0.01	SBR with SC150 fabric
WW-T43-6003A	Lebanon	58.51	SBR with SC150 fabric
WW-T43-6004	Lebanon	58.52	SBR with SC150 fabric
WW-T23-6003	Lebanon	58.75	SBR with SC150 fabric
WW-T33-6001	Lebanon	59.32	SBR with SC150 fabric
WW-T43-6001	Lebanon	M-0176-0.10	SBR with SC150 fabric
WW-T44-7002	Lebanon	M-0200-0.27	SBR with SC150 fabric
WW-T23-6001	Lebanon	60.65	SBR with SC150 fabric
WW-T23-6002	Lebanon	61.12	SBR with SC150 fabric
WW-T20-7002	Lebanon	61.17	SBR with SC150 fabric
WW-T20-7001	Lebanon	61.41	SBR with SC150 fabric
WW-T20-7003	Lebanon	61.97	SBR with SC150 fabric
WW-T10-7004	Lebanon	62.52	SBR with SC150 fabric
WW-T10-7003	Lebanon	63.70	SBR with SC150 fabric
WW-T10-7002	Lebanon	63.93	SBR with SC150 fabric
WW-T10-7001	Lebanon	64.07	SBR with SC150 fabric
<sup>a</sup> BMP (Best Management Practices) Streambank Restoration Details (SBR) are located in Attachment 2 of Transco's Environmental Construction Plan (Attachment M).			