

**APPENDIX L-3 - TABLE 1
 STREAMBANK STABILIZATION TABLE**

Resource ID	County	MP	Stream Bank Stabilization BMP^a
WW-T30-21001	Susquehanna	51.4	SBR with SC150 fabric
WW-T12-21004A	Susquehanna	51.7	SBR with SC150 fabric
WW-T12-21004	Susquehanna	51.7	SBR with SC150 fabric
WW-T12-21001	Susquehanna	52.4	SBR with SC150 fabric
WW-T50-21001	Susquehanna	53.4	SBR with SC150 fabric
WW-T50-21002	Susquehanna	54.1	SBR with SC150 fabric
WW-T50-21003	Susquehanna	54.1	SBR with SC150 fabric
WW-T12-21007	Susquehanna	55.1	SBR with SC150 fabric
WW-T12-21007A	Susquehanna	55.1	SBR with SC150 fabric
WW-T92-21002	Susquehanna	MOC-0061 0.07	SBR with SC150 fabric
WW-T12-21009A	Susquehanna	MOC-0061 0.09	SBR with SC150 fabric
WW-T48-21001	Susquehanna	56.8	SBR with SC150 fabric
WW-T17-21001	Susquehanna	57.2	SBR with SC150 fabric
a BMP (Best Management Practices) Streambank Restoration Details (SBR) are located in Attachment 2 of Transco's Environmental Construction Plan (Attachment M).			