

February 8, 2016

Brookhaven Borough Council 2 Cambridge Road Brookhaven, PA 19015

Reference: Sunoco Pipeline L.P. – Pennsylvania Pipeline Project Second Floodplain/Stormwater Management Program Consistency Request

Dear Sir/Madam:

On behalf of Sunoco Pipeline, L.P. (SPLP), Tetra Tech would like to follow-up on the Floodplain/Stormwater Management Program Consistency Request letter we sent to your municipality (same address) dated November 18, 2015. As discussed therein, SPLP in the process of obtaining a Chapter 105 Water Obstruction and Encroachment Permit for its proposed Pennsylvania Pipeline Project (Project). As part of the permit approval process, we respectfully request your review of the Project's consistency with local Floodplain Management and Storm Water Management programs, and a letter confirming the Project's consistency with these programs (as applicable).

A consistency letter from the Borough in regard to the local Floodplain Management and Storm Water Management Program is required pursuant to 25 Pennsylvania Code, Chapter 105 Regulations (Sections 105.14(b)(9), 105.13(e)(1)(v-vi)), and under the Stormwater Management Act (32 P.S.,§§ 680.1—680.17), respectively. Please refer to the previously sent attachments to assist your review. An electronic copy can be provided via email or a hard copy delivered upon request.

If no response is received within 30 days of receipt of this letter, we will understand that there are no issues of concern related to the Project's consistency with the Borough's applicable floodplain and stormwater management programs.

If you have further questions or require additional information, please do not hesitate to contact at (716) 849-9419 or via email at <u>rachel.silva@tetratech.com</u>.

Thank you for your timely response to this matter.


Respectfully yours, Tetra Tech, Inc.

chef & Selva

Rachel Silva

Silva, Rachel

From: Sent: To: Subject: trackingupdates@fedex.com Tuesday, February 09, 2016 11:16 AM Silva, Rachel FedEx Shipment 775596635351 Delivered



Please do not respond to this message. This email was sent from an unattended mailbox. This report was generated at approximately 10:16 AM CST on 02/09/2016.