

Southcentral Region
Changes made to submission from
November 2021 to March 2022

County	ES-Sheet Numbers	Changes made on each sheet
Blair	3.12	CCD concurred with permanent stabilization – Area moved to termination
	3.17	HDD area shaded to identify as part of partial termination
	3.21	HDD area shaded to identify as part of partial termination
	3.22	HDD area shaded to identify as part of partial termination
	3.23	HDD area shaded to identify as part of partial termination
	3.28	CCD concurred with permanent stabilization – Area moved to termination
	3.29	CCD concurred with permanent stabilization – Area moved to termination
	3.30	CCD concurred with permanent stabilization – Area moved to termination
	3.31	CCD concurred with permanent stabilization – Area moved to termination
	3.33	CCD concurred with permanent stabilization – Area moved to termination
	3.34	CCD concurred with permanent stabilization – Area moved to termination, HDD area shaded to identify as part of partial termination
	3.35	HDD area shaded to identify as part of partial termination
	3.36	CCD concurred with permanent stabilization – Area moved to termination, HDD area shaded to identify as part of partial termination
	3.46	CCD concurred with permanent stabilization – Area moved to termination
	3.47	CCD concurred with permanent stabilization – Area moved to termination
	3.50	CCD concurred with permanent stabilization – Area moved to termination
	3.51	CCD concurred with permanent stabilization – Area moved to termination
	3.52	CCD concurred with permanent stabilization – Area moved to termination
	3.53	CCD concurred with permanent stabilization – Area moved to termination
3.54	CCD concurred with permanent stabilization – Area moved to termination	
Huntingdon	3.09 to 3.12	HDD area shaded to identify as part of partial termination
	3.11	CCD did not concur with permanent stabilization - Area moved to renewal
	3.18	HDD area shaded to identify as part of partial termination
	3.21 to 3.24	HDD area shaded to identify as part of partial termination
	3.32 to 3.33	HDD area shaded to identify as part of partial termination
	3.33	CCD did not concur with permanent stabilization - Area moved to renewal
	3.56	CCD concurred with permanent stabilization – Area moved to termination
	3.61	HDD area shaded to identify as part of partial termination
	3.73	HDD area shaded to identify as part of partial termination
	3.80	CCD did not concur with permanent stabilization - Area moved to renewal
3.82	CCD concurred with permanent stabilization – Area moved to termination	
Juniata	3.01	CCD concurred with permanent stabilization – Area moved to termination
	3.02	CCD concurred with permanent stabilization – Area moved to termination
	3.03	CCD concurred with permanent stabilization – Area moved to termination
	3.04	CCD concurred with permanent stabilization – Area moved to termination
	3.05	CCD concurred with permanent stabilization – Area moved to termination, HDD area shaded to identify as part of partial termination
	3.06	CCD concurred with permanent stabilization – Area moved to termination
	3.07	CCD concurred with permanent stabilization – Area moved to termination
	3.08	CCD concurred with permanent stabilization – Area moved to termination
	3.09	CCD concurred with permanent stabilization – Area moved to termination

Southcentral Region
Changes made to submission from
November 2021 to March 2022

County	ES-Sheet Numbers	Changes made on each sheet
Perry	3.01	CCD did not concur with permanent stabilization - Area moved to renewal
	3.02	CCD did not concur with permanent stabilization - Area moved to renewal
	3.20	CCD did not concur with permanent stabilization - Area moved to renewal
	3.21	CCD did not concur with permanent stabilization - Area moved to renewal
	3.26	CCD did not concur with permanent stabilization - Area moved to renewal
	3.34	CCD did not concur with permanent stabilization - Area moved to renewal
	3.35	CCD did not concur with permanent stabilization - Area moved to renewal
Cumberland	4.04	CCD did not concur with permanent stabilization - Area moved to renewal, HDD area shaded to identify as part of partial termination
	4.05	HDD area shaded to identify as part of partial termination
	4.16	CCD did not concur with permanent stabilization - Area moved to renewal
	4.17	CCD did not concur with permanent stabilization - Area moved to renewal
	4.21	HDD area shaded to identify as part of partial termination
	4.22	CCD did not concur with permanent stabilization - Area moved to renewal, HDD area shaded to identify as part of partial termination
	4.24	CCD did not concur with permanent stabilization - Area moved to renewal, HDD area shaded to identify as part of partial termination
	4.25	HDD area shaded to identify as part of partial termination
	4.26	CCD did not concur with permanent stabilization - Area moved to renewal, HDD area shaded to identify as part of partial termination
	4.27	CCD did not concur with permanent stabilization - Area moved to renewal, HDD area shaded to identify as part of partial termination
	4.33	CCD did not concur with permanent stabilization - Area moved to renewal
	4.49	HDD area shaded to identify as part of partial termination
	4.51	HDD area shaded to identify as part of partial termination
	4.52	HDD area shaded to identify as part of partial termination
	4.57	HDD area shaded to identify as part of partial termination
	4.58 to 4.60	HDD area shaded to identify as part of partial termination
	4.64 to 4.65	HDD area shaded to identify as part of partial termination
	4.66	CCD did not concur with permanent stabilization - Area moved to renewal
	4.67	CCD did not concur with permanent stabilization - Area moved to renewal
	4.68	CCD did not concur with permanent stabilization - Area moved to renewal
4.89 to 4.90	HDD area shaded to identify as part of partial termination	
4.92 to 4.93	HDD area shaded to identify as part of partial termination	
4.96	HDD area shaded to identify as part of partial termination	
4.100 to 4.101	HDD area shaded to identify as part of partial termination	
York	4.01	CCD did not concur with permanent stabilization - Area moved to renewal, HDD area shaded to identify as part of partial termination
	4.02	CCD did not concur with permanent stabilization - Area moved to renewal
	4.03	CCD did not concur with permanent stabilization - Area moved to renewal
	4.04	HDD area shaded to identify as part of partial termination
	4.16	CCD did not concur with permanent stabilization - Area moved to renewal
Dauphin	4.01 to 4.02	HDD area identified as no LOD or disturbance and is part of partial termination
	4.03 to 4.04	HDD area shaded to identify as part of partial termination
	4.05	CCD concurred with permanent stabilization – Area moved to termination
	4.06	CCD concurred with permanent stabilization – Area moved to termination, HDD area shaded to identify as part of partial termination

Southcentral Region
Changes made to submission from
November 2021 to March 2022

County	ES-Sheet Numbers	Changes made on each sheet
Dauphin	4.07	HDD area shaded to identify as part of partial termination
	4.09 to 4.10	HDD area shaded to identify as part of partial termination
	4.13	CCD did not concur with permanent stabilization - Area moved to renewal
	4.15	HDD area shaded to identify as part of partial termination
	4.17	CCD concurred with permanent stabilization – Area moved to termination, HDD area shaded to identify as part of partial termination
	4.18	CCD concurred with permanent stabilization – Area moved to termination, HDD area shaded to identify as part of partial termination
	4.19	CCD concurred with permanent stabilization – Area moved to termination
	4.23 to 4.25	HDD area shaded to identify as part of partial termination
	4.25	CCD concurred with permanent stabilization – Area moved to termination
	4.26	CCD concurred with permanent stabilization – Area moved to termination
	4.27	CCD concurred with permanent stabilization – Area moved to termination, HDD area shaded to identify as part of partial termination
	4.28 to 4.29	HDD area shaded to identify as part of partial termination
	4.38 to 4.39	HDD area shaded to identify as part of partial termination
Lancaster	1.01 to 1.05	CCD did not concur with permanent stabilization - Area moved to renewal
	1.11 to 1.13	HDD area shaded to identify as part of partial termination
	1.20	CCD did not concur with permanent stabilization - Area moved to renewal
	1.21	CCD did not concur with permanent stabilization - Area moved to renewal
Lebanon	5.01 to 5.02	HDD area shaded to identify as part of partial termination
	5.04 to 5.05	HDD area shaded to identify as part of partial termination
	5.66 to 5.67	HDD area shaded to identify as part of partial termination
Berks	5.27	HDD area shaded to identify as part of partial termination
	5.28	HDD area shaded to identify as part of partial termination
	5.29	HDD area shaded to identify as part of partial termination
	5.45	HDD area shaded to identify as part of partial termination
	5.46	HDD area shaded to identify as part of partial termination
	5.88	HDD area identified as part of permit renewal area

Notes for 2022 submission:

1. Gray shading was added to areas requesting termination per public comment.
2. Red comment block was added to each E&S plan sheet stating that drawing and text elements in red represent approved changes made since original permit authorization on February 12,2017.
3. Extended partial termination shading was provided over all completed HDDs even if LOD was not shown over drill. Refer to the list above for more details.
4. For areas where CCD did not concur with permanent stabilization, they were moved to renewal. Refer to the list above for more details.
5. Updated communications and inspection reports were added to the submission package for all counties in the region.
6. Tracking tables for all counties were revised and indicated in red on the table.