

## LIST OF TABLES

### Chapter 1

Table 1.1 Annual and total summary of FBC ash generated in Pennsylvania to date .....	10
Table 1.2 Coal ash use at mine sites in Pennsylvania (annual use rates).....	11

### Chapter 2

Table 2.1 Mine drainage quality of the Bituminous and Anthracite Coal Regions of PA .....	48
---	----

### Chapter 3

Table 3.1 Field density test data at Panther Creek Energy .....	59
Table 3.2(a) Soil boring logs from NEPCO site TB-1.....	61
Table 3.2(b) Test boring logs from NEPCO site TB-2.....	61
Table 3.3 Soil boring logs from Knickerbocker Site .....	63
Table 3.4 Coal ash special conditions used in DEP permits.....	65
Table 3.5 Comparison of physical properties of coal ash, sand and clay .....	69
Table 3.6 Bearing capacity results for NEPCO .....	69

### Chapter 4

Table 4.1 Geotechnical data from ash reclamation area at Alden site.....	81
Table 4.2 Chemical analyses of Gilberton coal ash and SPLP leachate.....	92
Table 4.3 Chemical analyses of SER coal ash and SPLP leachate.....	96
Table 4.4 Groundwater monitoring data for B-D and SER sites in (mg/L).....	98
Table 4.5 Groundwater monitoring data of Susquehanna site in (mg/L) .....	107

### Chapter 5

Table 5.1 Comparison of background pollutant concentrations to recent concentrations in MW-1 .....	125
Table 5.2 Reduction in flow and concentrations at discharge 4SP.....	127
Table 5.3 Summary of flow and AMD pollutant load data for the discharges from the Revloc 1 site.....	129
Table 5.4 Summary of flow and AMD pollutant load data from the Revloc 2 site discharges .....	131
Table 5.5 Comparison of background median flow and mine drainage pollutant concentrations at SP-1, the monitoring point on the South Branch directly down stream of the Revloc 1 and 2 sites .....	131
Table 5.6 Summary of overburden analysis data for the Laurel Land Development McDermott site .....	138
Table 5.7 Summary of the overburden analysis data for the Abel-Dreshman site .....	147
Table 5.8 Sample results of July 29, 1982 showing the quality of AMD occurring on site that day .....	147

Table 5.9 Summary of mine drainage parameter results at point 29A, comparing the periods, before, during and after ash application and reclamation .....	149
Table 5.10 Summary of mine drainage parameter results at point 29B, comparing the periods, before, during and after ash application and reclamation .....	150
Table 5.11 Summary of mine drainage parameter results at point 29, comparing the periods, before, during and after ash application and reclamation .....	150

## **Chapter 6**

Table 6.1 Coal Ash use in Anthracite Mine Fire Projects .....	164
Table 6.2 Thickness coal veins (from Norris and Sons, 1927).....	168
Table 6.3 Laboratory tests of various grout mixtures .....	173
Table 6.4 Summary of project-scale grout mixture strength tests (from Levitz, 2003).....	174
Table 6.5 Influent and effluent water quality from aerobic constructed wetland.....	180
Table 6.6 Typical chemical characteristics of fly ash leachates used at the McCloskey site. (Data provided by B. E. Scheetz from TCLP extracts) .....	182
Table 6.7 Mine drainage discharge quality sampled in 1997. Concentration of AMD parameters for 9/2003 are shown in parenthesis followed by an * .....	184
Table 6.8 Pre-grouting water quality from selected groundwater monitoring points. Note the wide variety in concentrations from one monitoring point to the next, Especially Well K23 .....	189
Table 6.9 Percent reductions in mean concentrations as a result of the three grouting applications .....	193
Table 6.10 Pre- and post-grouting mean concentrations of mine drainage constituents and percent reduction in mean concentration for wells and toe of spoil seep located in discharge plumes. For locations refer to Fig. 6.21 .....	197

## **Chapter 7**

Table 7.1 Average thickness and range in thickness of coal beds mined in the eastern part of the Shenandoah quadrangle.....	211
Table 7.2 Analytical results for depth sampling of the Shen Penn pit. Samples collected on 3 May 1995. Concentrations are in mg/L. LD = less than detection. Values for As, Cd, Cr, and Hg were less than the detection level for all samples. Data from PA DEP* .....	216
Table 7.3 Chemical Analysis of SPLP Leach Test, with all concentrations in mg/L.....	218
Table 7.4 Sieve Analysis 60:40 Mix Schuylkill Energy Resources Ash.....	218
Table 7.5. Unconfined compressive strength of LKD activated fly ash grouts as a function of time .....	222
Table 7.6 Unconfined compressive strength of CKD activated fly ash grouts as a function of time. ....	224
Table 7.7 Variation in compaction pressure with depth under a load .....	224

## **Chapter 8**

Table 8.1. Cs-137 densitometer results collected by Tom Owen, July, 2000.....	236
Table 8.2. Percent grain size distribution ( $\mu\text{m}$ ) .....	236
Table 8.3. Mean and standard deviation data for blow counts per foot recorded at the center of cells 1 – 4 in November 2000 .....	238
Table 8.4. Range of concentrations in sediment (using the SPLP test) and in water from the Knickerbocker test cells, February 2000. For comparison, the maximum concentration levels (MCL) of contamination for drinking water as of 2002 are given .	240
Table 8.5. Average bulk chemical concentrations from the four test cells.....	241
Table 8.6. Test cell moisture loss values of samples collected November 2000.....	242

## **Chapter 9**

Table 9.1. Summary of coal production, water, sulfate, acid, and iron yields from the four anthracite fields in eastern Pennsylvania (from Growitz et al., 1985) .....	251
Table 9.2 Summary of water and sulfate discharge from mine drainage sites in the Southern Field (from Growitz et al., 1985).....	251
Table 9.3 Placement and volume estimates for the Big Gorilla calculated from depth traverses .....	256
Table 9.4 Average of values above detection from analyses performed on NEPCO fly and bottom ash for Module 25 regulations from 1992-2002. Maximum allowable leachate concentration values provided for comparison.....	258
Table 9.5 Comparison of bulk chemical analyses versus average composition of five culm-derived ash analyses. Values were calculated from aqueous chemistry by S. Atkinson.....	259
Table 9.6 Mineralogical analysis of culm-derived fly ash used in the “Big Gorilla” project .....	259
Table 9.7 Average, maximum, and minimum concentrations for analytes above detection limits in the Big Gorilla mine pool 1993-2002. Count is the number of above detection limit values used for the calculations. Note that true averages and minimums would be less if the concentrations below the detection limits were included.....	266
Table 9.8 Calculations of calcium June-November 1998 showing that approximately 1.24% of the calcium is available .....	276
Table 9.9 Selected chemical analyses from the Big Gorilla mine pool, analyzed by PA DEP. All concentrations are total and for a surface sample, except for 10/27/99, which was taken at a depth of 6m (20ft.).....	282
Table 9.10 Average of water chemistry of wells sampled 4 times a year on or near the NEPCO property. All concentrations reported in mg/L except for conductivity ( $\mu\text{S}/\text{cm}$ ), turbidity (ntu), and pH. Average values are calculated from concentrations above the detection limit, and (T) indicates total (dissolved and suspended) concentration. Samples analyzed by PA DEP .....	291
Table 9.11 Water analyses for NEPCO test borings. Analyzed by Scott Atkinson at MRL, PSU. All concentrations are for dissolved constituents and are reported in mg/L. V was <0.02 mg/L, and As was <0.005 mg/L .....	295

## **Chapter 10**

Table 10.1 Chemical analysis (total digestion) of 9 Class C and 49 Class F fly ashes (from Miller et al., 2000) .....	304
Table 10.2 Mineral composition of fluidized bed boiler ashes (Stehouwer et al., 1995a) ...	304
Table 10.3 Chemical composition of gypsum-containing clean coal combustion by- products (Miller et al., 2000) .....	305
Table 10.4 Soil pH ranges for selected plants.....	312

## **Chapter 11**

Table 11.1 Summary of the solubility products of phases in the ash structure .....	328
Table 11.2 Reported substitutions in the ettringite structure .....	336