

UNRESOLVED DAMAGE AND WATER LOSS REPORTED TO DEP

April 4, 2013

Company Name	Permit Name	Problem ID	Date Received	Claim No.	Feature Type	Type of Investigation	Interim Resolution	County	Municipality
AMFIRE MINING COMPANY LLC	DORA 8 DEEP MINE	3887	40442	P1043	Well	Water Loss	Implementing WS Replacement Plan	Indiana	North Mahoning
DORA 8 DEEP MINE TOTAL CASES = 1									
AMFIRE MINING COMPANY LLC	GILLHOUSER RUN MINE	4495	41239	P1262	Well	Water Loss	Implementing WS Replacement Plan	Indiana	Brush Valley
GILLHOUSER RUN MINE TOTAL CASES = 1									
AMFIRE MINING COMPANY LLC	NOLO MINE	3065	39449	P0825	Well	Water Loss	O&M Review	Indiana	Buffington
AMFIRE MINING COMPANY LLC	NOLO MINE	3665	40127	WL0979	Well	Water Loss	Implementing WS Replacement Plan	Indiana	Pine
AMFIRE MINING COMPANY LLC	NOLO MINE	3780	40295	P1022	Well	Water Loss	WS Replacement Plan Under Review	Indiana	Pine
AMFIRE MINING COMPANY LLC	NOLO MINE	3829	40365	P1031	Well	Water Loss	Implementing WS Replacement Plan	Indiana	Buffington
AMFIRE MINING COMPANY LLC	NOLO MINE	3929	40480	P1103	Well	Water Loss	Implementing WS Replacement Plan	Indiana	Pine
NOLO MINE TOTAL CASES = 5									
AMFIRE MINING COMPANY LLC	ONDO MINE	3350	39759	P0871	Well	Water Loss	Implementing WS Replacement Plan	Indiana	Brush Valley
AMFIRE MINING COMPANY LLC	ONDO MINE	3611	40080	P0946	Spring	Water Loss	O&M Review	Indiana	Brush Valley
AMFIRE MINING COMPANY LLC	ONDO MINE	3869	40424	P1044	Well	Water Loss	Awaiting Additional Effects	Indiana	Brush Valley
AMFIRE MINING COMPANY LLC	ONDO MINE	3947	40492	P1101	Well	Water Loss	Implementing WS Replacement Plan	Indiana	Brush Valley
AMFIRE MINING COMPANY LLC	ONDO MINE	4275	41029	P1217	Well	Water Contamination	Rebuttal Review	Indiana	Brush Valley
AMFIRE MINING COMPANY LLC	ONDO MINE	4571	41324	SA1882	Trailer	Structure Damage	Unresolved/Pending Investigation	Indiana	Brush Valley
ONDO MINE TOTAL CASES = 6									
AMFIRE MINING COMPANY LLC	RIDGE MINE	4058	40695	P1128	Well	Water Contamination	Currently Monitoring	Indiana	Young
AMFIRE MINING COMPANY LLC	RIDGE MINE	4146	40807	P1137	Well	Water Loss	O&M Review	Indiana	Young
AMFIRE MINING COMPANY LLC	RIDGE MINE	4272	41023	P1212	Well	Water Loss	Implementing WS Replacement Plan	Armstrong	South Bend
AMFIRE MINING COMPANY LLC	RIDGE MINE	4292	41054	P1221	Spring	Water Loss	Implementing WS Replacement Plan	Armstrong	South Bend
AMFIRE MINING COMPANY LLC	RIDGE MINE	4354	41107	P1234	Well	Water Loss	Implementing WS Replacement Plan	Armstrong	South Bend
RIDGE MINE TOTAL CASES = 5									
AMFIRE MINING COMPANY LLC TOTAL CASES = 18									
CANTERBURY COAL CO	DAVID DIANNE MINE	4135	40785	P1135	Well	Water Loss	Implementing WS Replacement Plan	Armstrong	Kiskiminetas
DAVID DIANNE MINE TOTAL CASES = 1									
CANTERBURY COAL CO TOTAL CASES = 1									
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	2645	38897	WL0626	Well	Water Loss	WS Replacement Plan Under Review	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	2718	38897	WL0626	Spring	Water Loss	WS Replacement Plan Under Review	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	2685	38972	P0663	Well	Water Loss	Implementing WS Replacement Plan	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	2703	38980	P0667	Spring	Water Loss	Implementing WS Replacement Plan	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	2975	39377	P0736	Spring	Water Loss	Implementing WS Replacement Plan	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	3013	39391	P0819	Spring	Water Loss	Implementing WS Replacement Plan	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	3024	39405	P0818	Well	Water Loss	Implementing WS Replacement Plan	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	3025	39405	P0818-1	Spring	Water Loss	Implementing WS Replacement Plan	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	3039	39406	P0821	Well	Water Loss	Implementing WS Replacement Plan	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	3040	39406	P0821-1	Spring	Water Loss	Implementing WS Replacement Plan	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	3051	39419	P0823	Well	Water Loss	Well, Spring/O&M Pending	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	3206	39601		Trailer	Structure Damage	In Negotiation	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	3297	39716	P0855	Spring	Water Loss	Implementing WS Replacement Plan	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	3317	39730	P0864	Well	Water Loss	Implementing WS Replacement Plan	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	3378	39777	SA1736	Other	Structure Damage	In Litigation	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	3400	39792	P0873	Well	Water Loss	Evaluate Permanent Supply	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	3436	39854	P0923	Well	Water Loss	Implementing WS Replacement Plan	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	3438	39854	P0924	Well	Water Loss	Implementing WS Replacement Plan	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	3612	40084	P0952	Well	Water Loss	Implementing WS Replacement Plan	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	3664	40137	P1003	Well	Water Loss	Implementing WS Replacement Plan	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	3734	40205	P1008-1	Spring	Water Loss	Implementing WS Replacement Plan	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	3747	40235	P1008-2	Spring	Water Loss	Implementing WS Replacement Plan	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	3750	40247	P1008-3	Spring	Water Loss	Implementing WS Replacement Plan	Greene	Richhill

UNRESOLVED DAMAGE AND WATER LOSS REPORTED TO DEP

April 4, 2013

Company Name	Permit Name	Problem ID	Date Received	Claim No.	Feature Type	Type of Investigation	Interim Resolution	County	Municipality
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	3817	40347		Land	Structure Damage	Currently Monitoring	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	3818	40347	P1008-4	Spring	Water Loss	Implementing WS Replacement Plan	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	3823	40351	P1008-5	Spring	Water Loss	Implementing WS Replacement Plan	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	3824	40351	P1008-6	Spring	Water Loss	Implementing WS Replacement Plan	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	3825	40351	P1008-7	Spring	Water Loss	Implementing WS Replacement Plan	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	3907	40457	P1048	Spring	Water Loss	Implementing WS Replacement Plan	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	3966	40526		Dwelling	Structure Damage	Currently Monitoring	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	3967	40526		Barn	Structure Damage	Currently Monitoring	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	4005	40630		Land	Land Damage	Currently Monitoring	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	4116	40760		Dwelling	Structure Damage	Currently Monitoring	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	4118	40760		Land	Land Damage	Currently Monitoring	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	4151	40828		Garage	Structure Damage	Currently Monitoring	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	4155	40830		Land	Land Damage	Currently Monitoring	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	4205	40934		Dwelling	Structure Damage	Currently Monitoring	Greene	Aleppo
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	4345	41089	P1229-1	Spring	Water Loss	Implementing WS Replacement Plan	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	4346	41089	P1229-2	Spring	Water Loss	Implementing WS Replacement Plan	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	4347	41089	P1229-3	Spring	Water Loss	Implementing WS Replacement Plan	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	4348	41100	P1229-4	Spring	Water Loss	Implementing WS Replacement Plan	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	4360	41110	P1229-5	Well	Water Loss	Implementing WS Replacement Plan	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	4361	41110	P1229-6	Well	Water Loss	Implementing WS Replacement Plan	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	4388	41134	P1235	Spring	Water Loss	Implementing WS Replacement Plan	Greene	Aleppo
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	4473	41212	P1256	Well	Water Loss	WS Replacement Plan Under Review	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	4505	41240	SA1884	Land	Land Damage	Unresolved/Pending Investigation	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	4570	41318		Spring	Water Loss	Awaiting Additional Effects	Greene	Richhill
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	4569	41324		Dwelling	Structure Damage	Currently Monitoring	Greene	Aleppo
CONSOL PA COAL CO LLC	BAILEY DEEP MINE	4587	41348	P1311	Well	Water Contamination	WS Replacement Plan Under Review	Greene	Aleppo
	BAILEY DEEP MINE TOTAL CASES = 49								
CONSOL PA COAL CO LLC	ENLOW FORK MINE	2455	38775	WL0617	Spring	Water Loss	WS Replacement Plan Under Development	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	2809	39160		Barn	Structure Damage	In Negotiation	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	2907	39301	P0726	Spring	Water Loss	O&M Review	Washington	Morris
CONSOL PA COAL CO LLC	ENLOW FORK MINE	2959	39359	P0747	Well	Water Loss	Implementing WS Replacement Plan	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	2966	39370	P0741	Spring	Water Loss	Well, Spring/O&M Pending	Washington	Morris
CONSOL PA COAL CO LLC	ENLOW FORK MINE	2969	39370	P0738	Spring	Water Loss	O&M Review	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	2973	39377	P0743	Well	Water Loss	Implementing WS Replacement Plan	Washington	Morris
CONSOL PA COAL CO LLC	ENLOW FORK MINE	3015	39392	P0812	Well	Water Loss	Implementing WS Replacement Plan	Greene	Morris
CONSOL PA COAL CO LLC	ENLOW FORK MINE	3016	39392	P0813	Well	Water Loss	Evaluate Permanent Supply	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	3011	39401	P0817	Well	Water Loss	Implementing WS Replacement Plan	Washington	West Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	3071	39456	P0828	Spring	Water Loss	Implementing WS Replacement Plan	Greene	Morris
CONSOL PA COAL CO LLC	ENLOW FORK MINE	3084	39485	P0827	Spring	Water Loss	Implementing WS Replacement Plan	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	3184	39575	P0846	Spring	Water Loss	Evaluate Permanent Supply	Greene	Morris
CONSOL PA COAL CO LLC	ENLOW FORK MINE	3238	39639	P0849-2	Well	Water Loss	Evaluate Permanent Supply	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	3295	39713		Well	Water Loss	Evaluate Permanent Supply	Washington	Morris
CONSOL PA COAL CO LLC	ENLOW FORK MINE	3328	39736	P0865-2	Well	Water Loss	Evaluate Permanent Supply	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	3329	39736	P0865-1	Spring	Water Loss	Implementing WS Replacement Plan	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	3322	39737	P0863	Well	Water Loss	Evaluate Permanent Supply	Washington	West Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	3340	39751	P0875	Well	Water Loss	Temp Water/Will Be Undermined	Greene	Morris
CONSOL PA COAL CO LLC	ENLOW FORK MINE	3341	39751	P0876	Well	Water Loss	Implementing WS Replacement Plan	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	3368	39765		Land	Land Damage	Performing Repairs	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	3395	39777		Land	Land Damage	Currently Monitoring	Washington	East Finley

UNRESOLVED DAMAGE AND WATER LOSS REPORTED TO DEP

April 4, 2013

Company Name	Permit Name	Problem ID	Date Received	Claim No.	Feature Type	Type of Investigation	Interim Resolution	County	Municipality
CONSOL PA COAL CO LLC	ENLOW FORK MINE	3420	39826	P0921	Well	Water Loss	Implementing WS Replacement Plan	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	3448	39874	P0926	Well	Water Loss	Implementing WS Replacement Plan	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	3549	40016	P0937	Well	Water Loss	Temp Water/Will Be Undermined	Washington	West Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	3583	40044		Land	Land Damage	Performing Repairs	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	3590	40060	WL0959	Spring	Water Loss	Temporary Water	Washington	Morris
CONSOL PA COAL CO LLC	ENLOW FORK MINE	3638	40109	P0957	Spring	Water Loss	Implementing WS Replacement Plan	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	3663	40134	P1002	Well	Water Loss	Implementing WS Replacement Plan	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	3739	40213		Dwelling	Structure Damage	Currently Monitoring	Washington	West Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	3757	40255	P1014-1	Spring	Water Loss	Temporary Water	Washington	Morris
CONSOL PA COAL CO LLC	ENLOW FORK MINE	3785	40255	P1014-2	Spring	Water Loss	Implementing WS Replacement Plan	Washington	Morris
CONSOL PA COAL CO LLC	ENLOW FORK MINE	3786	40255	P1014-3	Spring	Water Loss	Implementing WS Replacement Plan	Washington	Morris
CONSOL PA COAL CO LLC	ENLOW FORK MINE	3787	40255	P1014-4	Spring	Water Loss	Implementing WS Replacement Plan	Washington	Morris
CONSOL PA COAL CO LLC	ENLOW FORK MINE	3788	40255	P1014-5	Spring	Water Loss	Implementing WS Replacement Plan	Washington	Morris
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4015	40632	P1121	Well	Water Loss	Implementing WS Replacement Plan	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4055	40690		Barn	Structure Damage	Currently Monitoring	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4056	40690		Side Walk	Land Damage	Currently Monitoring	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4088	40735		Garage	Structure Damage	Currently Monitoring	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4089	40735		Driveway	Structure Damage	Currently Monitoring	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4142	40793	P1131	Well	Water Contamination	Under Appeal	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4264	41011	P1211	Well	Water Loss	Implementing WS Replacement Plan	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4267	41021	P1213	Well	Water Loss	Implementing WS Replacement Plan	Washington	South Franklin
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4285	41053	P1220	Well	Water Loss	Implementing WS Replacement Plan	Washington	South Franklin
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4300	41064	WL1212	Well	Water Loss	Unresolved/Pending Investigation	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4318	41074	P1228	Well	Water Loss	Implementing WS Replacement Plan	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4365	41117		Trailer	Structure Damage	Currently Monitoring	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4381	41128	WL1230	Well	Water Contamination	Unresolved/Pending Investigation	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4389	41136		Dwelling	Structure Damage	Currently Monitoring	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4393	41141	P1240	Spring	Water Loss	Implementing WS Replacement Plan	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4395	41145	P1244	Well	Water Loss	Implementing WS Replacement Plan	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4435	41180	P1246	Well	Water Contamination	Implementing WS Replacement Plan	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4444	41192	WL1239	Well	Water Loss	Unresolved/Pending Investigation	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4465	41206	WL1243	Well	Water Loss	Unresolved/Pending Investigation	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4471	41212	P1260-1	Well	Water Loss	Implementing WS Replacement Plan	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4472	41212	P1260-2	Spring	Water Loss	Implementing WS Replacement Plan	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4475	41214	WL1245	Well	Water Contamination	Unresolved/Pending Investigation	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4488	41225	P1259	Well	Water Loss	WS Replacement Plan Under Review	Greene	Morris
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4490	41226		Land	Land Damage	Currently Monitoring	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4500	41234		Well	Water Contamination	Temp Water Offered/Homeowner Declined	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4507	41241	P1264-1	Spring	Water Loss	Implementing WS Replacement Plan	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4520	41250	P1264-2	Well	Water Loss	WS Replacement Plan Under Review	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4547	41296		Garage	Structure Damage	Currently Monitoring	Washington	South Franklin
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4581	41339		Well	Water Contamination	Temp Water Offered/Homeowner Declined	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4591	41354		Well	Water Contamination	Currently Monitoring	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4595	41354	WL1310	Well	Water Loss	Unresolved/Pending Investigation	Washington	East Finley
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4597	41359		Dwelling	Structure Damage	Currently Monitoring	Washington	South Franklin
CONSOL PA COAL CO LLC	ENLOW FORK MINE	4598	41359		Barn	Structure Damage	Currently Monitoring	Washington	South Franklin
ENLOW FORK MINE TOTAL CASES = 68									
CONSOL PA COAL CO LLC TOTAL CASES = 117									
CONSOLIDATION COAL CO	BLACKSVILLE 2 MINE	2957	39357	P0734-1	Spring	Water Loss	Implementing WS Replacement Plan	Greene	Wayne

UNRESOLVED DAMAGE AND WATER LOSS REPORTED TO DEP

April 4, 2013

Company Name	Permit Name	Problem ID	Date Received	Claim No.	Feature Type	Type of Investigation	Interim Resolution	County	Municipality
CONSOLIDATION COAL CO	BLACKSVILLE 2 MINE	4274	41023	P1216-1	Well	Water Loss	Implementing WS Replacement Plan	Greene	Jackson
CONSOLIDATION COAL CO	BLACKSVILLE 2 MINE	4316	41074	P1226-2	Well	Water Contamination	Implementing WS Replacement Plan	Greene	Jackson
CONSOLIDATION COAL CO	BLACKSVILLE 2 MINE	4317	41074	P1226-1	Well	Water Contamination	Implementing WS Replacement Plan	Greene	Jackson
CONSOLIDATION COAL CO	BLACKSVILLE 2 MINE	4410	41151	P1226-3	Spring	Water Loss	Implementing WS Replacement Plan	Greene	Gilmore
CONSOLIDATION COAL CO	BLACKSVILLE 2 MINE	4498	41232		Land	Land Damage	Currently Monitoring	Greene	Jackson
CONSOLIDATION COAL CO	BLACKSVILLE 2 MINE	4501	41240	P1216-2	Well	Water Contamination	WS Replacement Plan Under Review	Greene	Jackson
CONSOLIDATION COAL CO	BLACKSVILLE 2 MINE	4506	41242	P1216-3	Stream	Water Loss	WS Replacement Plan Under Review	Greene	Jackson
CONSOLIDATION COAL CO	BLACKSVILLE 2 MINE	4515	41247		Dwelling	Structure Damage	Currently Monitoring	Greene	Jackson
CONSOLIDATION COAL CO	BLACKSVILLE 2 MINE	4516	41247		Garage	Structure Damage	Currently Monitoring	Greene	Jackson
CONSOLIDATION COAL CO	BLACKSVILLE 2 MINE	4517	41247		Barn	Structure Damage	Currently Monitoring	Greene	Jackson
CONSOLIDATION COAL CO	BLACKSVILLE 2 MINE	4518	41247		Outbuilding	Structure Damage	Currently Monitoring	Greene	Jackson
CONSOLIDATION COAL CO	BLACKSVILLE 2 MINE	4573	41327	P0734-2	Spring	Water Loss	WS Replacement Plan Under Review	Greene	Wayne
BLACKSVILLE 2 MINE TOTAL CASES = 13									
CONSOLIDATION COAL CO	DILWORTH DEEP MINE	4111	40760		Land	Land Damage	Currently Monitoring	Greene	Jefferson
DILWORTH DEEP MINE TOTAL CASES = 1									
CONSOLIDATION COAL CO TOTAL CASES = 14									
CUMBERLAND RESOURCES LP	CUMBERLAND MINE	3514	39976	P0931	Well	Water Loss	Implementing WS Replacement Plan	Greene	Whiteley
CUMBERLAND RESOURCES LP	CUMBERLAND MINE	3572	40038		Dwelling	Structure Damage	Currently Monitoring	Greene	Whiteley
CUMBERLAND RESOURCES LP	CUMBERLAND MINE	3802	40318	P1028	Well	Water Loss	Rebuttal Review	Greene	Whiteley
CUMBERLAND RESOURCES LP	CUMBERLAND MINE	3935	40485		Land	Land Damage	Performing Repairs	Greene	Center
CUMBERLAND RESOURCES LP	CUMBERLAND MINE	4120	40765		Church	Structure Damage	Currently Monitoring	Greene	Wayne
CUMBERLAND RESOURCES LP	CUMBERLAND MINE	4139	40792	P1134	Well	Water Contamination	Implementing WS Replacement Plan	Greene	Wayne
CUMBERLAND RESOURCES LP	CUMBERLAND MINE	4282	41051		Dwelling	Structure Damage	Currently Monitoring	Greene	Wayne
CUMBERLAND RESOURCES LP	CUMBERLAND MINE	4283	41051		Garage	Structure Damage	Currently Monitoring	Greene	Wayne
CUMBERLAND RESOURCES LP	CUMBERLAND MINE	4284	41051		Barn	Structure Damage	Currently Monitoring	Greene	Wayne
CUMBERLAND RESOURCES LP	CUMBERLAND MINE	4286	41054		Dwelling	Structure Damage	Currently Monitoring	Greene	Wayne
CUMBERLAND RESOURCES LP	CUMBERLAND MINE	4288	41054		Barn	Structure Damage	Currently Monitoring	Greene	Wayne
CUMBERLAND RESOURCES LP	CUMBERLAND MINE	4290	41054	P1223-1	Spring	Water Loss	Implementing WS Replacement Plan	Greene	Wayne
CUMBERLAND RESOURCES LP	CUMBERLAND MINE	4291	41054	P1223-2	Well	Water Loss	Implementing WS Replacement Plan	Greene	Wayne
CUMBERLAND RESOURCES LP	CUMBERLAND MINE	4293	41054		Land	Land Damage	Currently Monitoring	Greene	Wayne
CUMBERLAND RESOURCES LP	CUMBERLAND MINE	4294	41054		Pool	Structure Damage	Currently Monitoring	Greene	Wayne
CUMBERLAND RESOURCES LP	CUMBERLAND MINE	4399	41150	P1242	Spring	Water Loss	Implementing WS Replacement Plan	Greene	Wayne
CUMBERLAND RESOURCES LP	CUMBERLAND MINE	4403	41158	P1248	Well	Water Loss	Implementing WS Replacement Plan	Greene	Wayne
CUMBERLAND RESOURCES LP	CUMBERLAND MINE	4404	41158		Land	Land Damage	Currently Monitoring	Greene	Wayne
CUMBERLAND RESOURCES LP	CUMBERLAND MINE	4493	41228	P1303	Well	Water Loss	Implementing WS Replacement Plan	Greene	Wayne
CUMBERLAND RESOURCES LP	CUMBERLAND MINE	4494	41229	P1263-1	Spring	Water Loss	Implementing WS Replacement Plan	Greene	Wayne
CUMBERLAND RESOURCES LP	CUMBERLAND MINE	4496	41229	P1263-2	Well	Water Loss	Implementing WS Replacement Plan	Greene	Wayne
CUMBERLAND RESOURCES LP	CUMBERLAND MINE	4532	41282		Dwelling	Structure Damage	Currently Monitoring	Greene	Wayne
CUMBERLAND RESOURCES LP	CUMBERLAND MINE	4534	41285		Land	Land Damage	Currently Monitoring	Greene	Wayne
CUMBERLAND RESOURCES LP	CUMBERLAND MINE	4535	41285		Outbuilding	Structure Damage	Currently Monitoring	Greene	Wayne
CUMBERLAND RESOURCES LP	CUMBERLAND MINE	4536	41285	P1307	Spring	Water Loss	Implementing WS Replacement Plan	Greene	Wayne
CUMBERLAND RESOURCES LP	CUMBERLAND MINE	4596	41359		Dwelling	Structure Damage	Currently Monitoring	Greene	Wayne
CUMBERLAND MINE TOTAL CASES = 26									
CUMBERLAND RESOURCES LP TOTAL CASES = 26									
DANA MINING CO OF PA LLC	4 WEST MINE	3703	40186		Land	Land Damage	Performing Repairs	Greene	Dunkard
4 WEST MINE TOTAL CASES = 1									
DANA MINING CO OF PA LLC	PRIME NO 1 DEEP MINE	4543	41291	P1308	Pond	Water Loss	WS Replacement Plan Under Review	Greene	Perry
PRIME NO 1 DEEP MINE TOTAL CASES = 1									
DANA MINING CO OF PA LLC TOTAL CASES = 2									

UNRESOLVED DAMAGE AND WATER LOSS REPORTED TO DEP

April 4, 2013

Company Name	Permit Name	Problem ID	Date Received	Claim No.	Feature Type	Type of Investigation	Interim Resolution	County	Municipality
EIGHTY FOUR MINING CO	MINE 84	2317	38607	P0522	Well	Water Loss	WS Replacement Plan Under Review	Washington	Amwell
EIGHTY FOUR MINING CO	MINE 84	2348	38639	P0525	Well	Water Loss	WS Replacement Plan Under Review	Washington	Amwell
EIGHTY FOUR MINING CO	MINE 84	2422	38688	WL0588	Well	Water Loss	O&M Review	Washington	Somerset
EIGHTY FOUR MINING CO	MINE 84	2515	38804		Septic Tank	Structure Damage	Temporary Repair	Washington	Amwell
EIGHTY FOUR MINING CO	MINE 84	2513	38819		Well	Water Loss	Temp Water/Will Be Undermined	Washington	Amwell
EIGHTY FOUR MINING CO	MINE 84	2514	38819		Well	Water Loss	Temp Water/Will Be Undermined	Washington	Amwell
EIGHTY FOUR MINING CO	MINE 84	2811	39153	P1219	Well	Water Loss	O&M Review	Washington	Amwell
EIGHTY FOUR MINING CO	MINE 84	3019	39395	WL0758	Well	Water Loss	O&M Review	Washington	North Bethlehem
EIGHTY FOUR MINING CO	MINE 84	3199	39597		Septic Tank	Structure Damage	Currently Monitoring	Washington	Amwell
EIGHTY FOUR MINING CO	MINE 84	3224	39612	P0848	Spring	Water Loss	WS Replacement Plan Under Review	Washington	Amwell
EIGHTY FOUR MINING CO	MINE 84	3303	39724		Land	Land Damage	Unresolved	Washington	Amwell
EIGHTY FOUR MINING CO	MINE 84	3476	39912	P0927	Well	Water Loss	WS Replacement Plan Under Review	Washington	Amwell
EIGHTY FOUR MINING CO	MINE 84	3540	40008	WL1021	Well	Water Loss	Implementing WS Replacement Plan	Washington	Amwell
EIGHTY FOUR MINING CO	MINE 84	3598	40073		Septic Tank	Structure Damage	Performing Repairs	Washington	South Strabane
EIGHTY FOUR MINING CO	MINE 84	4372	41108	P1239	Well	Water Loss	Implementing WS Replacement Plan	Washington	Amwell
EIGHTY FOUR MINING CO	MINE 84	4408	41156	P1243	Well	Water Loss	Implementing WS Replacement Plan	Washington	South Strabane
MINE 84 TOTAL CASES = 16									
EIGHTY FOUR MINING CO TOTAL CASES = 16									
ELK LICK ENERGY INC	ROYTOWN	4383	41130	P1241	Well	Water Contamination	Rebuttal Review	Somerset	Lincoln
ELK LICK ENERGY INC	ROYTOWN	4391	41137	WL1232	Well	Water Loss	Unresolved/Pending Investigation	Somerset	Lincoln
ROYTOWN TOTAL CASES = 2									
ELK LICK ENERGY INC TOTAL CASES = 2									
EMERALD COAL RESOURCES LP	EMERALD DEEP MINE	4237	39874	SA1850	Land	Land Damage	Performing Repairs	Greene	Franklin
EMERALD COAL RESOURCES LP	EMERALD DEEP MINE	3752	40221		Land	Land Damage	Currently Monitoring	Greene	Jefferson
EMERALD COAL RESOURCES LP	EMERALD DEEP MINE	3912	40463	WL1057	Spring	Water Loss	Implementing WS Replacement Plan	Greene	Whiteley
EMERALD COAL RESOURCES LP	EMERALD DEEP MINE	4150	40829		Land	Land Damage	Currently Monitoring	Greene	Whiteley
EMERALD COAL RESOURCES LP	EMERALD DEEP MINE	4171	40861		Land	Land Damage	Currently Monitoring	Greene	Jefferson
EMERALD COAL RESOURCES LP	EMERALD DEEP MINE	4181	40861		Dwelling	Structure Damage	Currently Monitoring	Greene	Jefferson
EMERALD COAL RESOURCES LP	EMERALD DEEP MINE	4178	40884		Land	Land Damage	Currently Monitoring	Greene	Franklin
EMERALD COAL RESOURCES LP	EMERALD DEEP MINE	4242	40989	P1210-1	Spring	Water Loss	Implementing WS Replacement Plan	Greene	Franklin
EMERALD COAL RESOURCES LP	EMERALD DEEP MINE	4269	40989	P1210-2	Spring	Water Loss	Implementing WS Replacement Plan	Greene	Franklin
EMERALD COAL RESOURCES LP	EMERALD DEEP MINE	4270	40989	P1210-2	Spring	Water Loss	WS Replacement Plan Under Review	Greene	Franklin
EMERALD COAL RESOURCES LP	EMERALD DEEP MINE	4271	40989	P1210-2	Spring	Water Loss	WS Replacement Plan Under Review	Greene	Franklin
EMERALD COAL RESOURCES LP	EMERALD DEEP MINE	4336	41099	SA1863	Tower	Structure Damage	DEP Supported Claim	Greene	Jefferson
EMERALD COAL RESOURCES LP	EMERALD DEEP MINE	4352	41108	WL1220	Stream	Water Loss	Unresolved/Pending Investigation	Greene	Franklin
EMERALD COAL RESOURCES LP	EMERALD DEEP MINE	4371	41120	WL1223	Well	Water Loss	Currently Monitoring	Greene	Jefferson
EMERALD COAL RESOURCES LP	EMERALD DEEP MINE	4385	41131	P1238	Well	Water Loss	Implementing WS Replacement Plan	Greene	Franklin
EMERALD COAL RESOURCES LP	EMERALD DEEP MINE	4434	41179	P1254	Well	Water Loss	Implementing WS Replacement Plan	Greene	Franklin
EMERALD COAL RESOURCES LP	EMERALD DEEP MINE	4439	41183	P1255	Well	Water Loss	Implementing WS Replacement Plan	Greene	Franklin
EMERALD COAL RESOURCES LP	EMERALD DEEP MINE	4457	41205	SA1889	Dwelling	Structure Damage	Unresolved/Pending Investigation	Greene	Franklin
EMERALD COAL RESOURCES LP	EMERALD DEEP MINE	4464	41207	WL1242	Well	Water Loss	Unresolved/Pending Investigation	Greene	Cumberland
EMERALD COAL RESOURCES LP	EMERALD DEEP MINE	4556	41313	P1119	Land	Land Damage	Damage Claim Form Sent to Owner	Greene	Whiteley
EMERALD DEEP MINE TOTAL CASES = 20									
EMERALD COAL RESOURCES LP TOTAL CASES = 20									
INDIANA INVESTMENTS INC	URLING 1/3 DEEP MINE	4349	41093	P1233	Well	Water Loss	Implementing WS Replacement Plan	Indiana	Armstrong
URLING 1/3 DEEP MINE TOTAL CASES = 1									
INDIANA INVESTMENTS INC TOTAL CASES = 1									
MAPLE CREEK MINING INC	MAPLE CREEK MINE	2913	39307	SA1686	Dwelling	Structure Damage	In Litigation	Washington	Carroll
MAPLE CREEK MINING INC	MAPLE CREEK MINE	2931	39322	SA1690	Garage	Structure Damage	In Litigation	Washington	Carroll

UNRESOLVED DAMAGE AND WATER LOSS REPORTED TO DEP

April 4, 2013

Company Name	Permit Name	Problem ID	Date Received	Claim No.	Feature Type	Type of Investigation	Interim Resolution	County	Municipality
MAPLE CREEK MINING INC	MAPLE CREEK MINE	4238	40448	SA1818	Dwelling	Structure Damage	Awaiting Additional Effects	Washington	Carroll
MAPLE CREEK MINING INC	MAPLE CREEK MINE	4252	40994		Dwelling	Structure Damage	Currently Monitoring	Washington	Carroll
MAPLE CREEK MINING INC	MAPLE CREEK MINE	4405	41157	P1251	Well	Water Loss	Implementing WS Replacement Plan	Washington	Carroll
MAPLE CREEK MINING INC	MAPLE CREEK MINE	4406	41157		Land	Land Damage	Currently Monitoring	Washington	Carroll
MAPLE CREEK MINING INC	MAPLE CREEK MINE	4407	41157		Dwelling	Structure Damage	Currently Monitoring	Washington	Carroll
MAPLE CREEK MINING INC	MAPLE CREEK MINE	4414	41165		Land	Land Damage	Currently Monitoring	Washington	Carroll
MAPLE CREEK MINING INC	MAPLE CREEK MINE	4415	41165		Dwelling	Structure Damage	Currently Monitoring	Washington	Carroll
MAPLE CREEK MINING INC	MAPLE CREEK MINE	4416	41165	P1253	Well	Water Loss	Implementing WS Replacement Plan	Washington	Carroll
MAPLE CREEK MINING INC	MAPLE CREEK MINE	4417	41165		Building	Structure Damage	Currently Monitoring	Washington	Carroll
MAPLE CREEK MINING INC	MAPLE CREEK MINE	4418	41165		Land	Land Damage	Unresolved/Pending Investigation	Washington	Carroll
MAPLE CREEK MINING INC	MAPLE CREEK MINE	4419	41165		Dwelling	Structure Damage	Currently Monitoring	Washington	Carroll
MAPLE CREEK MINING INC	MAPLE CREEK MINE	4420	41165	P1252	Well	Water Loss	Implementing WS Replacement Plan	Washington	Carroll
MAPLE CREEK MINE TOTAL CASES = 14									
MAPLE CREEK MINING INC TOTAL CASES = 14									
MCVILLE MINING CO	CLEMENTINE MINE # 1	3130	39524	P0843	Well	Water Loss	In Litigation	Armstrong	South Buffalo
MCVILLE MINING CO	CLEMENTINE MINE # 1	3134	39524	P0842	Well	Water Loss	In Litigation	Armstrong	South Buffalo
MCVILLE MINING CO	CLEMENTINE MINE # 1	4296	41058	WL1210	Well	Water Loss	Unresolved/Pending Investigation	Armstrong	South Buffalo
MCVILLE MINING CO	CLEMENTINE MINE # 1	4362	41117	WL1222	Well	Water Contamination	Unresolved/Pending Investigation	Armstrong	South Buffalo
MCVILLE MINING CO	CLEMENTINE MINE # 1	4411	41152	P1249	Pond	Water Loss	WS Replacement Plan Under Review	Armstrong	South Buffalo
MCVILLE MINING CO	CLEMENTINE MINE # 1	4487	41221		Dwelling	Structure Damage	Currently Monitoring	Armstrong	South Buffalo
MCVILLE MINING CO	CLEMENTINE MINE # 1	4542	41290		Dwelling	Structure Damage	Currently Monitoring	Armstrong	South Buffalo
MCVILLE MINING CO	CLEMENTINE MINE # 1	4572	41325	WL1307	Well	Water Contamination	Unresolved/Pending Investigation	Armstrong	South Buffalo
MCVILLE MINING CO	CLEMENTINE MINE # 1	4574	41331	WL1309	Well	Water Contamination	Unresolved/Pending Investigation	Armstrong	North Buffalo
MCVILLE MINING CO	CLEMENTINE MINE # 1	4582	41340		Driveway	Land Damage	Temporary Repair	Armstrong	South Buffalo
CLEMENTINE MINE # 1 TOTAL CASES = 10									
MCVILLE MINING CO TOTAL CASES = 10									
QUECREEK MINING INC	QUECREEK NO 1	3256	39664	P1202	Well	Water Loss	Implementing WS Replacement Plan	Somerset	Lincoln
QUECREEK MINING INC	QUECREEK NO 1	4576	41339		Well	Water Loss	Awaiting Additional Info from Operator	Somerset	Lincoln
QUECREEK NO 1 TOTAL CASES = 2									
QUECREEK MINING INC TOTAL CASES = 2									
ROSEBUD MINING CO	BEAVER VALLEY MINE	4386	41131	WL1228	Well	Water Loss	Unresolved/Pending Investigation	Beaver	Greene
ROSEBUD MINING CO	BEAVER VALLEY MINE	4387	41131	WL1228	Well	Water Loss	Unresolved/Pending Investigation	Beaver	Greene
ROSEBUD MINING CO	BEAVER VALLEY MINE	4585	41346		Well	Water Loss	Temporary Water	Beaver	Greene
BEAVER VALLEY MINE TOTAL CASES = 3									
ROSEBUD MINING CO	CHERRY TREE MINE	4323	41079	P1230-1	Well	Water Contamination	Implementing WS Replacement Plan	Indiana	Montgomery
ROSEBUD MINING CO	CHERRY TREE MINE	4379	41124	WL1226	Well	Water Contamination	Unresolved/Pending Investigation	Indiana	Montgomery
CHERRY TREE MINE TOTAL CASES = 2									
ROSEBUD MINING CO	DARMAC 2 MINE	4462	41207	P1258	Well	Water Loss	Rebuttal Review	Indiana	Armstrong
DARMAC 2 MINE TOTAL CASES = 1									
ROSEBUD MINING CO	DUTCH RUN MINE	4230	40975	WL1206	Well	Water Loss	O&M Review	Indiana	Washington
DUTCH RUN MINE TOTAL CASES = 1									
ROSEBUD MINING CO	HEILWOOD MINE	4382	41129		Dwelling	Structure Damage	Currently Monitoring	Indiana	Pine
HEILWOOD MINE TOTAL CASES = 1									
ROSEBUD MINING CO	LOGANSPORT MINE	4185	40890	P1204	Well	Water Loss	WS Replacement Plan Under Review	Armstrong	Bethel
ROSEBUD MINING CO	LOGANSPORT MINE	4341	41089	WL1216	Well	Water Loss	Unresolved/Pending Investigation	Armstrong	Bethel
ROSEBUD MINING CO	LOGANSPORT MINE	4377	41123	P1236	Well	Water Loss	Implementing WS Replacement Plan	Armstrong	Bethel
ROSEBUD MINING CO	LOGANSPORT MINE	4447	41197	WL1240	Well	Water Loss	Unresolved/Pending Investigation	Armstrong	Bethel
ROSEBUD MINING CO	LOGANSPORT MINE	4552	41304	WL1306	Well	Water Contamination	Unresolved/Pending Investigation	Armstrong	Bethel
LOGANSPORT MINE TOTAL CASES = 5									

UNRESOLVED DAMAGE AND WATER LOSS REPORTED TO DEP

April 4, 2013

Company Name	Permit Name	Problem ID	Date Received	Claim No.	Feature Type	Type of Investigation	Interim Resolution	County	Municipality
ROSEBUD MINING CO	MINE 78	4430	41173	WL1237	Well	Water Loss	Unresolved/Pending Investigation	Cambria	Adams
MINE 78 TOTAL CASES = 1									
ROSEBUD MINING CO	ROSSMOYNE NO 1	3629	40095	WL1308	Well	Water Loss	O&M Review	Indiana	South Mahoning
ROSEBUD MINING CO	ROSSMOYNE NO 1	4114	40760	WL1134	Well	Water Loss	WS Replacement Plan Under Review	Indiana	South Mahoning
ROSEBUD MINING CO	ROSSMOYNE NO 1	4115	40760	P1130	Well	Water Loss	WS Replacement Plan Under Review	Indiana	South Mahoning
ROSEBUD MINING CO	ROSSMOYNE NO 1	4378	41123	WL1225	Well	Water Contamination	Unresolved/Pending Investigation	Indiana	South Mahoning
ROSSMOYNE NO 1 TOTAL CASES = 4									
ROSEBUD MINING CO	TJS NO 6	3979	40570	WL1106	Well	Water Loss	Unresolved/Pending Investigation	Armstrong	Plumcreek
ROSEBUD MINING CO	TJS NO 6	4522	41256	P1301	Well	Water Loss	Implementing WS Replacement Plan	Armstrong	Plumcreek
TJS NO 6 TOTAL CASES = 2									
ROSEBUD MINING CO	TRACY LYNNE MINE	4259	41004	P1218	Well	Water Contamination	Implementing WS Replacement Plan	Armstrong	Kiskiminetas
ROSEBUD MINING CO	TRACY LYNNE MINE	4266	41018	SA1862	Dwelling	Structure Damage	DEP Supported Claim	Armstrong	Kiskiminetas
ROSEBUD MINING CO	TRACY LYNNE MINE	4319	41075	WL1214	Well	Water Contamination	Unresolved/Pending Investigation	Armstrong	Kiskiminetas
ROSEBUD MINING CO	TRACY LYNNE MINE	4350	41099	P1232	Well	Water Contamination	Implementing WS Replacement Plan	Armstrong	Kiskiminetas
ROSEBUD MINING CO	TRACY LYNNE MINE	4412	41163	WL1236	Well	Water Contamination	Rebuttal Review	Armstrong	Kiskiminetas
ROSEBUD MINING CO	TRACY LYNNE MINE	4432	41179	P1250	Well	Water Loss	Implementing WS Replacement Plan	Armstrong	Kiskiminetas
ROSEBUD MINING CO	TRACY LYNNE MINE	4503	41240	P1304	Well	Water Loss	WS Replacement Plan Under Review	Armstrong	Kiskiminetas
TRACY LYNNE MINE TOTAL CASES = 7									
ROSEBUD MINING CO TOTAL CASES = 27									
ROX COAL INC	AGUSTUS MINE	4397	41149	WL1234	Well	Water Contamination	Unresolved/Pending Investigation	Somerset	Shade
AGUSTUS MINE TOTAL CASES = 1									
ROX COAL INC	BARBARA NO 1 & NO 2 MINES	4584	41341		Well	Water Loss	Temporary Water	Somerset	Brothersvalley
ROX COAL INC	BARBARA NO 1 & NO 2 MINES	4588	41352		Well	Water Loss	Temporary Water	Somerset	Brothersvalley
ROX COAL INC	BARBARA NO 1 & NO 2 MINES	4589	41352		Well	Water Loss	Temporary Water	Somerset	Brothersvalley
BARBARA NO 1 & NO 2 MINES TOTAL CASES = 3									
ROX COAL INC	KIMBERLY RUN MINE	3948	40494	P1058	Well	Water Loss	Implementing WS Replacement Plan	Somerset	Somerset
ROX COAL INC	KIMBERLY RUN MINE	4019	40626		Well	Water Contamination	Temporary Water	Somerset	Somerset
ROX COAL INC	KIMBERLY RUN MINE	4227	40968	WL1205	Well	Water Contamination	Unresolved/Pending Investigation	Somerset	Somerset
ROX COAL INC	KIMBERLY RUN MINE	4298	41058	P1225	Well	Water Loss	Implementing WS Replacement Plan	Somerset	Somerset
ROX COAL INC	KIMBERLY RUN MINE	4344	41099	WL1219	Well	Water Loss	Implementing WS Replacement Plan	Somerset	Somerset
ROX COAL INC	KIMBERLY RUN MINE	4489	41221	P1261	Well	Water Loss	WS Replacement Plan Under Review	Somerset	Somerset
ROX COAL INC	KIMBERLY RUN MINE	4521	41257	WL1248	Well	Water Contamination	Unresolved/Pending Investigation	Somerset	Somerset
ROX COAL INC	KIMBERLY RUN MINE	4533	41284	P1309	Well	Water Contamination	WS Replacement Plan Under Review	Somerset	Somerset
ROX COAL INC	KIMBERLY RUN MINE	4546	41292	WL1303	Well	Water Contamination	Unresolved/Pending Investigation	Somerset	Somerset
ROX COAL INC	KIMBERLY RUN MINE	4555	41312	P1310	Well	Water Contamination	WS Replacement Plan Under Review	Somerset	Somerset
ROX COAL INC	KIMBERLY RUN MINE	4583	41341		Well	Water Contamination	Temporary Water	Somerset	Somerset
KIMBERLY RUN MINE TOTAL CASES = 11									
ROX COAL INC TOTAL CASES = 15									
TANOMA COAL CO INC	TANOMA DEEP MINE	3190	39587	WL0821	Well	Water Loss	Implementing WS Replacement Plan	Indiana	Rayne
TANOMA DEEP MINE TOTAL CASES = 1									
TANOMA COAL CO INC TOTAL CASES = 1									
WESTERN ALLEGHENY ENERGY LLC	KNOB CREEK MINE	4249	40989	WL1207	Well	Water Loss	Unresolved/Pending Investigation	Indiana	Young
WESTERN ALLEGHENY ENERGY LLC	KNOB CREEK MINE	4590	41354		Well	Water Contamination	Temp Water Offered/Homeowner Declined	Indiana	Young
KNOB CREEK MINE TOTAL CASES = 2									
WESTERN ALLEGHENY ENERGY LLC TOTAL CASES = 2									