

# NHCS 2015 Highwall Failure

2015 Satellite Image Projected on 2023 Google Earth Image and Showing Locations of Test Pits, Prior Location of Primrose Creek, 2023 Found Culvert and Proposed Creek Restoration Path

Appendix 1, Exhibit 1, Plate 6

## Legend

- Approx. Path of Creek Restoration
- Downstream Primrose Creek
- Found (2023) Culvert Location
- Highwall Failure Area
- Prior Path Primrose Creek

