

PENNSYLVANIA

P.O. Box 468 Pipersville, PA 18947 215.766.1211

WEST VIRGINIA

P.O. Box 794 Morgantown, WV 26505 304.212.6866

800.264.4553

February 6, 2017

Mr. Gary Latsha Inspector Supervisor PA Department of Environmental Protection Pottsville District Mining Operations 5 West Laurel Boulevard Pottsville, PA 17901

SUBJECT: New Hope Crushed Stone Quarry

January 2016 CAP Monthly Report Compliance Order No. 16-5-032-N Noncoal Permit No. 7974SM3 Solebury Township, Bucks County EarthRes Project No. 011012.015

Dear Mr. Latsha:

On behalf of New Hope Crushed Stone & Lime Company (NHCS), EarthRes Group, Inc. (EarthRes) is providing the monthly Corrective Action Plan (CAP) update in response to Compliance Order No. 16-5-032-N issued by the Department and dated August 26, 2016. This letter and attached table details activities completed by NHCS during the month of January 2017.

There were 21 working days in January and NHCS completed reclamation / restoration activities in accordance with the manpower requirements detailed in the Department's January 29, 2016 letter. Reclamation was completed over 16 work days; stream reclamation was not completed due to weather conditions. Rain and snow was observed on approximately 20 days throughout the month, with significant precipitation occurring on January 2nd (0.32 in.), 3rd (0.42 in.), 11th (0.63 in.), 17th (0.38 in), 20th (0.21 in.), 23rd (0.97 in.) and the 24th (0.34 in.).

NHCS worked on most rain days moving reclamation fill to the east and north walls. Work was able to continue due to the short haul distance and stable ground conditions, which are much better in the eastern quarry area (i.e. stone on the ground and shallow bedrock). Due to wet conditions and safety considerations, fill placement over the wall was minimally completed. Additionally, the access road through the south pit and to the western wall is now inaccessible

due to pit flooding. Accordingly, effort was required to create a ramp on the east wall to regain access to the north and west walls. These conditions are shown on the attached photographs. The details of the work completed in January are provided in the attached table.

Conclusion

NHCS completed significant work in January, but efforts were reduced due to precipitation due to winter weather conditions. NHCS is hopeful that upon resuming work in favorable weather conditions that make up reclamation volumes can be completed by the end of the 2nd quarter of 2016.

Work efforts on stream restoration and/or reclamation will continue in the coming months as scheduled, noting potential limitations due to weather, safety and other factors as indicated in the September 23, 2016 CAP and November 4, 2016 CAP update filed with the Department.

If you have any questions or need any additional information, please contact me at (215) 766-1211.

Sincerely,

EarthRes Group, Inc.

Louis F. Vittorio, Jr., P.G.

Vice President

Enclosure: January Reclamation and Restoration Efforts

Site Photographs

cc: Ms. Christina Cursley, NHCS



January 2017 Reclamation and Restoration Work

Days Worked:			Hours Worked:
Days working on Reclamation	16		Working days per month: 16
Days working in Stream			Number of employees 4
Inclement Weather	1		Hours allotted per day 7
Loader For Repairs	1		
Ramp on East Wall	<u>3</u>		
Total Working Days January	21		Hours to be worked for
			reclamation days 448
Dirt Moved:			
	Yards	Tons	
Days working on Reclamation	16		
Cubic Yards per hour	200	300	Actual hours worked on Rec 434
Hours allotted per day	7	7	
Required Yards/Tons to be moved	22,400	33,600	
Actual Dirt moved by trucks	24,007	36,011	
Reclamation Berm	-		
Total moved	24,007	36,011	
Make-Up Reclamation Completed	1,607	2,411	
Make-op Recialitation Completed	1,007	2,411	
Truck loads moved		588	
			0
Cumulative Stream Days			
	Hours	Days	
Miscellaneous Repairs	-	-	
Actual Stream Work	-	-	





