

PA Underground Coal Mine Fires (Rev. July 2025)								
MAP NO.	FIRE NAME	COUNTY	PA ID	MONITORING ACTIVITY	YEAR	RECLAMATION ACTIVITY	YEAR	FIRE STATUS
1	Becks Run Road	Allegheny	0031-02	PI, TM	2020	Surface seal	1998	DOR
2	Fairhaven Park	Allegheny	0369-01	PI	2025	Flushing	1969	DOR
3	Large	Allegheny	2602-01	PI	2019	Adjacent construction revealed no fire	2000	DOR
4	Matchette Road Fire	Allegheny	0644-06	PI, TM	2025	Backfill subsidence area(s)	2024	CB
5	Moon Run	Allegheny	1723-01	PI	2025	Surface seal	1998	DOR
6	Renton	Allegheny	1710-01	PI, TM	2023	Partial excavation	2020	CB
7	Wall, Signal Hill	Allegheny	4380-04	PI	2017	Surface seal	2007	CB
8	Jeanesville	Carbon	2116-11	PI, TM	2019	Reclamation complete	2019	OUT
9	Summit Hill Borough (Lansford East)	Carbon	4652-27	PI, TM	2025	None, suspended by property owner	2018	CB
10	Snow Shoe	Centre	6797-03	PI	2024	Surface seal	1994	DOR
11	Centralia	Columbia	2000-01 4036-12	PI, TM, GM, TIR	2025	Razed structure	2025	CB
12	Clayford North, Golf Course	Fayette	2798-05	PI	2020	Surface seal	1990	DOR
13	East Francis Ave	Fayette	2746-01	PI, TM	2025	Exploratory drilling and flushing	1989	DOR
14	Fairchance	Fayette	0460-07	PI	2025	Reclamation complete	2025	OUT
15	Newcomer	Fayette	2733-13	PI	2010	Surface seal	1984	CB
16	Newell	Fayette	2790-02	PI	2009	Isolation trench, backfilled	1960	DOR
17	Percy	Fayette	2718-01	PI	2018	Grouting	2007	DOR
18	Phillips North	Fayette	7605-23	PI, TM	2022	Reclamation complete	2022	OUT
19	Plummer-Puritan	Fayette	2749-01	PI, TM, TIR	2023	Subsidence reclamation	2023	CB
20	Pittstown (Glowacki)	Fayette	0149-01	PI, TM	2024	Grouting	2022	CB
21	Rocks Works (Bowood No. 1)	Fayette	4689-09	PI	2014	Reclamation complete	2014	OUT
22	Dolph	Lackawanna	2080-17	PI, TM, GM, TIR	2019	Reclamation complete	2024	OUT
23	Powderly Creek	Lackawanna	1520-16	PI, TM	2023	Reclamation complete	2018	OUT
24	Summit Gardens	Lackawanna	0402-01	PI, TM	2023	Adjacent reclamation revealed no fire	2009	DOR
25	Ballfield East	Luzerne	2155-12	PI, TIR	2025	Backfill subsidence area(s)	2020	CB
26	Hanover Reservoir	Luzerne	1556-26	PI, TM, GM, TIR	2024	Reclamation Design	2025	CB
27	Laurel Run (East Georgetown)	Luzerne	3709-04	PI, TM, TIR	2025	None	2025	DOR
28	Laurel Run (Audenreid)	Luzerne	0540-01	PI, TM, TIR	2025	Property owner maintaining area	2020	CB
29	Laurel Run (Sturdevant - Metcalf)	Luzerne	0541-01	PI, TM, TIR	2025	Exploratory drilling and grouting	2019	CB
30	Laurel Run (Mordecai)	Luzerne	0542-01	PI, TM, TIR	2025	Subsidence reclamation	2016	CB
31	Warrior Gap	Luzerne	2128-02	PI	2017	Exploratory drilling	1993	DOR
32	North Franklin (Trevorton Southwest)	Northumberland	2062-16	PI, TM	2025	None	2025	CB
33	Bear Valley Southwest	Northumberland	3233-09	PI, TM	2025	None	2025	CB
34	Glen Burn (Cameron)	Northumberland	2068-02	PI, TM, TIR	2025	Tunnel plugs (2)	1989	CB
35	Glen Burn (Hickory Swamp)	Northumberland	2060-10	PI, TM, TIR	2025	Firebreak installed	2013	CB
36	Glen Burn (Luke Fidler)	Northumberland	2061-02	PI, TM, TIR	2025	Tunnel plug (1)	1989	CB
37	Locust Summit	Northumberland	3602-09	PI, TM	2017	None, suspended by property owner	2017	CB
38	Locust Summit West	Northumberland	3610-09	PI	2025	None	2025	CB
39	Forestville North	Schuylkill	0422-01	PI, TIR	2018	Exploratory drilling	1980	DOR
40	Raven Run (Girardville North II)	Schuylkill	4039-09	PI, TM, TIR	2025	None	2025	CB
41	South Shenandoah	Schuylkill	1009-04	PI, TM	2025	Exploratory drilling	1993	DOR
42	Joffre North	Washington	0654-01	PI	2010	Active strip mine	2010	DOR
43	Maiolie Road	Westmoreland	0907-14	PI	2018	Reclamation complete	2005	OUT
44	Shaner	Westmoreland	0217-01	PI, TM	2010	Isolation trench, backfilled	1995	DOR

MONITORING ACTIVITY NOTES:

Aerial Thermal Infrared Imagery = TIR
Gas Monitoring = GM
Periodic Visual Site Investigation = PI
Temperature Monitoring = TM

FIRE STATUS NOTES:

Confirmed Burning (CB) = Visual fire, elevated borehole and/or surface temperatures, distressed vegetation, venting smoke or steam observed
Presumed Burning (PB) = No visual fire, elevated borehole and/or surface temperatures, no distressed vegetation, no venting smoke or steam observed at the time of visitation
Dormant (DOR) = No visual fire, no elevated borehole and/or surface temperatures, no distressed vegetation, no venting smoke or steam observed for more than five years
OUT = The known underground mine fire was excavated, extinguished, backfilled and the surface reclaimed