

BUREAU OF ABANDONED MINE RECLAMATION
WILKES-BARRE DISTRICT

DRILLERS REPORT

PROJECT NO. OSM 40(511-83)101.1 Pittston II-Phase I

LOCATION City of Pittston and Borough of Hughestown

STREET Center

DESCRIPTION House # 64

BOREHOLE NO. 79M DRILLED ^{S. P. 12-19-84} 12-19-84 19

DRILLED BY Van Fleet Drilling SURFACE ELEVATION Approx 636

OK For G.E. Ray Const (N3400, E 6820)

STRATA	PIPE DIA.		PIPE INSTALLED		DRILLED		TOTAL		VEIN ELEVATION	NAME OF VEIN
	IN.	FT.	IN.	FT.	IN.	FT.	IN.			
Wash				19	-	19	-			
Rock	8	23		4	-	23	-			
Rock				37	-	60	-			
Broken				3	-	63	-			
Open				5	-	68	-			Pittston
Broken				8	-	76	-	560		
Rock	6"	115	-	49	-	125	-			
Open				8	-	133	-			Marcy
Broken				3	-	136	-	500		
Broken				2	-	138	-			

REMARKS 8" Drilling @ 23' 6" Drilling @ 115'
8" casing @ 23' 6" casing @ 115'

MACHINE NO. I-R T1 DRILLER Van Fleet, Peter J. 10

BIT NO. _____ DEPT. REPRESENTATIVE H. B. M... 10

TYPE & SIZE OF BIT _____

DRILLERS REPORT

PROJECT NO. OSM 40(511-83) 1011
 LOCATION Pittston
 STREET 105 Ft along Pitt Alley from Upper Div. St
 DESCRIPTION rear house No 51 Washington Terrace
 BOREHOLE NO. 83 M DRILLED 3/15 19 3/19
 DRILLED BY Van Fleet Drilling SURFACE ELEVATION Approx 705
 (N3548, E8305)

OK

STRATA	PIPE INSTALLED		DRILLED		TOTAL		VEIN ELEVATION	NAME OF VEIN
	PIPE DIA. IN.	FT.	IN.	FT.	IN.	FT.		
Wash				26		26		
Rock				4		30		
Rock				36		66		
Tot Broken				3		69		
Rock				7		76		
Tot Broken				10		86		Checker
Rock				57		143		
Flush				7		150		Pittston
Rock				48		198		
Open				1		199		
Broken				8		207		Marcy
Rock				2		209		

REMARKS Core Run 3/15/85 8" Drilling 30 6" Drill 17
8" CASING 50 6" CASF 188

MACHINE NO. _____ DRILLER Pete Van Fleet
 BIT NO. _____
 TYPE & SIZE OF BIT _____

P. O. BOX 9335
SOUTH CHARLESTON, WEST VIRGINIA

DRILLERS REPORT

PROJECT NO. OSM 40 (511-83) 10/6/
LOCATION Pittston
STREET Mill St
DESCRIPTION House #198
BOREHOLE NO. 92C DRILLED 4-3 19ES
DRILLED BY Van Fleet SURFACE ELEVATION Approx 645
ok (N2510, E7308)

STRATA	PIPE DIA.		PIPE INSTALLED		DRILLED		TOTAL		VEIN ELEVATION	NAME OF VEIN
	IN.	FT.	IN.	FT.	IN.	FT.	IN.	FT.		
<u>wash</u>				<u>12</u>		<u>12</u>	<u>12</u>	<u>12</u>		
<u>rock</u>				<u>25</u>		<u>37</u>				
<u>flush</u>				<u>8</u>		<u>45</u>			<u>600</u>	<u>Checker</u>

REMARKS 8" drilling 45'
NO casing installed
MACHINE NO. _____ DRILLER Van Fleet Robert
BIT NO. _____ Ed. Byelle

DRILLERS REPORT

PROJECT NO. OSM 40(511-93) 101.1

LOCATION Pittston

STREET # 140 Mill St.

DESCRIPTION _____

BOREHOLE NO. 93C DRILLED 5/13/85 19

DRILLED BY VAW Fleet SURFACE ELEVATION Approx 641
OK (N 2920, E 6855)

STRATA	PIPE INSTALLED		DRILLED		TOTAL		VEIN ELEVATION	NAME OF VEIN
	PIPE DIA. IN.	FT.	IN.	FT.	IN.	FT.		
WASH					25		25	
Rock					1		26	
Flush					16		42	CHECKER

REMARKS 42' - 8" Drilling Only

MACHINE NO. _____ DRILLER Robert G. Fleet

BIT NO. 98" DEPT. REPRESENTATIVE 1611

DRILLERS REPORT

PROJECT NO. OSM40 (511-83) 101.1

LOCATION Histon

STREET MILL ST # 132

DESCRIPTION _____

BOREHOLE NO. 94C DRILLED 5/13/85 19

DRILLED BY Vawter SURFACE ELEVATION Approx 641
 (N2995, E 6770)

STRATA	PIPE INSTALLED		DRILLED		TOTAL		VEIN ELEVATION	NAME OF VEIN
	PIPE DIA. IN.	FT.	IN.	FT.	IN.	FT.		
WASH				21		21		
Rock				8		29	CHECKER	
COAL				11		40		

REMARKS (40') - 8" Drilling only

MACHINE NO. _____ DRILLER John Vawter

BIT NO. 94

TYPE & SIZE OF BIT _____ BEST REPRESENTATIVE 01 - H

DRILLERS REPORT

PROJECT NO. OSM 40 (511-83) 101.1
LOCATION Histon
STREET Mill St # 95
DESCRIPTION _____
BOREHOLE NO. 95C DRILLED 5/13/85 19__
DRILLED BY Vaw Hest SURFACE ELEVATION Approx 642
(N 3220, E 6515)

STRATA	PIPE DIA.		PIPE INSTALLED		DRILLED		TOTAL		VEIN ELEVATION	NAME OF VEIN
	IN.	FT.	IN.	FT.	IN.	FT.	IN.			
WASH				4		4				
Rock				22		26				
Coal				9		35			(CHENKER)	
Rock				2		37				

REMARKS (37') = 8" Drilling only

MACHINE NO. _____ DRILLER Robert L. Vawter
BIT NO. 9 7/8"

DRILLERS REPORT

PROJECT NO. 05M40(511-83)101.1
 LOCATION Pittston
 STREET Alley between Mill & Carroll St.
 DESCRIPTION Rear house #142/144 Carroll St.
 BOREHOLE NO. 97 C DRILLED June 13 1955
 DRILLED BY Van Fleet Drilling SURFACE ELEVATION APPROX. 650
 K 2411N 7145E

STRATA	PIPE DIA.		PIPE INSTALLED		DRILLED		TOTAL		VEIN ELEVATION	NAME OF VEIN
	IN.	FT.	IN.	FT.	IN.	FT.	IN.			
wash				28		28				
rock				17		45				
open				7		52			596	Checker
silt				2		54				
rock				2		56				
8" drilling				56'	✓					
8" casing				43'	✓					

REMARKS _____

MACHINE NO. _____ DRILLER Robert Van Fleet

BIT NO. _____

PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF ABANDONED MINE RECLAMATION
WILKES-BARRE DISTRICT

DRILLERS REPORT

PROJECT NO. OSM NO 511-83-1011

LOCATION ALLEY BETWEEN MILL & CARROLL ST.

STREET _____

DESCRIPTION _____

BOREHOLE NO. 980 DRILLED JUNE 13-14 19 85

DRILLED BY YAN FLEET SURFACE ELEVATION APPROX. 645

OK 2615N 6915E

STRATA	PIPE DIA.	PIPE INSTALLED		DRILLED		TOTAL		VEIN ELEVATION	NAME OF VEIN
	IN.	FT.	IN.	FT.	IN.	FT.	IN.		
SAND				20		20			
ROCK				26		46			
FLUSH				8		54		591	CHECKER
ROCK				2		56			

REMARKS 56' OF 8" DRILLING ✓
NO CASING ✓

MACHINE NO. _____ DRILLER _____

BIT NO. _____

TYPE & SIZE OF BIT 9 7/8" DEPT. REPRESENTATIVE Marty Williams

DRILLERS REPORT

PROJECT NO. OSM 40 (511-83) 101.1
 LOCATION Pittston
 STREET Carrill St
 DESCRIPTION House #174
 BOREHOLE NO. 99C DRILLED June 13 1955
 DRILLED BY Van Fleet Drilling SURFACE ELEVATION APPROX. 660
 OK 2615N 6915E

STRATA	PIPE DIA.		PIPE INSTALLED		DRILLED		TOTAL		VEIN ELEVATION	NAME OF VEIN
	IN.	FT.	IN.	FT.	IN.	FT.	IN.	FT.		
wash				41		41				
open				6		47				
flush				3		50			610	Checker
rock				2		52				
8" drilling				52' ✓						
E" casing				41' ✓						(Cased to 41' due to Area Collapsing during drilling)

REMARKS Installed casing to 41' due to sandy area & no rock present

MACHINE NO. _____ DRILLER Roger L. Van Fleet
 BIT NO. _____

