
## **SURFACE EROSION**



Cracking of Masonry Wall Due To Foundation Undermining by Surface Erosion

Modified after Techebotarioff