


PENN PILOT PHOTO 1937, Enlargement of HDD area (red line indicates proposed HDD location): Note areas on photo (surface depressions and variation in soil moisture) near proposed HDD that may indicate additional fracture trace not shown anywhere on most recent documents submitted by Sunoco Logistics.



Wells near proposed HDD that are not in PAGWIS (Penn Pilot photo 1937 enlargement)



Wells prior to PA GWIS ★
Proposed HDD —