

May 9, 2017

#### **NOTICE OF VIOLATION**

#### CERTIFIED MAIL NO. 7015 0640 0002 3145 0400

Mr. Mathew L. Gordon Sunoco Pipeline, L.P. 535 Fritztown Road Sinking Springs, PA 16908

Re: Violations of the Clean Stream Law

Pennsylvania Pipeline Project (a.k.a. Mariner East II)

Permit No. E23-524 Brookhaven Borough Delaware County

Dear Mr. Gordon:

On May 3, 2017, the Department of Environmental Protection (DEP) received notice of an inadvertent release of drilling solution near 5005 Chester Creek Road in Brookhaven Borough, Delaware County. On May 4, 2017, DEP conducted a follow-up inspection; a copy of the inspection report is enclosed. Drilling solution by definition is an industrial waste which was discharged to Chester Creek, a water of the Commonwealth (Warm Water Fisheries). The discharge of industrial waste to waters of the Commonwealth is a violation of Section 301 of the Clean Streams Law, 35 P.S. Section 691.301.

DEP acknowledges your timely response to the above-referenced violation. Moving forward, please be advised that upon the occurrence of any incidents resulting in discharges into "Waters of this Commonwealth," Sunoco shall:

- A. Immediately notify the pertinent DEP Regional Office 24-hour Emergency Response Line. For the Southeast Regional Office, the telephone number is 484.250.5900.
- B. Within 5 business days, submit a written response to this office (to the attention of Mr. John Hohenstein by e-mail at jhohenste@pa.gov), including the following information:
  - 1. A complete list of materials used in the drilling fluids utilized at this site and an estimation of the amount of drilling fluid released.

- 2. A description of immediate actions taken by Sunoco to contain and remove this discharge from waters of this Commonwealth.
- 3. A discussion of any revisions and/or updates to your Inadvertent Return (IR) Contingency Plan that can be implemented to prevent and respond to future discharges.
- 4. A detailed analysis/explanation of the root cause or causes of the unpermitted discharges.
- 5. A plan to monitor these areas to determine if there are secondary impacts to the aquatic ecosystem and hydrology.

Please be advised that DEP and/or the Delaware County Conservation District will conduct additional inspections of the site. If future inspections reveal that required corrective actions have not been made and/or additional violations have occurred, DEP may initiate enforcement action.

This Notice of Violation is neither an order nor any other final action of DEP. It neither imposes nor waives any enforcement action available to DEP under any of its statutes. If DEP determines that an enforcement action is appropriate, you will be notified of the action.

I look forward to your cooperation in this matter. If you have any questions, please call my office at the telephone number located in the first page footer.

Sincerely

Domenic Rocco, P.E. Regional Manager

Waterways and Wetlands

Enclosure(s): DEP Inspection Report

cc: Mr. Embry, Sunoco Pipeline

Mr. Prosceno, TetraTech

Ms. Wheeler, Delaware County Conservation District

PA Fish and Boat Commission, Southeast Office

Mr. Caplan - U.S. Army Corps of Engineers, Philadelphia District

Brookhaven Borough Re 30 (GJS17WAW)129 bcc: Mr. Hohenstein – DEP (via e-mail)

Mr. Knorr – DEP (via e-mail) Mr. Nassani – DEP (via e-mail)

Ms. Henning-Dudley – DEP (via e-mail) Mr. De Francesco – DEP (via e-mail) Mr. C. Smith – DEP (via e-mail)

Re 30 (GJS17WAW)129



# COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF WATERSHED MANAGEMENT

DEP Data Records	Inspection Record #
Complaint Record #	Enforcement Record #
Permit # E23-524	


#### WATER OBSTRUCTION AND ENCROACHMENT INSPECTION REPORT

DEP/CCD Office	23-524		hone 84-250-5160	176	Project Type	Inadvert	ent Return	·		
Address	2 East Main Street Location 5005 Chester Creek Road									
	Norristown, PA 19401			County Delaws	County Delaware					
Owner/Permittee	e Sunoco Logistics Partners, Phone L.P.			Municipality Brook	khaven To	wnship				
	535 Fritztown Road			*******	Water Course or I	Body of W	ater Chest	er Creek		
Mailing Address	Sinking Springs, PA 16	908			Latitude:	39°	51'	58.	.7" N	
		***************		Longitude: 75° 24' 23.5" W					_	
Type of Inspection:	□ ADMIN - Administrative / File Review       □ CONST - Construction Progress       □ OTHER         □ CEI - Compliance Evaluation       □ FUI - Follow-up Inspection         □ COMPL - Complaint Inspection       ☑ INCDT - Incident response									
			INSPECTIO	ON F	FINDINGS		250.000	St.	77.	
Fa	ilure to:	Violatio	n? (Check if yes)		Failu	re to:		Violatio	on? (Check	if yes)
Obtain a Chapter	105 permit	□ [10:	5.11] 693.6/18		erform work accord			1	5.44] 693.18	
Operate or mainta	ain permitted project	□ [10:	5.51] 693.13/18		mplement Erosion a Plan	ınd Sedir	nent Contro	1 105	5.46] 693.18	
Acknowledge peri	mit conditions	<b>[10</b> :	5.42] 693.18		Obtain Department a nvironmental Asse		for	[10t	5.15] 693.18	
Maintain a valid p	ermit	[10:	5.43] 693.18	0	Other:			☑ [Dis	charge under	CSL]
□ NOVIO (No violations r			□ outs1	Γ (Οι	utstanding violations	i)		RECUR (R	ecurring viola	itions)
Inspection Results Code:	☐ VIOIC (Violations no immediately correct		☑ VIOLS (Violation(s) note:	d)	VOV (New oviolations no		anding		ew and recur is noted)	ring
of water. For pe	nditions and violations rmitted work, confirm	compliar	ice or specify violation	ons.						
	t conducted an incide ine at stream crossing									
	t. This is a violation of									
	m the uplands and st									
	t. The in stream cont			vill b	e removed prior t	o comin	g rain Frid	ay. Attacl	ned is the m	ap,
initial email inclu	ent response and the	incident	report.					-	<u>.</u> _	
-		-	<del></del>			· · · · ·			_	
Sketch attached	i? ☐ Yes ⊠ No	Pho	tos taken? 🛚 Yes		☐ No Additio	onal inf	ormation	attached?	Yes Yes	□No
Inspector nan Christian M V	" '		Inspector Si	gna	ture: Christia	en M	l. Vlot	Date 5/4/17	and Time: 7	
Inspector was	accompanied by:		Signature of Owner		vner/Permittee:			Date: 5/4/17		
Other: En	☑ Other: Environmental Inspector Print Name: Joseph Proscenia									
The Owner/Perropportunity to dis	nittee's signature act	ctor. The	es that they have a e signature does not	read ned	the report and cessarily mean the	received at they a	d a copy a	and that the the report.	hey were gi	iven the
	☐ White – DE	Р			☐ Yellow	– Owne	r/Permitte	9		

Google Maps

### 39°51'58.7"N 75°24'23.5"W

Sunoco PPP Inadvertent Return 5-3-17



39.866309, -75.406539

## 39°51'58.7"N 75°24'23.5"W

From:

Vlot. Christian

To:

Knorr, Donald; Hohenstein, John; Rocco, Domenic

Cc: Subject: Bauer, Robert; Miller, Rex Re: Incident Report

Date:

Thursday, May 04, 2017 10:01:48 AM

**Attachments:** 


Image-1.png Image.png

I visited the site this morning. The return was is uplands but right next to an inlet to Chester creek. Everything is cleaned up pretty well and they have containment around return area. They estimated 500 gals fracked out.

They did say they have lost about 20,000 gals of of fluid over the past days so who knows where that went. Will see

They have contacted home owners to see if there basements are filled with fluid. The house closest to site is vacant.

Josh also said a formal report will be sent.





Outlet of STW inlet



Containment around return area.

Christian M. Vlot | Water Pollution Biologist II
Department of Environmental Protection | Waterways and Wetlands
2 East Main Street | Norristown, PA 19401

2 East Main Street | Norristown, PA 19401 Phone: 484.250.5153 | Fax: 484.250.5971

www.depweb.state.pa.us

From: Knorr, Donald

**Sent:** Thursday, May 4, 2017 8:52:34 AM **To:** Rocco, Domenic; Hohenstein, John **Cc:** Bauer, Robert; Miller, Rex; Vlot, Christian

Subject: FW: Incident Report

**Donald F. Knorr, PWS** | Water Pollution Biologist 3 Department of Environmental Protection | Waterways and Wetlands 2 East Main Street | Norristown, PA 19401

Phone: 484.250.5147 | Fax: 484.250.5971 www.depweb.state.pa.us

From: Majett, Carrie

Sent: Thursday, May 04, 2017 8:44 AM

To: Knorr, Donald <doknorr@pa.gov>

Subject: Incident Report

Hi Don,

Please see the attached Incident Report that was sent to us this morning; however while talking to him, I found out that it went into a creek. He said that he spoke to you last night or contacted you.

Thanks Don.

Carrie

DEP INCIDENT NOTIFICATION REPORT	
REVISED 1/26/17	

Received By	Carrie Majett	
Date Received	May 4,2017	
Time Received	8:16am	
Reported During	☐ After Hours	☑ Work Hours

	CALLERS NAME/ORGANIZATION	TELEPHO	NE NUMBER
1.	Chris Embry/Sunoco Logistics	610-670-323	7
2.	* * * * * * * * * * * * * * * * * * * *		
	BREIF DESCRIPTION OF INCIDENT (See NOTES AND CALL LOG on reverse)	Incident Date	Incident Time
		5/3/2017	3:00 pm

	INCIDENT LOCATION			
County:	Delaware	ADDRESS / DIRECTIONS:		
Township:	Aston Township	Intersection of Beatrice&Judy Lane/		
		Aston, PA		

		POTENIALLY RESPONSIBLE PART	Y
NAME/ORG	SANIZATION:	Sunoco Logistics	PHONE NUMBER
ADDRESS:	535 Fritzto	own Road, Sinking Spring,PA 19608	610-670-3237

	INCIDENT CONTAMINA	ANT INFORMATION	ing fishing a segment of		
INCIDENT CLASSIFICATION: Water Contamination MEDIA CONTAMINATED:					
TYPE OF RELEASE:	Release/Discharge	Prima	Surface Water		
SUBSTANCE:	Bentonite Clay&Water	Seconda	Surface Water		
MATERIAL INVOLVED:	Other	QUANTITY/UNITS:	Appx. 500 Gallons		
WATERWAY IMPACT:	Affected	WATER SUPPLY:	Yes		
WATERWAY NAME:	Chester Creek	SOURCE OF MATERIAL:	Other/Natural		
TOTAL POTENTIAL RELEASE A	MOUNT, even if none actually got	out.	500 Gallons		
TOTAL RELEASE AMOUNT, whether or not any was contained or recovered:			500 Gallons		
TOTAL AMOUNT KNOWN TO	BE CONTAINED AND/OR RECOVERED	•	500 Gallons		

INCIDENT REFERRAL							
INCEDENT REFERRED FOR:	Program Follow-Up/Information	DATE REFERRED:	5/4/2017				
PROGRAM(S) REFERRED TO:	Water Supply	WATER SUPPLY					

REMEDIAL ACTION(S) TAKEN: (Source Control, Containment, Counter Measure, Clean-Up)					
Contained it and clean it up. Us vac truck to remove the material.					
CLEANUP CONTRACTOR RETAINED BY: Responsible Party					
CLEANUP CONTRACTOR NAME:		PHONE NUMBE	R:		

ENVIRON	MENTALLY	RELATED EVACUA	ATIONS/CASUALTIES: Choo	se an item.
NUMBER EVACUATED	N/A	NUMBER INJURED	NUMBER OF FATAL	ITIES

MATI	RIALS USED (Adsorbent, Test	strips, Samples, PPE, etc.)	
	Sand Bags		
HOURS WORKED:	MILEAGE:	PAY GRADE:	

HOURS WORKED:	MILEAGE:	PAY GRADE:	
	ADDITIONAL INCIDE		
They were installing causing the clay to	g horizontal direction drills, a go into the creek.	ind there were an inadverant	return,