

PHOTOGRAPHIC LOG

Client Name:

PennEast Pipeline

Site Location:

Luzerne County, Pennsylvania

Project No. 60414094

Photo No.

Date:

1

04/25/16

Direction Photo Taken:

Southeast

Description:

Intermittent stream, 042517_GM_1002_I_MI, flows to an existing dirt road (AR-033A) from the southeast.



Photo No.

2

04/25/16

Date:

Direction Photo Taken:

West

Description:

Intermittent Stream 042517_GM_1002_I_MI follows a tire rut for approximately 60 feet (west) then exits AR-033A to the northwest.



Photo No.

Date:

04/25/16

Direction Photo Taken:

Northwest

Description:

View of stream northwest of the existing dirt access road (AR-33).

