COMMONWEALTH OF PENNSYLVANIA ENVIRONMENTAL QUALITY BOARD

PETITION FORM

I.	PE	PETITIONER INFORMATION										
		Name: Clearfield Creek Watershed Association										
		Mailing Address: 316 Beldin Hollow Road										
	Ashville, PA 16613											
		Telephone Number: 814-238-2838 2/3/14 Date: 1/11/14										
п.	PE'	ITION INFORMATION										
	A.	The petitioner requests the Environmental Quality Board to (check one of the following):										
		☐ Adopt a regulation										
		Amend a regulation (Citation)										
		Repeal a regulation (Citation)										
		Please attach suggested regulatory language if request is to adopt or amend a regulation.										
	B.	Why is the petitioner requesting this action from the Board? (Describe problems encountered under current regulations and the changes being recommended to address the problems. State factual and legal contentions and include supporting documentation that establishes a clear justification for the requested action.) We petition that the Designated Use for the headwaters section of Beaverdam Run in Cambria County be upgraded from CWF:MF to Extra Value (EV). The stream is a significant tributary to Glendale Lake at Prince Gallitzin Park and the excellent quality should be preserved to protect fishing and water activities. The chemistry and biota of the stream currently justify this upgrade. The current good fishing in the stream and its tributaries should be preserved. Some of the watershed is within the boundaries of Prince Gallitzin Park and some is within State Gameland 108.										

C.		scribe the types of persons, businesses and organizations likely to be impacted by this proposal. significant impacts are evident. About 40% of the watershed is forested; most of the rest is agricultural,						
		inly growing hay, and including a few small dairy operations. About 12 homes lie within the watershed,						
D.	Does the action requested in the petition concern a matter currently in litigation? If yes, please explain.							
		are not aware of any litigation in the watershed.						
E.		stream redesignation petitions, the following information must be included for the petition to be considered applete. Attach supporting material as necessary.						
	1.	A clear delineation of the watershed or stream segment to be redesignated, both in narrative form and on a map.						
	2.	The current designated use(s) of the watershed or segment.						
	3.	The requested designated use(s) of the watershed or segment.						
	4.	Available technical data on instream conditions for the following: water chemistry, the aquatic community (benthic macroinvertebrates and/or fishes), or instream habitat. If such data are not included, provide a description of the data sources investigated.						
	5.	A description of existing and proposed point and nonpoint source discharges and their impact on water quality and/or the aquatic community. The names, locations, and permit numbers of point source discharges and a description of the types and locations of nonpoint source discharges should be listed.						
	6.	Information regarding any of the qualifiers for designation as high quality waters (HQ) or exceptional value waters (EV) in §93.4b (relating to qualifying as High Quality or Exceptional Value waters) used as a basis for the requested designation.						
	7.	A general description of land use and development patterns in the watershed. Examples include the amount or percentage of public lands (including ownership) and the amount or percentage of various land use types (such as residential, commercial, industrial, agricultural and the like).						
	8.	The names of all municipalities through which the watershed or segment flows, including an official contact name and address.						
	9.	Locational information relevant to items 4-8 (except for contact names and addresses) displayed on a map						


All petitions should be submitted to the Secretary of the Department of Environmental Protection P.O. Box 2063 Harrisburg, PA 17105-2063

or maps, if possible.

PETITION FOR UPGRADE OF BEAVERDAM RUN, CAMBRIA COUNTY

- 1. The proposed upgrade includes the watershed of Beaverdam Run upstream of Beaver Valley Road. The watershed is a significant tributary of Glendale Lake in Chest Township. The stream extends west from the lake for about 1.5 miles, then southward for about 2 miles across Glendale Lake Road (SR1021). See the accompanying map.
- 2. The current designated use is CWF-MF.
- 3. The requested designated use is CWF-MF-EV
- 4. See the 2 attached reports of chemical and biota testing at 2 sites along the stream. The tests show that the stream meets Extra Value standards.
- 5. No permitted discharges are known within the watershed.
- 6. The IBI using the SSWAP method is 92 for the sample site near the mouth and 96.5 a short distance upstream.
- 7. The watershed has an area of about 3.4 square miles. About 40% of the watershed is forested and 60% is cleared land. The farmland is mainly for dairying. About 0.5 sq. mi. of the watershed is in State Gameland 108. An additional forested area is held by the Patton Sportsmen Club. The Commonwealth of PA holds mineral rights in most of its land, and Cambria Heights School owns mineral rights at the west side of the watershed. There is no other significant industry or commercial activity within the watershed.
- 8. About 2/3 of the watershed is in Chest Township, and the other 1/3 is in Allegheny Township, part of Cambria County. The contact phone for Chest Township is 814-674-8166 or 814-674-5259. Mr. Mark Lachene is Chair of the Chest Township Supervisors. The phone for Clearfield Township is 814-674-8166.
- 9. See map.





Glendale Lake Area

Cambria County

Showing Wyerough, Killbuck and Beaverdam Runs

2 miles

Station ID 20120502-1115-dcounahan

Survey ID 63625

Stream Name Beaverdam Run (01209357) Sample Method 6-Dframe Composite, 200 subsample

Stream Code 26371

Strahler 3

Collection Date 20120502

Collection Time 1115

Latitude 40.6472074 Longitude -78.5872626

HUC8 02050201 Upper West Branch Susquehanna

Station Location Comments

Beaverdam Run - CWF - HUC 02050201 - SWP 08C - 20120502-1115-DFC.

West Br Susquehanna Segment 01 Site 112, Coalport Quad, Cambria County.

Driving Directions: From nagles Crossroads head north on Beaver Valley Roadbout 1,500 meters. Pull off on right. walk across Beaver Valley road. Sampled upstream of culvert.

Biology / Habitat Comments

Wild trout collected in net

All E,P,T in net

Lots of sand and cobble

many riffles

Land Use Comments

Station Impairment Status Comments

Station attained, IBI Score = 92.6. Designated use of CWF should be re-evaluated.

Taxa List			# grids	from first pan	6 # grids from	n second pan	0	Subsample Size 239
Taxa Name	Individuals	PTV	FFG	BCG A (coldwater)	Attribute (warmwater)	any EV indic	ator	taxa names are highlighted
Baetis	2	6	CG	4	5			
Diphetor	1	6	CG	2	2			
Epeorus	6	0	SC	2	2			
Maccaffertium	3	3	SC	3	3			
Drunella	3	1	SC	2	2			
Ephemerella	93	1	CG	3	2			
Ephemera	1	2	CG	3	2			
Pteronarcys	1	0	SH	1	2			
Tallaperla	1	0	SH	1	1			
Amphinemura	3	3	SH	3	3			
Leuctra	8	0	SH	2	2			
Acroneuria	3	0	PR	3	3			
Remenus	2	2	PR	1	1			
Isoperla	1	2	PR	2	2			
Haploperia	2	0	PR	3	3			
Nigronia	1	2	PR	3	3			
Wormaldia	6	0	FC	1	1			
Polycentropus	4	6	FC	4	4			
Diplectrona	34	0	FC	2	2			
Ceratopsyche	2	5	FC	4	4			
Cheumatopsyche	1	6	FC	5	5			
Rhyacophila	2	1	PR	2	2			
Pycnopsyche	1	4	SH	3	3			
Neophylax	1	3	SC	3	3			
Ectopria	2	5	SC	3	3			
Optioservus	13	4	SC	4	4			
Oulimnius	11	5	SC	3	2			
Ceratopogonidae	1	6	PR	4	4			
Chelifera	2	6	PR	4	4			
Tipula	1	4	SH	5	5			
Antocha	2	3	CG	4	4			
Chironomidae	24	6	CG	5	5			
Oligochaeta	1	10	CG	5	5			

Station ID 20120502-1115-dcounahan

Stream Name Beaverdam Run (01209357)

Stream Code 26371

Strahler 3

Survey ID 63625

Sample Method 6-Dframe Composite, 200 subsample

Latitude 40.6472074 Longitude -78.5872626

Collection Date 20120502 Collection Time 1115

	res				Standa	rdized Met	ric Values		
				reestone					
		Raw		6D200	IXIIIIG-IX	uii			
	Metric	2009	2011			Multihabi	tat Lime	estone	
Metric Names		Values	small	large	2007	2D100	Pool-Glie		2009
Total Richness		33	100.0	106.5	94.3		106.5	178.3	183.3
Ephemeroptera Richness		7					116.7		
Trichoptera Richness		8					72.7		
EPT Richness		23			100.0	150.3	135.3	287.5	287.5
Trichoptera Richness (PTV	(0-4)	5				138.9			
EPT Richness (PTV 0-4)		18	94.7	112.5					
Beck's Index (version 3)		34	89.5	154.5	87.2				
Beck's Index (version 4)		33				165.8	150.0		275.0
FC + PR + SH Richness		19				163.8			
Hilsenhoff Biotic Index		2.05	98.0	114.4	96.7	117.9		126.4	129.1
% Inolerant Individuals (P	TV 0-3)	72.4	85.7	108.5				275.2	
% Intolerant Individuals (P	TV 0-5)	84.9			91.8				
% Tolerant Individuals (P7	TV 7-10)	0.4						100.6	101.1
Shannon Diversity		2.36	82.4	82.4	81.4		97.0	122.8	110.7
	IBI s	core	91.7	97.1	91.9	100.0	95.0	100.0	100.0
% Ephemeroptera 45.6 %	6 Ephen	neroptera (PTV 0-4)	44.4	% Domi	nant Taxon	38.9	BCG Richness R	atio 2
% Plecoptera 8.8 Ephemeroptera Rici			hness(PT	V 0-4) 5	% Chironomidae		10.0	BCG Individuals	Ratio 3
% Trichoptera 21.3 P	lecopte	ra Richnes	S	8	% Simu	liidae	0.0	EV Indicator Tax	a Richness
Not impaired Y Bi	ology in	paired N	Hab	itat impair	ed N	Ir	sufficient (data N	
	sment	N	lmp	act is loca	lized N	R	e-evaluate	designated use	4
Rock pick influenced asses								Pool-Glide Asse	ssment? N
Rock pick influenced asses Physical Habitat Ass	sessm	ent						The state of the s	
	sessm		trate / Cov	er 0	Frequ	ency of Riff	iles 20	Contition of Ban	ks 17
Physical Habitat Ass						ency of Riff			20000
Physical Habitat Ass Instream Cover 19		Subst elocity/Dep		es 18	Cha	78	sity 20	Contition of Ban	16
Physical Habitat Ass Instream Cover 19 Epifaunal Substrate 18		Substelocity/Dep	th Regime	es 18 ity 0	Chann Chann	nnel Sinuos	sity 20 tus 19	Contition of Ban Bank Vegetation	16
Physical Habitat Ass Instream Cover 19 Epifaunal Substrate 18 Embeddedness 16 Pool Substrate 0		Substellocity/Dep Pool Sedimen	oth Regime	es 18 ity 0 on 16	Chann Chann	nnel Sinuos el Flow Sta nnel Alterat	sity 20 tus 19 ion 18	Contition of Ban Bank Vegetation Disruptive Press	16 sure 14
Physical Habitat Ass Instream Cover 19 Epifaunal Substrate 18 Embeddedness 16 Pool Substrate 0 Instre	Vo	Substellocity/Dep Pool Sedimen	oth Regime	es 18 ity 0 on 16 Riparian	Cha Chann Cha	nnel Sinuos el Flow Sta nnel Alterat	sity 20 tus 19 ion 18	Contition of Ban Bank Vegetation Disruptive Press Riparian Zone	16 sure 14
Physical Habitat Ass Instream Cover 19 Epifaunal Substrate 18 Embeddedness 16 Pool Substrate 0	Vo	Subst elocity/Dep Pod Sediment re 69	oth Regime of Variabili t Deposition	es 18 ity 0 on 16 Riparian	Cha Chann Cha Score 46	nnel Sinuos el Flow Sta nnel Alterat	sity 20 tus 19 ion 18	Contition of Ban Bank Vegetation Disruptive Press Riparian Zone Score 204	16 sure 14
Physical Habitat Ass Instream Cover 19 Epifaunal Substrate 18 Embeddedness 16 Pool Substrate 0 Instre	Ve eam Sco	Subst elocity/Dep Poor Sediment re 69	oth Regime of Variabili t Deposition	es 18 ity 0 on 16 Riparian Lab s	Chann Chan Chan Score 46	nnel Sinuos nel Flow Sta nnel Alterat	sity 20 tus 19 ion 18 Total	Contition of Ban Bank Vegetation Disruptive Press Riparian Zone Score 204	16 sure 14
Physical Habitat Ass Instream Cover 19 Epifaunal Substrate 18 Embeddedness 16 Pool Substrate 0 Instre Field Measurements Temperature (°C) 11.9 pH 7.38	Vo eam Sco i	Subsite of the state of the sta	oth Regime of Variabili t Deposition lived Oxyg y (mg/L as	es 18 ity 0 on 16 Riparian Lab s en (mg/L)	Chann Chann Cha Score 46 samples 9.33 40	nnel Sinuos nel Flow Sta nnel Alterat	sity 20 tus 19 ion 18 Total	Contition of Ban Bank Vegetation Disruptive Press Riparian Zone Score 204	16 sure 14
Physical Habitat Ass Instream Cover 19 Epifaunal Substrate 18 Embeddedness 16 Pool Substrate 0 Instre Field Measurements Temperature (°C) 11.9	Vocatus fo	Subsite of Sediment of Sedimen	oth Regime bl Variabilit Deposition lived Oxyg y (mg/L as	es 18 ity 0 on 16 Riparian Lab s en (mg/L)	Chann Chann Cha Score 46 Samples 9.33 40 Design	nnel Sinuos nel Flow Sta nnel Alterat	sity 20 tus 19 ion 18 Total Flow (C	Contition of Ban Bank Vegetation Disruptive Press Riparian Zone Score 204	16 sure 14
Physical Habitat Ass Instream Cover 19 Epifaunal Substrate 18 Embeddedness 16 Pool Substrate 0 Instre Field Measurements Temperature (°C) 11.9 pH 7.38 Use Assessment Sta	Totatus fo	Subsine Poor Sedimentore 69 Dissocial Alkalining (20130)	oth Regime bl Variabili bl Deposition lived Oxyg y (mg/L as m Reac 806-0841	es 18 ity 0 on 16 Riparian Lab s en (mg/L) s CaCO3) h	Chann	nnel Sinuos el Flow Sta nnel Alterat Condu	sity 20 tus 19 ion 18 Total Flow (Cuctivity (us)	Contition of Ban Bank Vegetation Disruptive Press Riparian Zone Score 204 FS) 0 cm) 229	16 16 sure 14 13
Physical Habitat Ass Instream Cover 19 Epifaunal Substrate 18 Embeddedness 16 Pool Substrate 0 Instre Field Measurements Temperature (°C) 11.9 pH 7.38 Use Assessment Sta	Totatus fo	Subsine Poor Sedimentore 69 Dissocial Alkalining (20130)	oth Regime bl Variabili bl Deposition lived Oxyg y (mg/L as m Reac 806-0841	es 18 ity 0 on 16 Riparian Lab s en (mg/L) s CaCO3) h	Chann	nnel Sinuos el Flow Sta nnel Alterat Condu	sity 20 tus 19 ion 18 Total Flow (Cuctivity (us)	Contition of Ban Bank Vegetation Disruptive Press Riparian Zone Score 204	16 16 sure 14 13
Physical Habitat Ass Instream Cover 19 Epifaunal Substrate 18 Embeddedness 16 Pool Substrate 0 Instre Field Measurements Temperature (°C) 11.9 pH 7.38 Use Assessment Sta	Totatus fo	Subsine Poor Sedimentore 69 Dissocial Alkalining (20130)	oth Regime bl Variabili bl Deposition lived Oxyg y (mg/L as m Reac 806-0841	es 18 ity 0 on 16 Riparian Lab s en (mg/L) s CaCO3) h	Chann	nnel Sinuos el Flow Sta nnel Alterat Condu	sity 20 tus 19 ion 18 Total Flow (Cuctivity (us)	Contition of Ban Bank Vegetation Disruptive Press Riparian Zone Score 204 FS) 0 cm) 229	16 16 sure 14 13
Physical Habitat Ass Instream Cover 19 Epifaunal Substrate 18 Embeddedness 16 Pool Substrate 0 Instre Field Measurements Temperature (°C) 11.9 pH 7.38 Use Assessment Sta	Totatus fo	Subsine Poor Sedimentore 69 Dissocial Alkalining (20130)	oth Regime bl Variabili bl Deposition lived Oxyg y (mg/L as m Reac 806-0841	es 18 ity 0 on 16 Riparian Lab s en (mg/L) s CaCO3) h	Chann	nnel Sinuos el Flow Sta nnel Alterat Condu	sity 20 tus 19 ion 18 Total Flow (Cuctivity (us)	Contition of Ban Bank Vegetation Disruptive Press Riparian Zone Score 204 FS) 0 cm) 229	16 16 sure 14 13

End Date

Draft Date

Meeting Date

Begin Date

Final Date 4/7/2007

Station ID 19990524-1730-LMS

Stream Name Beaverdam Run (01209357)

Stream Code 26371

Strahler

Survey ID 44087

Sample Method Kick Screen: Statewide Surface Water Assessment Program

3

Collection Date

Collection Time

Latitude 40.6490635 Longitude -78.6108232

HUC8 02050201

Upper West Branch Susquehanna

Station Location Comments

Site is located on Beaverdam Run off of T524 about 1.5 miles from intersection with SR 1021 at large bend in road (Coalport quad).

Biology / Physical Habitat Comments

Epeorus present. Beaverdams upstream.

Land Use Comments

Area at site is mostly forested, in state game lands 108. Some old field and residential upstream. Beaver dams upstream.

Impairment Status Comments

Sediment, probably from beaver dams upstream.

Taxa List					
	Abundance	Abundance			
Taxa Name	Category	Range	PTV	FFG	
Baetidae	Present	3-9	6	CG	
Heptageniidae	Common	10-24	3	SC	
Ephemerellidae	Abundant	25-100	2	CG	
Leptophlebiidae	Present	3-9	4	CG	
Ephemeridae	Present	3-9	4	CG .	
Gomphidae	Rare	<3	4	PR	
Nemouridae	Present	3-9	2	SH	
Leuctridae	Present	3-9	0	SH	
Perlidae	Present	3-9	3	PR	
Perlodidae	Rare	<3	2	PR	
Chloroperlidae	Rare	<3	0	PR	
Sialidae	Rare	<3	6	PR	
Nigronia	Present	3-9	2	PR	
Philopotamidae	Common	10-24	3	FC	
Polycentropodidae	Rare	<3	6	FC	
Hydropsychidae	Abundant	25-100	5	FC	
Rhyacophilidae	Present	3-9	1	SC	
Glossosomatidae	Rare	<3	0	SC	
Limnephilidae	Rare	<3	4	SH	
Elmidae	Present	3-9	5	CG	
Chironomidae(other)	Common	10-24	6		
Tipulidae	Rare	<3	4	SH	
Other Worms	Rare	<3	8		

SSWAP metrics and IBI

	Raw Metric Value	Standardized Metric Value	
Total Richness	23	104.5	
EPT Richness (PTV 0 - 4)	13	118.2	
Beck's Index (version 3)	15	107.1	
Hilsenhoff Biotic Index	3.53	87.3	
Shannon Diversitiy	2.51	95.3	
	SSWAP IBI	96.5	

Station ID 19990524-1730-LMS Stream Name Beaverdam Run (01209357) Stream Code 26371 Strahler 3 Sample Method Kick Screen: Statewide Surface Water Assessment Program Survey ID 44087 **Collection Date Collection Time** Latitude 40.6490635 Longitude -78.6108232 HUC8 02050201 Upper West Branch Susquehanna 1. Abundance obviously low N 2. Seven or fewer families N 3. Three or fewer mayfly individuals (exclude Baetidae, Caenidae, Siphlonuridae) N 4. Stoneflies collectively present Mayflies and caddisflies collectively abundant (exclude Baetidae, Caenidae, Siphlonuridae, Hydropsychidae, Polycentropidae) N Jul - Sep: at least four EPT families with tolerance value of 4 or less Y Nov - May: at least six EPT families with tolerance value of 4 or less 7. Four or more famlies with tolerance value of 3 or less Y 8. Six or more families with tolerance value of 4 or less 9. Dominant family with tolerance value of 4 or less 10. Dominant family with tolerance value greater than 5 (criteria 7 and 8 negate this criterion) 11. Seven or more families with tolerance value of 6 or more (criteria 7 and 8 negate this criterion) 12. Sample dominated by families with a mean tolerance value of 5 or less 13. Sample dominated by families with a mean tolerance value of 6 or more 14. Embeddedness (or substrate character for pool/glide) + sediment deposition N = 24 or less (20 or less for warmwater, low gradient streams) 15. Condition of banks + bank vegetation = 24 or less (20 or less for warmwater, low gradient streams) 16. Total habitat score 140 or less for forested, coldwater, high gradient streams (120 or less for warmwater, low gradient streams) 17a. Special conditions (attaining) 17b. Special conditions (impaired) 17c. Special conditons description Not impaired Y Biology impaired N Habitat impaired N Insufficient data N Rock pick influenced assessment N Impact is localized Re-evaluate designated use N Physical Habitat Assessment Pool/Glide Assessment N Instream Cover Substrate / Cover Frequency of Riffles 14 **Contition of Banks** 15 **Epifaunal Substrate** Velocity/Depth Regimes **Channel Sinuosity** 15 16 **Bank Vegetation** Embeddedness 15 Channel Flow Status **Pool Variability Disruptive Pressure** 17 **Pool Substrate** Channel Alteration 16 0 Sediment Deposition 11 Riparian Zone 18 Instream Score 56 Riparian Score 49 Total Score 183 Field Measurements Lab samples Temperature (°C) Dissolved Oxygen (mg/L) Flow (CFS) 5.9 Alkalinity (mg/L as CaCO3) Conductivity 131 Use Assessment Status for Stream Reach **Designated Use CWF Existing Use Aquatic Life** Attaining (20130806-0841-gawalters) Attained based on station 20120502-1115-dcounahan. IBI score = 92.6 (gawalters) **Fish Consumption Potable Water Supply** Recreation TMDL Information (if any) Clearfield Creek (Finalized): AMD - Metals **Begin Date Meeting Date Draft Date End Date** Final Date 4/7/2007