



**WATER SUPPLY INSPECTION REPORT**

FACILITY NAME <b>West Lebanon Twp. Water System</b>		PWS ID NO. <b>7380040</b>	INSPECTION DATE <b>10/17/11</b>
FACILITY LOCATION/ADDRESS <b>322 N 22<sup>nd</sup> St, Lebanon PA 17046</b>		COUNTY <b>Lebanon</b>	MUNICIPALITY <b>W. Lebanon Twp</b>
RESPONSIBLE OFFICIAL'S NAME <b>John Brenner</b>		TELEPHONE NO. <b>274-1598</b>	
		SYSTEM TYPE <b>Comm.</b>	POPULATION <b>~900</b>
CERTIFIED OPERATOR'S NAME <b>J. Brenner / R. Lewis / Skinner</b>		FIELD ORDER NO.	
		ISSUE DATE (MM/DD/YY)	

V I O L A T I O N S	A1. Failure to respond to an emergency		C1. Failure to meet design/construction stds.		INSPECTION TIME START <b>9:00</b> STOP <b>10:55</b>
	A2. Failure of key treatment processes		C2. Failure to conduct performance monitoring		
	A3. Failure to respond to an acute violation		C3. Failure to treat as permitted		
	B1. Failure to provide an adequate supply		C4. Failure to operate and maintain PWS		INSPECTION TYPE FULL PARTIAL <input checked="" type="checkbox"/>
	B2. Failure to provide min. disinfectant residual		C5. Failure to obtain certified operator		
	B3. Failure to respond to PMCL/TT violation		C6. Improper interruption/repair		COMPLAINT
B4. Failure to comply with an Order		C7. Failure to comply with permit condition		FOLLOWUP	
B5. Failure to obtain a permit		D1. Reports/Records/Maps			
B6. Other significant deficiencies		E1. Other			

NARRATIVE Inspection conducted today due to information that there was a heating oil discharge <sup>(small amount of sludge)</sup> at Brentwood Industries due to flooding. Brentwood Industries is located at 2101 Lehman St Lebanon PA (West Lebanon)

Well #1 is about 1100ft+ steeply upgradient from the discharge site.  
Well #2 is about 1600 ft. from the discharge site at the same approximate elevation.

DEP Hydrogeol. { Derrick Havice P.G. recommended water testing based on information from Kathy Horvath P.G. She recommended West Lebanon be on the look-out lists for petroleum taste/odor and sheen. John Brenner stated he will take a VOA sample in November 2011 and again in Jan-Feb 2012, and be vigilant for petroleum markers.

WATER QUALITY SAMPLING POINT LOCATION	SAMPLE NUMBER	pH	CHLORINE		TURBIDITY	OTHER	COLLECTION TIME	SAC #
			F	T				

Not requested - copy mailed  
RECEIVED BY (SIGNATURE AND DATE)  
**2011839**  
FACTS INSPECTION ID NO.

Jack Curry 10/17/11  
INVESTIGATOR (SIGNATURE AND DATE)  
**-NA-**  
FACTS VIOLATION ID NO.

B  
SUPV. INITIALS  
**NA**  
PADWIS UPDATED

White - District Office       Yellow - Regional Office       Pink - Public Water Supplier