

Facility Name: Middle Spring Creek Primary Facility ID: _____

Inspection Date: 08/07/24		Inspection Time: 08:40		Lat/Long: Various	
Program: ECB		☐ Storage Tanks		☒ HSCA	
				☐ LRP	
Owner Name: Various			Inspection ID:		Site ID:
Facility Location (911) Address: 1503 Roxbury Road 1409 Roxbury Road 22 Fish Hatchery Road 35 Fish Hatchery Road 40 Fish Hatchery Road				Municipality: Southampton Township	
				County: Cumberland/Franklin	
Responsible Official Name:				Responsible Official Address:	
Title: Environmental Protection Specialist				SCRO	
				909 Elmerton Ave	
				Harrisburg 17110	
Responsible Official Telephone:				Interviewee Name:	
Email Address: crywolf@pa.gov				Affiliation:	
				Email Address:	

Narrative:

Weather: Cloudy and misty, approx. 75 degrees F

Left office and arrived at 1503 Roxbury Rd, Mr. Paul Witter's Farm where biosolids are permitted to be applied. I arrived at 08:40 but Mr. Witter was not home. He and I had previously spoken on the phone where he had given permission to take samples from the water spigot next to the burn barrel in front of his house. Took samples (#201) including a duplicate sample (#202) and field blank (#203).

Drove to Terry Diehl's house but there was no answer. Stopped at his butcher shop next door and spoke with Mr. and Mrs. Diehl. Took sample at 09:10 (#204) from the butcher shop sink which is on the same source well as the residence. They have cartridge filters and UV on their water supply. Sample was taken post-treatment. They said that they comply with regulations for sampling of the butcher shop water. They mentioned that during storms there is often a lot of surface runoff across Mr. Witter's Farm towards their property and Middle Spring Creek.

Next, I stopped at Jeffrey and Dorothy Zeigler's home at 35 Fish Hatchery Road. Mr. Zeigler has cartridge filtration so I took a sample before treatment in the basement and then post-treatment at the kitchen tap. At 09:30 I took pre-treatment sample #205 and at 09:35 I took post-treatment sample #206.

I stopped at Weaver Compact Tractor at 22 Fish Hatchery Road and Mrs. Weaver showed me where the reverse osmosis water treatment was in their basement. I collected sample #207 at 09:50. At 09:55 I collected a sample (#208) at the kitchen tap.


DEP Representative Name Crystal Wolf	DEP Representative Signature 	Title Environmental Protection Specialist	Date: 08/07/24
			Telephone: 717-705-7751
<i>Signature by the person interviewed does not necessarily imply concurrence with the findings on this report, but does acknowledge that the person was shown the report or that a copy was left with the person.</i>			
			Telephone:

Facility Name: _____ Middle Spring Creek _____ Primary Facility ID: _____

Narrative (continued):

Next I went to Mr. Gary Cassatt's house at 40 Fish Hatchery Road. There is no treatment on his water, but his water is spring fed and there is a spring house down the hill from his house which I did not inspect. I took sample #209 from his kitchen tap at 10:25.

I drove into Shippensburg for lunch and then drove to BOL to drop off samples at 11:40.

DEP Representative Name Crystal Wolf	DEP Representative Signature 	Title Environmental Protection Specialist	Date: 08/07/24
			Telephone: 717-705-7751
<i>Signature by the person interviewed does not necessarily imply concurrence with the findings on this report, but does acknowledge that the person was shown the report or that a copy was left with the person.</i>			
Interviewee Name	Interviewee Signature	Title	Date:
			Telephone:



NARRATIVE REPORT FORM


Facility Name: _____ Middle Spring Creek _____ Primary Facility ID: _____

MAPS / PHOTOGRAPHS / ATTACHMENTS

Page 3 of 5 Page 4 of 5



NARRATIVE REPORT FORM



DEP Representative Name Crystal Wolf	DEP Representative Signature <i>Crystal Wolf</i>	Title Environmental Protection Specialist	Date: 08/07/24 Telephone: 717-705-7751
--	--	--	---