

2700-FM-AQ0023 Rev. 1/2008 pennsylvania DEPARTMENT OF ENVIRONMENTAL PROTECTION		INSPECTION REPORT		Commonwealth of Pennsylvania Department of Environmental Protection Air Quality Program	
Date(s) of Inspection:	TV ☐ SM ☐ NM ☐	PA ☐ GP ☐ MEGA ☐	Permit #(s): GP-01-0050 GP-01-0153	Expiration Date: 12/27/22	Case #: _____
Company Name: Richard E. Pierson Materials Corp.			Municipality: East Rockhill Twp		County: BUCKS
Plant Name: East Rockhill Quarry			Physical Location: 2105 N. Rockhill Rd. Sellersville, PA 18960		Federal ID — Plant Code #:
Responsible Official: Jim Allen			Mailing Address:		
Title: Site Superintendent					
Phone #(s): 609-743-0350					

Mark (X) All Inspection Types That Apply To This Inspection:

☐ Full Compliance Evaluation (FCE)	☐ Plan Approval Inspection	☐ File Review (FR)
☐ Operating Permit Inspection (PI)	☐ Initial Permit Inspection (IPI)	☐ Complaint Inspection (CI)
☒ Routine/Partial (RTPT)	☐ Follow-Up Inspection (Ref. Date: _____)	☐ Sample Collection (SC)
☐ Minor Source(s) Inspection (RFD)	☐ Stack Test Observation	☐ Multi-Media Inspection (MM)
☐ Other:	☐ Announced	

Annual Compliance Certification Received: ☐ YES ☐ NO ☒ N/A	Date Received:
AIMS Report Received: ☐ YES ☐ NO ☒ N/A	Date Received:

Mark (X) All Activities That Apply:

☐ File Review	☒ Pre-Inspection Briefing	☒ Exit Interview/Briefing
☒ Pre-Inspection Observations	☒ Check For New/Unreported Sources	☐ Sample(s) Collected
☐ Visible Emissions Observations	☐ Verify Operation of CEMS	☐ Other

Comments/Recommendations:

Enforcement since last FCE ☐ Yes ☐ No (If yes, attach summary)

I arrived on site at 11:40 am to conduct a routine/partial inspection. I met with Jim Allen from R.E. Pierson who directed me to where their consultant was sampling. I met with Louis Vittorio Jr and Christopher DeMarco, from EarthKies, who had just finished sampling crusher fines near the portable crushing area. 2 composite samples were taken at four different locations. I was then shown where the samples were taken at the aggregate stockpiles, 4 samples were taken from the 4 stockpiles. I then observed 5 samples of water being taken, 2 from NPDS outfall, 2 from retention ponds, and 1 from the quarry pit pond. I took pictures of

Compliance Status: ☐ In ☐ Out ☐ Pending ☐ Awaiting Co. Report	Needs a Follow-Up Inspection? ☐ Yes ☐ No		
Company Representative: James Allen	Title: Site Supt	Signature: 	Date: 12/20/18
DEP Representative: Jennifer Remes-Buschmann	Title: AQ Specialist	Signature: 	Date/Time: 12/20/18

This document is official notification that a representative of the Department of Environmental Protection, Air Quality Program, inspected the identified site. The findings of this inspection are shown above and on any attached pages, and may include violations uncovered during the inspection. Violations may also be discovered upon review of sample results or from any additional review of Department records. Notification will be forthcoming, if such violations are noted.

pennsylvania
DEPARTMENT OF ENVIRONMENTAL PROTECTION

INSPECTION REPORT

Continued

Commonwealth of Pennsylvania
Department of Environmental Protection
Air Quality Program

each sample location. I did not observe any crushing activities taking place during my inspection. I noted no visible emissions, fugitive emissions, or malodors while I was on site.

Company -- plant name:

RE Pearson

Initials of representative interviewed:

ja

Date:

12/20/18

Page 2 of 2

Reviewed By

sem

☐ White – Site☐ Yellow – District Office☐ Pink – Regional Office

Aggregate Sampling

Samples collected from fines under the portable crusher:

First 4 composite sample locations





Overview of first 4 composite samples



Second 4 composite sample locations







Overview of second 4 composite samples



Aggregate Sample from 2A Stone Pile:



Pad 1



Pad 2



Aggregate sample from 1B Stone Pile:





Aggregate sample from 2B Stone Pile:





Aggregate sample from Screenings Pile:





Water Sample from NPDES 001 Outfall:





Water Sample from first sediment pond:





Water Sample from second sediment pond:





Water Sample from main quarry pit:



