

2700-FM-AQ0023 Rev. 1/2008 pennsylvania DEPARTMENT OF ENVIRONMENTAL PROTECTION			INSPECTION REPORT		Commonwealth of Pennsylvania Department of Environmental Protection Air Quality Program		
Date(s) of Inspection: 1/16/19		TV ☐ SM ☐ NM ☐	PA ☒ GP ☐ MEGA ☐	Permit #(s): 09-0241	Expiration Date: 5/30/20	Case #: —	PF ID #: 823349
Company Name: Richard E. Pierson Materials Corp.			Municipality: East Rockhill Twp		County: Bucks		
Plant Name: East Rockhill Quarry			Physical Location: 2105 N. Rockhill Rd Sellersville, PA 18400		Federal ID — Plant Code #:		
Responsible Official: Jim Allen				Mailing Address: PO Box 704			
Title: Site Superintendent				Bridgeport, NJ 08014			
Phone #(s): 609-743-0350							
Mark (X) All Inspection Types That Apply To This Inspection:							
☐	Full Compliance Evaluation (FCE)		☐	Plan Approval Inspection		☐	File Review (FR)
☐	Operating Permit Inspection (PI)		☐	Initial Permit Inspection (IPI)		☐	Complaint Inspection (CI)
☒	Routine/Partial (RTPT)		☐	Follow-Up Inspection (Ref. Date: _____)		☐	Sample Collection (SC)
☐	Minor Source(s) Inspection (RFD)		☐	Stack Test Observation		☐	Multi-Media Inspection (MM)
☐	Other:		☒	Announced			
Annual Compliance Certification Received: ☐ YES ☐ NO ☒ N/A					Date Received:		
AIMS Report Received: ☐ YES ☐ NO ☒ N/A					Date Received:		
Mark (X) All Activities That Apply:							
☐	File Review		☒	Pre-Inspection Briefing		☒	Exit Interview/Briefing
☒	Pre-Inspection Observations		☒	Check For New/Unreported Sources		☐	Sample(s) Collected
☐	Visible Emissions Observations		☐	Verify Operation of CEMS		☐	Other
Comments/Recommendations:							
Shawn Mountain and I arrived on site at 8:00 am to conduct a routine/partial inspection to observe air sampling. We met with Andrew Gutshall (from Hanson), Leo Church (from R.E. Pierson), Skip Garner, Tim Walters, Stefan Brooks (from Compliance Plus Services). We observed the sampling of 6 locations, took photos, and the filter collection, labeling, and pump calibration. We observed that there was no activity at the site during the sampling. A train went by during sampling, and a track being loaded onto a flatbed. We left the site near the end of the sampling run, and came back before they							
Enforcement since last FCE ☐ Yes ☐ No (If yes, attach summary)							
Compliance Status: ☐ In ☐ Out ☐ Pending ☐ Awaiting Co. Report					Needs a Follow-Up Inspection? ☐ Yes ☐ No		
Company Representative: Leo Church		Title: Sales		Signature: 		Date: 1/16/19	
DEP Representative: Jennifer Ramos-Buschmann		Title: AD Specialist		Signature: 		Date/Time: 1/16/19 2:15pm	
This document is official notification that a representative of the Department of Environmental Protection, Air Quality Program, inspected the identified site. The findings of this inspection are shown above and on any attached pages, and may include violations uncovered during the inspection. Violations may also be discovered upon review of sample results or from any additional review of Department records. Notification will be forthcoming, if such violations are noted.							

pennsylvania
DEPARTMENT OF ENVIRONMENTAL PROTECTION

INSPECTION REPORT

Continued

Commonwealth of Pennsylvania
Department of Environmental Protection
Air Quality Program

were finished, we observed no visible emissions, fugitive emissions, or malodors while on site. Arnee Bolinger was on site for a short time during the sampling. CPS told us that they plan to sample an additional 4 days, not necessarily consecutively.

Company -- plant name:

K.E. Pearson

Initials of representative interviewed:

L.C.

Date:

1/16/2019

Page 2 of 2

Reviewed By

Slm

☐ White -- Site☐ Yellow -- District Office☐ Pink -- Regional Office

PHOTO LOG FORM

Pennsylvania Department of Environmental Protection
Southeast Regional Office – Air Quality Program

Facility Name R.E. Pierson Materials Corporation	PF ID: 823349	Date Photos Taken 1/16/2019
Facility Address 2205 North Rockhill Road Sellersville, PA	Municipality East Rockhill Township County Bucks	

Photo ID #	Time	Description/Observations
IMG-0003	8:19 a.m.	Sample set-up West 1 (W1) (facing approx. S)
IMG-0004	8:19 a.m.	Sample set-up W1 – note filter canister
IMG-0005	8:20 a.m.	Close-up of pump on sample set-up W1
IMG-0006	8:20 a.m.	Close-up of pump on sample set-up W1
IMG-0007	8:33 a.m.	Sample set-up West 2 (W2) (facing approx. N)
IMG-0008	8:44 a.m.	Sample set-up Middle 1 (M1) (facing approx. E)
IMG-0009	8:44 a.m.	Sample set-up M1 (facing approx. E)
IMG-0010	8:45 a.m.	Sample set-up M1 close-up
IMG-0011	8:46 a.m.	Sample set-up M1 – note location near portable crushers (facing approx. WSW)
IMG-0012	9:04 a.m.	Sample set-up East 1 (E1) – blasted area near working face @ southern end of East area. (facing approx.. SSE)
IMG-0013	9:05 a.m.	Sample set-up E1 – blasted area near working face (facing approx. SW)
IMG-0014	9:05 a.m.	Inadvertent photo
IMG-0015	9:13 a.m.	Sample set-up East 2 (E2) – approximately the center of the East area above the high wall. (facing approx. WNW)
IMG-0016	9:15 a.m.	Sample set-up E2 (facing approx. SW)
IMG-0017	9:16 a.m.	Sample set-up E2 (facing approx. E)
IMG-0018	9:16 a.m.	Inadvertent photo
IMG-0019	9:16 a.m.	Inadvertent photo
IMG-0020	9:16 a.m.	Inadvertent photo
IMG-0021	9:26 a.m.	Sample set-up East 3 (E3) – Northern end of the East area above the high wall. (facing approx. S)
IMG-0022	9:26 a.m.	Sample set-up E3 – closeup
IMG-0023	9:27 a.m.	Sample set-up E3 – sample filter label

PHOTO LOG FORM

Pennsylvania Department of Environmental Protection
Southeast Regional Office – Air Quality Program

Facility Name	R.E. Pierson Materials Corporation	PF ID:	823349	Date Photos Taken	1/16/2019
Facility Address	2205 North Rockhill Road Sellersville, PA	Municipality	East Rockhill Township		
		County	Bucks		
IMG-0024	12:11 p.m.	Inadvertent photo – near E3			
IMG-0025	12:11 p.m.	Panorama from northern edge of pit			
IMG-0026	12:11 p.m.	Panorama from northern edge of pit			
IMG-0027	12:47 p.m.	Filter sample collection from W1 location.			
IMG-0030	12:47 p.m.	Inadvertent photo			
IMG-0032	1:00 p.m.	From west edge of highwall (facing approx. SW)			
DEP Photographer		Signature		Date	
Shawn Mountain				1/29/19	

IMG-0003



IMG-0004



IMG-0005



IMG-0006



IMG-0007



IMG-0008



IMG-0009



IMG-0010



IMG-0011




IMG-0012



IMG-0013



IMG-0014



IMG-0015




IMG-0016



IMG-0017




IMG-0018



IMG-0019



IMG-0020



IMG-0021



IMG-0022



IMG-0023



IMG-0024



IMG-0025




IMG-0026



IMG-0027



IMG-0030



IMG-0032

