2700-FM-BAQ0023 2/2015 pennsylvania DEPARTMENT OF ENVIRONMENTAL PROTECTION	INSPECTION REPORT		Commonwealth of Pennsylvania Department of Environmental Protection Air Quality Program	
Date(s) of Inspection: TV PA GP SM GP NM MEGA	Permit #(s): 101-0050 101-0050	Expiration Date:	Case #: PF ID #:	
Company Name:	Municipality:		County:	
Richard E. Pierson Materials	CAP. East ROLK	hill Twp	Bucks Forders ID — Plant Code #:	
5 East Rakhill Quarry	Same as b	pelow	Federal ID — Plant Code #:	
Responsible Official: Darren Landis		Mailing Address: 2051. Rock	chill the Rd	
Title: Supervisor/General	nl Manager	Sellersvill	e PA 18960	
Responsible Official: Darren Landis Title: Supervisor/General Manager Sellersville, PA 18960 Phone #(s): GC1-743-7195				
Mark (X) All Inspection Types That Apply To This Inspection:				
Full Compliance Evaluation (FCE)	☐ Plan Approval Inspecti		File Review (FR)	
Operating Permit Inspection (PI)	☐ Initial Permit Inspection	n (IPI)	Complaint Inspection (CI)	
☐ Routine/Partial (RTPT)	Follow-Up Inspection (Ref. Date:)	Sample Collection (SC)	
☐ Minor Source(s) Inspection (RFD)	Stack Test Observation	n	Multi-Media Inspection (MM)	
Other:	Announced	Announced		
Annual Compliance Certification Received: YES NO N/A Date Received:				
AIMS Report Received: YES NO N/A Date Received:				
Mark (X) All Activities That Apply:				
File Review	Pre-Inspection Briefing	1	Exit Interview/Briefing	
☐ Pre-Inspection Observations	☐ Check For New/Unrep	orted Sources	Sample(s) Collected	
☐ Visible Emissions Observations	☐ Verify Operation of CE	MS	Other	
Comments/Recommendations: Enforcement since last FCE Yes No (If yes, attach summary) Shawn Mountain and Wrived on site at 9.00 am and we met				
with Annie Bollinger (mining). We met with Richard Pierson Jr				
who gave us a tour of the Facility. (rushers on site are as				
follows: Model OH331, Serial # 0990J16260; Model O5331,				
Serial # 0990J16202; Mudel UJ440i, Serial # 6990515255.				
We were shound where the crushers are currently, where				
they will be used, and the location where they mining				
equipment will be. They have a 1,500 gallons water tank on site				
and plan to have a permenant water track on site, we				
informed him of the requirement to test the crushers				
Compliance Status:				
Company Representative:	Title:	Signature:	Date: /	
DEP Representative:	Title:	Luli	1/24/13	
Jeunifor Ramos-Bushmaun	AU Specialist	Signature:	my-Buchmann 124/18	
This document is official notification that a representative of the Department of Environmental Protection, Air Quality Program, inspected the identified site. The findings of this inspection are shown above and on any attached pages, and may include violations uncovered during the inspection. Violations may also be discovered upon review of sample results or from any additional review of Department records. Notification will be forthcoming, if such violations are noted.				
Page 1 of 2 eFacts Inspection ID#: 2686086 Date: 1/24/18 Reviewed By 5				
☐ White – Regional Office		'ellow – Site	☐ Pink – District Office	

2700-FM-AQ0024 Rev. 2/99	INSPECTION REPORT Continued	Commonwealth of Pennsylvania Department of Environmental Protection Air Quality Program
within 180% of First	operating. We also to	ld him that they
well have to monitor	the hours of operat	ion and firel
usage of the crush		re the portable
l' (<i>)</i>		ition and we
informed him that	they will need new	permits to do so.
We explained the f	-ugitive emission rego	lations to him
as well. We took pic	tures of the site,	
	_	
*		
Company-plant name: Richard E. Pierson Materi	Initials of representative interviews Als Corp - East Karkhill Quary	
Page <u>2</u> of <u>2</u>	Reviewed By	What I want to the same of the

(Serry)