2700-FM-BAQ0023 2/2015 pennsylvania penatrient of environmental perotection		INSPECTION REPORT			Commonwealth of Pennsylvania Department of Environmental Protection Air Quality Program	
Date(s) of inspection:  TV PA GP B  SM GP B  NM MEGA	] [6	499-09-0153 1	2/2	7 /22	Case	823349
Company Name: Richard E. Pierson Materials are East Rock			thill Tup County:			bucks
Plant Name: Physical Location:					eral ID — Plant Code #:	
East Rockhill Guarry Same as below  Responsible Official:  Mailing Address:						
Durren Landis			2105 N. ROCKHILL Rd.			
Title: General Manager  Phone #(s):			2105 N. ROCKHILL Rd. Sellersville, PA 18960			
Phone #(s): (e)9-743-7195						
Mark (X) All Inspection Types That Apply To This Inspection:						
Full Compliance Evaluation (FCE)		Plan Approval Inspection				File Review (FR)
Operating Permit Inspection (PI)		Initial Permit Inspection (IPI)			X	Complaint Inspection (CI)
Routine/Partial (RTPT)		Follow-Up Inspection (Ref. Date:)				Sample Collection (SC)
Minor Source(s) Inspection (RFD)		Stack Test Observation				Multi-Media Inspection (MM)
Other:	Announced					
Annual Compliance Certification Received: YES NO X N/A Date Received:						
AIMS Report Received:  YES NO NA Date Received:						
Mark (X) All Activities That Apply:						
File Review		Pre-Inspection Briefing			Ø	Exit Interview/Briefing
Pre-Inspection Observations		Check For New/Unreported Sources				Sample(s) Collected
☐ Visible Emissions Observations		Verify Operation of CEMS				Other
Comments/Recommendations:  I arrived on site at 1:30 pm to conduct a Complaint investigation in spection regarding dust. I net with Charlie Elwell who gove me a four of the facility. The primary crusher was not in operation but observed where the new water spray bur had been placed near the jaw. I did not observed any dust being kicked up from trucks driving around the site, and I was told that the water truck was full and ready to be used if necessary. Ar. Elwell told me that the complaint was made.						
Compliance Status:			ort	Needs a Follow-Up Inspection? Yes No		
Company Representative:	Title: Supervisor			Signature:		Date:
DEP Representative: Jennifer Ramos-Buchmann						
This document is official notification that a representative of the Department of Environmental Protection, Air Quality Program, inspected the identified site. The findings of this inspection are shown above and on any attached pages, and may include violations uncovered during the inspection. Violations may also be discovered upon review of sample results or from any additional review of Department records. Notification will be forthcoming, if such violations are noted.						
Page of eFacts Inspection ID#: 2723860 Date: 4/27/18 Reviewed By Say						eviewed By Serry
☐ White – Regional Office		☐ Yell	low – S	Site		☐ Pink – District Office