2700-FM-BAQ0023 2/2015 pennsylvania Department of environmental protection	INSPECTION	N REPORT	Commonwealth of Pennsylvania Department of Environmental Protection Air Quality Program
Date(s) of Inspection: TV PA U/7/18 SM GP X MM MEGA MEGA MEGA	Permit #(s): GP9-09-0080 GP3-09-0153	Expiration Date: 2/27/22	Case #: PF ID #: 823349
Company Name: Kichard E. Revson Miterials corp East Rockfill Twp Bucks Plant Name: Physical Location: Federal ID - Plant Code #:			
East Rockhill Quarry Same as below			
Responsible Official:		2105 N. Rockhill Rd.	
Title:		Sell-ersville, PA 18960	
Supervisor / Genera	Manager	Sell-ersville	, PAT 189160
Phone #(s): (209 - 743 - 7195			
Mark (X) All Inspection Types That Apply To This Inspection:			
Full Compliance Evaluation (FCE)	Plan Approval Inspection	1	File Review (FR)
Operating Permit Inspection (PI)	Initial Permit Inspection ((IPI)	Complaint Inspection (CI)
Routine/Partial (RTPT)	Follow-Up Inspection (Re	ef. Date:)	Sample Collection (SC)
Minor Source(s) Inspection (RFD)	Stack Test Observation		Multi-Media Inspection (MM)
Other:	Announced		• • •
Annual Compliance Certification Received: YES NO X N/A Date Received:			
AIMS Report Received: YES NO X N/A Date Received:			
Mark (X) All Activities That Apply:			
File Review	Pre-Inspection Briefing		X Exit Interview/Briefing
Pre-Inspection Observations	Check For New/Unreported Sources		Sample(s) Collected
Visible Emissions Observations	Verify Operation of CEMS		Other
Comments/Becommendations: Enforcement since last FCE Yes No (If yes, attach summary) Plan Barnhart mc arrivel on Site at 1130 pm 10 Conduct a routine/partial inspection, we met with Charlie Elwell who Showed us around the site, we observed that no additional construction had been brought on site and no additional construction had been conducted relating to the primary arusher, since my last site visit on 5/23/18, we also abserved the portable crushers which were in operation, we noted some sufficiency from the dust of the works, and shorthy afterwards the water track began spraying those areas down, the dust we observed was not significant, compliance status: In Out Pending Awaiting Co. Report Needs a Follow-Up Inspection? Yes No Company Representative: Charle Elwell Title: Signature: Dep Representative: Title: Signature: Dep Representative: Title: Signature: Determine to official notification that a representative of the Department of Environmental Proteotion, where works are official notification that a representative of the Department of Environmental Proteotion, where work of a signature: Dep Representative: The accurate of the provide work of the proved the definited site. The Indings of this inspection are shown above and on any attached pages, and way induced work will be forthcoming, if such violations are noted.			
Page of eFacts Inspection ID#: 2738984 Date: 017118 Reviewed By 5em			
White – Regional Office		llow – Site	Pink – District Office