2700-FM-BAQ0023 2/2015 pennsylvania DEPARTMENT OF ENVIRONMENTAL PROTECTION		INSPECTION REPORT			Commonwealth of Pennsylvania Department of Environmental Protection Air Quality Program	
Date(s) of Inspection: $TV \square PA \square GP \square GP \square MEGA \square$		Permit #(s); 1P9-09-0080 1P3-09-0153	Expiration $\mathcal{U} = \mathcal{U}$	n Date: 7 / A Q	Cas	- \$23349
Company Name: Richard E. Pierson Materials Corp East Ro Plant Name: Plant Name: Plant Name: Physical Location:				County: CKhill Tup BACKS Federal ID — Plant Code #:		
East Kockhill Quarry Same as below						
Responsible Official: Jrw Allen			Mailing Address: 2105 N. Arthill Rd.			
Title:			2105 N. Rakhill Rd. Sellersville, PA 18960			
Ditc Super Intendent			Senersville, 177 10100			
609-743-0350						
Mark (X) All Inspection Types That Apply To This Inspection:						
Full Compliance Evaluation (FCE)		Plan Approval Inspection				File Review (FR)
Operating Permit Inspection (PI)		Initial Permit Inspection (IPI)				Complaint Inspection (CI)
Routine/Partial (RTPT)		Follow-Up Inspection (Ref. Date:)				Sample Collection (SC)
Minor Source(s) Inspection (RFD)		Stack Test Observation				Multi-Media Inspection (MM)
Other:		Announced				
Annual Compliance Certification Received:	YE	YES INO N/A Date Received:				
AIMS Report Received: DYES NO X N/A Date Received				d:		
Mark (X) All Activities That Apply:						
File Review	Ø	Pre-Inspection Briefing			X	Exit Interview/Briefing
Pre-Inspection Observations	Ø	Check For New/Unreported Sources				Sample(s) Collected
Visible Emissions Observations		Verify Operation of CEMS				Other
Comments/Recommendations: I amiled on site at 12:55 pm to concuct a routine /partial						
Inspection, I met with Jim Allen who shaved me around						
the site. I observed that no additional equipment had been						
whyt on site and no additional contraction had been when a site and no additional contraction had been						
the portable crashers which were not M operation						
because they were being repaired; I was informed that they						
Stopped working as of vestercay. Asserved the water mek						
watering doubt the roads suring my inspection. I noted no						
malocors or significant amounts of dust while on site.						
Compliance Status: In I Out Pending Awaiting Co. R			eport Needs a Follow-Up Inspection? Yes No			
Company Representative: Title:			Signature: Date;			
James Allen	7	ite Supt		tans		ln 7/13/18
DEP Representative: Title: Signature: Date/Time:						Date/Time:
Jennifer Ramos-Buschmann AD Specialist				Jerrif Kamp-Geschnung 1113/18		
This document is official notification that a representative of the Department of Environmental Protection, Air Quality Program, inspected the identified site. The findings of this inspection are shown above and on any attached pages, and may include violations uncovered during the inspection. Violations may also be discovered upon review of sample results or from any additional review of Department records. Notification will be forthcoming, if such violations are noted.						
Page _ of _ eFacts Inspection ID#: 2751875 Date: 7/10/18 Reviewed By Sey						
_				ellow – Site		Pink – District Office