

1879114

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF MINING AND RECLAMATION

Page 1 of 1
Date 4/21/2010
On Site Times AM

Mine Name Rock Hill Quarry
Weather Clear 50 F

INSPECTION REPORT
NONCOAL

PERMITTEE Hanson Aggregates of Pa., Inc.	TOWNSHIP East Rockhill	COUNTY Bucks	PERMIT NO. 7974SM1
ADDRESS 2900 Terminal Ave. Richmond VA 23234 804-221-3781	VIOLATION HISTORY QNOV'S QCO'S	VIOLATIONS NOTED <input type="checkbox"/> FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> PREVIOUS VIOLATIONS: COMPLIANCE ORDER <input type="checkbox"/> CORRECTED <input type="checkbox"/> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/> UNCORRECTED <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/>	LICENSE NO. & EXP. DATE 1848 Pending OPERATIONAL STATUS Active

GENERAL MINING INFORMATION: Large Noncoal Small Noncoal Complete Partial or Followup
 a. Areas-Minerals-Pit Dimensions (L/W/H) – Method: Diabase Open Pit ~ 1500' (457m) x 900' (274m) x 250' (76m)
 b. Acreage (total): 103.3 (41.77ha) Bonded 103.2 Affected ~103 Regraded 0 Reclaimed 0
 c. Equipment-Use & Conditions: No equipment on site
 d. Contract Miner yes no e. Blasting at Site yes no (Explain yes answer) No recent blasting

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp.	Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp.	Date
X	700 Unauthorized Mining					NA	730 Concurrent Reclamation				
X	701 Signs and Markers					NA	731 Backfilling and Grading				
NA	702 Casing and Sealing Drilled Holes					NA	733 Covering Coal and Acid/Toxic Mat.				
X	703 Topsoil-Rem/Sto/Hning					NA	735 Revegetation				
X	704 Effluent Standard					NA	742 Permanent Mining Cessation				
NA	706 Diversions and Conveyance					X	743 Haul Roads/Restoration				
X	707 Sediment Control Measures					X	745 Support Facilities				
NA	708 Treatment Facilities					X	749 General Safety				
X	709 Sedimentation Ponds					X	753 Permit Conditions				
X	710 Discharge Structures					NA	754 Temporary Mining Cessation				
NA	711 Acid and Toxic Forming Spoil					NA	755 Closing Underground Mine Openings				
NA	712 Impoundments					X	756 Distance Limitations-Barriers				
NA	713 Dams, Ponds-Design/Const./Maint.					X	757 Bench				
NA	715 Water Monitoring-Ground/Surface					X	758 Permit Line Setback				
NA	717 Water Rights and Replacement					NA	759 Stability Analysis				
NA	718 Water Discharge-Underground Mine					NA	760 Post Mining Renovation				
X	723 Blasting Requirement					NA	761 Postmining Land Use				
X	727 Disposal of Solid Wastes					NA	762 Cleanup				
X	728 Air Resources Protection										

COMMENTS AND RECOMMENDATIONS: This complete inspection was conducted solo. The gate was unlocked. No activity was observed.

Violation History: None

Person Contacted None	Title	Discharge/Seeps <input type="checkbox"/> yes <input type="checkbox"/> no Samples Collected <input type="checkbox"/> yes <input type="checkbox"/> no Range of Samples Collected
Signature Mailed	Investigator Signature Amiee Bollinger <i>A Bollinger</i>	Sampler I.D. No. 4519 Employee #608058

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

District File / Permittee / Inspector