

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL PROTECTION  
BUREAU OF MINING AND RECLAMATION

Mine Name Rock Hill Quarry

INSPECTION REPORT  
NONCOAL

Date 4/25/01

Weather Overcast 50°

On Site Times AM

1024457

PERMITTEE <u>HANSON AGGREGATES OF PA. INC.</u> ADDRESS <u>1900 SULLIVAN TRAIL ERSON, PA. 18040</u>  <u>610-253-4271</u>	TOWNSHIP <u>EAST ROCK HILL</u>	COUNTY <u>BUCKS</u>	PERMIT NO. <u>7974SM1</u>
VIOLATION HISTORY 0 NOV'S 0 CO'S	VIOLATIONS NOTED <input type="checkbox"/> FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> PREVIOUS VIOLATIONS: COMPLIANCE ORDER <input type="checkbox"/> CORRECTED <input type="checkbox"/> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/> UNCORRECTED <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/>	LICENSE NO. & EXP. DATE <u>3-00679 (1845) 9/30/01</u>	OPERATIONAL STATUS <u>ACTIVE</u>

GENERAL MINING INFORMATION: Large Noncoal  Small Noncoal \_\_\_\_\_ Complete  Partial or Followup \_\_\_\_\_

a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: DIA BASE - OPEN PIT  
N 1500' (457m) x 900' (274m) x 250' (76m) 5 LEVELS  
1033 (41.77ha)

b. Acreage (total): 1 Bonded 103.2 Affected ~ 103 Regraded 0 Reclaimed 0

c. Equipment-Use & Conditions:

d. Contract Miner  yes  no e. Blasting at Site  yes  no (Explain yes answers) NO RECENT BLASTING

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	700 Unauthorized Mining				<u>NA</u>	730 Concurrent Reclamation			
<input checked="" type="checkbox"/>	701 Signs and Markers				<input checked="" type="checkbox"/>	731 Backfilling and Grading			
<u>NA</u>	702 Casing and Sealing Drilled Holes				<input checked="" type="checkbox"/>	733 Covering Coal and Acid/Toxic Mat.			
<u>NA</u>	703 Topsoil-Rem/Sto/Hndlng				<input checked="" type="checkbox"/>	735 Revegetation			
<input checked="" type="checkbox"/>	704 Effluent Standard				<input checked="" type="checkbox"/>	742 Permanent Mining Cessation			
<u>NA</u>	706 Diversions and Conveyance				<input checked="" type="checkbox"/>	743 Haul Roads/Restoration			
<input checked="" type="checkbox"/>	707 Sediment Control Measures				<input checked="" type="checkbox"/>	745 Support Facilities			
<u>NA</u>	708 Treatment Facilities				<input checked="" type="checkbox"/>	749 General Safety			
<input checked="" type="checkbox"/>	709 Sedimentation Ponds				<input checked="" type="checkbox"/>	753 Permit Conditions			
<input checked="" type="checkbox"/>	710 Discharge Structures				<u>NA</u>	754 Temporary Mining Cessation			
<u>NA</u>	711 Acid and Toxic Forming Spoil				<u>NA</u>	755 Closing Underground Mine Openings			
<input checked="" type="checkbox"/>	712 Impoundments				<input checked="" type="checkbox"/>	756 Distance Limitations-Barriers			
<input checked="" type="checkbox"/>	713 Dams, Ponds-Design/Const./Maint.				<input checked="" type="checkbox"/>	757 Bench Development			
<input checked="" type="checkbox"/>	715 Water Monitoring-Ground/Surface				<input checked="" type="checkbox"/>	758 Permit Line Setback			
<input checked="" type="checkbox"/>	717 Water Rights and Replacement				<u>NA</u>	759 Stability Analysis			
<input checked="" type="checkbox"/>	718 Water Discharge-Underground Mine				<input checked="" type="checkbox"/>	760 Post Mining Renovation			
<input checked="" type="checkbox"/>	723 Blasting Requirement				<input checked="" type="checkbox"/>	761 Postmining Land Use			
<input checked="" type="checkbox"/>	727 Disposal of Solid Wastes				<input checked="" type="checkbox"/>	762 Cleanup			
<input checked="" type="checkbox"/>	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: THIS INSPECTION CONDUCTED "SOLO"

VIOLATION HISTORY - NO VIOLATION 2 YEARS

Person Contacted <u>NONE</u>	Title 	Discharge/Seeps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Samples Collected <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Range of Samples Collected _____ to _____
Signature <u>MAILED</u>	Investigator Signature & I.D. No. <u>149238</u> <u>Darryl Watten</u>	4 5 3 2

**COMMENTS AND RECOMMENDATIONS**

Mine Name ROCK HILL QUARRY

Date 4/25/01

PERMITTEE <u>HANSON AGGREGATES</u>	TOWNSHIP <u>EAST ROCKHILL</u>	COUNTY <u>BUCKS</u>	PERMIT NO. <u>7974SM1</u>
(1) ETS CONTROLS SHOULD BE UPGRADED - WATER IS FLOWING FROM THE PIT, PAST THE CRUSHER AND DOWN THE ROADS TOWARD THE ENTRANCE TO THE SITE. AT THIS POINT, THE WATER INFILTRATES, ALL OF THIS WATER IS BYPASSING THE SED CONTROL MEASURES, THIS CONDITION SHOULD BE CORRECTED ASAP.			
(2) NO ACTIVITY ON SITE ON THIS DATE - NO SIGN OF RECENT ACTIVITY			
(3) ID SIGN IS AT THE ENTRANCE TO THE SITE, BUT HAS AGAIN BEEN KNOCKED DOWN OR BLOWN OVER, OPERATOR SHOULD TAKE STEPS TO INSURE THE SIGN IS SECURELY FASTENED.			
(4) GATE WAS OPEN - LOCK MISSING			
(Empty rows for additional comments)			
Person Contacted <u>NONE</u>	Title _____		
Signature <u>MAILED</u>	Investigator Signature & I.D. No. <u>149238</u> <u>Davey Watten</u>		

4 5 3 2