

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

Date 4-5-96

Mine Name Rock Hill
Weather Snow Covered

INSPECTION REPORT
NONCOAL

Site Times AM 11:11

PERMITTEE <u>The Mineral Creek Steepway</u>	TOWNSHIP <u>E. Abck Hill</u>	COUNTY <u>Bucks</u>	PERMIT NO. <u>79475 M3</u>
ADDRESS <u>P.O. Box 201 Easton PA 18042</u>	VIOLETION HISTORY <u>NOV'S</u> <u>CO'S</u>	VIOLETIONS NOTED PREVIOUS VIOLATIONS: CORRECTED <input type="checkbox"/> UNCORRECTED <input type="checkbox"/>	FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> COMPLIANCE ORDER <input type="checkbox"/> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/>
GENERAL MINING INFORMATION: Large Noncoal <input checked="" type="checkbox"/> Small Noncoal <input type="checkbox"/> Complete <input checked="" type="checkbox"/> Partial or Followup <input type="checkbox"/>		LICENSE NO. & EXP. DATE <u>3013-7201-96</u>	
a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: <u>1500 x 900 x 250-5 LPTS</u> <u>S F P</u>		OPERATIONAL STATUS <u>ACTIVE</u>	

b. Acreage (total): Bonded 104 Affected ALL Regraded _____ Reclaimed _____

c. Equipment-Use & Conditions: SAME

d. Contract Miner yes no a. Blasting at Site yes no (Explain yes answers) NO

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	700 Unauthorized Mining					730 Concurrent Reclamation			
	701 Signs and Markers					731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat			
	703 Topsoil Rem/Stor/Handling					736 Revegetation			
	704 Effluent Standard					742 Permanent Mining Cessation			
	706 Diversions and Conveyance					743 Haul Roads/Restoration			
<input checked="" type="checkbox"/>	707 Sediment Control Measures				<input checked="" type="checkbox"/>	745 Support Facilities			
	708 Treatment Facilities				<input checked="" type="checkbox"/>	749 General Safety			
	709 Sedimentation Ponds				<input checked="" type="checkbox"/>	753 Permit Conditions			
	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Forming Spoil					755 Closing Underground Mine Openings			
	712 Impoundments					756 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const/Maint.					757 Bench Development			
	715 Water Monitoring-Ground/Surface					758 Permit Line Setback			
	717 Water Rights and Replacement					759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
<input checked="" type="checkbox"/>	723 Blasting Requirement					761 Postmining Land Use			
<input checked="" type="checkbox"/>	727 Disposal of Solid Wastes				<input checked="" type="checkbox"/>	762 Cleanup			
<input checked="" type="checkbox"/>	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS:
NO ONE ON SITE
ENTRANCE ROAD COVERED BY OVER 6" OF UNMELTED SNOW

Person Contacted <u>Jaggy M.</u>	Title	Discharge/Sneeps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
Signature <u>Jones Carpenter</u>		Samples Collected <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
		Range of Samples Collected _____ to _____
		Investigator Signature & I.D. No. <u>Jones Carpenter</u> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the Investigator. The signature does not necessarily mean he agrees with the report.