

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

Mine Name ROCK HILL
Weather Sunny

INSPECTION REPORT
NONCOAL

Date 8-23-92

On Site Times AM

PERMITTEE <u>The General Cracked Stone Co</u>	TOWNSHIP <u>E. ROCKHILL</u>	COUNTY <u>BUCKS</u>	PERMIT NO. <u>79745M3</u>
ADDRESS <u>P.O. Box 231 1689 SULLIVAN TRAIL EASTON PA - 18042</u>	VIOLETION HISTORY <u>NOV'S</u> <u>CO'S</u>	VIOLETIONS NOTED <input type="checkbox"/> PREVIOUS VIOLATIONS: CORRECTED <input type="checkbox"/> UNCORRECTED <input type="checkbox"/>	FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> COMPLIANCE ORDER <input type="checkbox"/> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/>
GENERAL MINING INFORMATION: Large Noncoal <input checked="" type="checkbox"/> Small Noncoal <input type="checkbox"/> Complete <input checked="" type="checkbox"/> Partial or Followup <input type="checkbox"/>		LICENSE NO. & EXP. DATE <u>733-12-31-92</u>	
a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: <u>1500' x 900' x 250'</u> <u>OPEN PIT QUARRY</u>		OPERATIONAL STATUS <u>ACTIVE</u>	

b. Acreage (total): Bonded 103.2 Affected 103.2 Regraded Reclaimed

c. Equipment-Use & Conditions: FEL

d. Contract Miner yes no e. Blasting at Site yes no (Explain yes answers) NONE

PERFORMANCE STANDARDS NONCOAL									
Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	700 Unauthorized Mining					730 Concurrent Reclamation			
<input checked="" type="checkbox"/>	701 Signs and Markers					731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat			
	703 Topsoil-Rem/Sto/Hndng					735 Revegetation			
	704 Effluent Standard					742 Permanent Mining Cessation			
<input checked="" type="checkbox"/>	706 Diversions and Conveyance					743 Haul Roads/Restoration			
	707 Sediment Control Measures					<input checked="" type="checkbox"/> 745 Support Facilities			
	708 Treatment Facilities					<input checked="" type="checkbox"/> 749 General Safety			
<input checked="" type="checkbox"/>	709 Sedimentation Ponds					<input checked="" type="checkbox"/> 753 Permit Conditions			
	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Forming Spoil					755 Closing Underground Mine Openings			
	712 Impoundments					756 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const/Maint.					757 Bench Development			
	715 Water Monitoring-Ground/Surface					758 Permit Line Setback			
	717 Water Rights and Replacement					759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
<input checked="" type="checkbox"/>	723 Blasting Requirement					761 Postmining Land Use			
<input checked="" type="checkbox"/>	727 Disposal of Solid Wastes				<input checked="" type="checkbox"/>	762 Cleanup			
<input checked="" type="checkbox"/>	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: Water at 147' level -
NO SVE- Problem
Over 500 TONS Shipped This year
NO Problem Observed

Person Contacted <u>Brian Ladage</u>	Title <u>Estimator</u>	Discharge/Seeps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
Signature <u>[Signature]</u>	Investigator Signature & I.D. No. <u>James Cooper</u>	Range of Samples Collected _____ to _____

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.