

1195296

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF MINING AND RECLAMATION

Mine Name Rock Hill Quarry

INSPECTION REPORT
NONCOAL

Date 12/16/02

Weather _____

On Site Times _____

PERMITTEE <u>Hanson Aggregates of Pennsylvania Inc.</u>	TOWNSHIP <u>East Rock Hill</u>	COUNTY <u>Bucks</u>	PERMIT NO. <u>79745M1</u>
ADDRESS <u>1900 Sullivan Trail Easton Pa 18040 610-253-4271</u>	VIOLATIONS NOTED <input type="checkbox"/> FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> PREVIOUS VIOLATIONS: COMPLIANCE ORDER <input type="checkbox"/> NOV'S CORRECTED <input type="checkbox"/> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/> CO'S UNCORRECTED <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/>		LICENSE NO. & EXP. DATE <u>1848 9/30/03</u>
			OPERATIONAL STATUS <u>Active</u>

GENERAL MINING INFORMATION: Large Noncoal X Small Noncoal _____ Complete X Partial or Followup _____

a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: Dabase OPEN Pit ~1500' X 900' X 250'

b. Acreage (total): Bonded 103.2 Affected ~103 Regraded 0 Reclaimed 0

c. Equipment-Use & Conditions: None

d. Contract Miner yes no e. Blasting at Site yes no (Explain yes answers)

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<u>N/A</u>	700 Unauthorized Mining				<u>N/A</u>	730 Concurrent Reclamation			
<u>1</u>	701 Signs and Markers				<u>1</u>	731 Backfilling and Grading			
<u>N/A</u>	702 Casing and Sealing Drilled Holes				<u>1</u>	733 Covering Coal and Acid/Toxic Mat.			
<u>1</u>	703 Topsoil-Rem/Sto/Hndng				<u>1</u>	735 Revegetation			
<u>1</u>	704 Effluent Standard				<u>1</u>	742 Permanent Mining Cessation			
<u>N/A</u>	706 Diversions and Conveyance				<u>1</u>	743 Haul Roads/Restoration			
<u>1</u>	707 Sediment Control Measures				<u>1</u>	745 Support Facilities			
<u>N/A</u>	708 Treatment Facilities				<u>1</u>	749 General Safety			
<u>1</u>	709 Sedimentation Ponds				<u>1</u>	753 Permit Conditions			
<u>1</u>	710 Discharge Structures				<u>N/A</u>	754 Temporary Mining Cessation			
<u>N/A</u>	711 Acid and Toxic Forming Spoil				<u>1</u>	755 Closing Underground Mine Openings			
<u>1</u>	712 Impoundments				<u>1</u>	756 Distance Limitations-Barriers			
<u>1</u>	713 Dams, Ponds-Design/Const./Maint.				<u>1</u>	757 Bench Development			
<u>1</u>	715 Water Monitoring-Ground/Surface				<u>1</u>	758 Permit Line Setback			
<u>N/A</u>	717 Water Rights and Replacement				<u>N/A</u>	759 Stability Analysis			
<u>1</u>	718 Water Discharge-Underground Mine				<u>1</u>	760 Post Mining Renovation			
<u>1</u>	723 Blasting Requirement				<u>1</u>	761 Postmining Land Use			
<u>1</u>	727 Disposal of Solid Wastes				<u>1</u>	762 Cleanup			
<u>1</u>	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS:

Person Contacted _____ Title _____	Discharge/Seeps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Samples Collected <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Range of Samples Collected <u>0</u> to _____
Signature <u>Mailed</u>	Investigator Signature & I.D. No. <u>Emp # 411545</u> <u>Joseph P. McCarty</u> 4 5 1 2

COMMENTS AND RECOMMENDATIONS

Mine Name _____

Date 12/16/02

PERMITTEE	TOWNSHIP	COUNTY	PERMIT NO.
Hanson Aggregates of PA	East Rock Hill	Bucks	79745m

Mining operations at this permit remains idle. The operator notified the Pottsville District office that they were going to remove the required 500 tons of material from the site. At the time of this inspection it does appear that work was conducted along the Western edge of the site.

The operator is advised that the T.D sign has been removed from the wooden frame and will need to be replaced. The sign should be visible from the public roadway.

No E&S control problems noted and there was no discharge from monitoring point del. (NPAES # PA0594121 expires 7/19/03)

Violation history: None

Person Contacted	Title	Investigator Signature & I.D. No.
		Joseph McLaughlin
Signature		4 5 1 2

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.