

Commonwealth of Pennsylvania

DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF SURFACE MINE RECLAMATION
INSPECTION
REPORT

Mini mit No. 733-5
Drainage Permit No. 7974SM1
Mine Inspection No. 54
Reinspection No. 1-83

Company <u>General Crushed Stone Co</u>		Mine Location: County <u>Bucks</u>	Township <u>E Rockhill</u>
Mining Permit Acres Affected <u>95</u>		Drainage Permit Acres Affected	
Status of Operation: Active	Inactive <u>X</u>	Not Started	

- 1. Is this operation in compliance with the Safety Rules and Regulations? YES X NO NOTED
- 2. Is this mine operating in compliance with the conditions of the mining permit? YES X NO NOTED
- 3. Is the mine operating in compliance with the conditions of the mine drainage permit? YES X NO NOTED

REMARKS AND RECOMMENDATIONS:

Quarry closed LACK of BUSINESS -
STONE REMAINING IN STOCK NOT BEING SOLD
AT PRESENT -

License # supplied from MAIN OFFICE

DYNAMITE STORAGE #1617
Cap STORAGE #1616
Licenses to Purchase #1770

Company Official Contacted <u>Joseph P. Binner Jr</u>	Title <u>Office Manager, Contractor</u>
Mine Inspector <u>James Carpenter</u>	Inspection Date <u>2-16-83</u>

INSPECTORS' RECOMMENDATIONS TO BUREAU:

5-5A-5A2 ALL Closed