

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

Date 2-3-95

Mine Name ROCK HILL
Weather SUNNY

INSPECTION REPORT:
NONCOAL

On-Site Times: 1 hr

PERMITTEE <u>The General Crushed Stone Co.</u>	TOWNSHIP <u>E. ROCKHILL</u>	COUNTY <u>BUCKS</u>	PERMIT NO. <u>79745M1</u>
ADDRESS <u>PO BOX 231 1609 SULLIVAN TRAIL EASTON, PA 18042</u>	VIOLETION HISTORY <u>NOV'S</u> <u>CO'S</u>	VIOLETIONS NOTED <input type="checkbox"/> FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> PREVIOUS VIOLATIONS: COMPLIANCE ORDER <input type="checkbox"/> <u>306</u> CORRECTED <input type="checkbox"/> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/> UNCORRECTED <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/>	LICENSE NO. & EXP. DATE <u>833-72-31-93</u> OPERATIONAL STATUS <u>ACTIVE</u>

GENERAL MINING INFORMATION: Large Noncoal Small Noncoal Complete Partial or Followup

a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: 1500x900x250-5 LIFTS
OPEN PIT QUARRY

b. Acreage (total): Bonded 104.2 Affected ALL Regraded 0 Reclaimed 0

c. Equipment-Use & Conditions: SAME

d. Contract Miner yes no e. Blasting at Site yes no (Explain yes answers) NONE

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	700 Unauthorized Mining					730 Concurrent Reclamation			
	701 Signs and Markers					731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat			
	703 Topsoil-Rem/Sto/Handing					735 Revegetation			
	704 Effluent Standard					742 Permanent Mining Cessation			
	706 Diversions and Conveyance					743 Haul Roads/Restoration			
	707 Sediment Control Measures					745 Support Facilities			
	708 Treatment Facilities					749 General Safety			
	709 Sedimentation Ponds					753 Permit Conditions			
	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Forming Spoil					756 Closing Underground Mine Openings			
	712 Impoundments					758 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const/Maint.					757 Bench Development			
	715 Water Monitoring-Ground/Surface					758 Permit Line Setback			
	717 Water Rights and Replacement					759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
	723 Blasting Requirement					761 Postmining Land Use			
	727 Disposal of Solid Wastes					762 Cleanup			
	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: GATE LOCKED AT R.R.

NO ONE ON SITE

TRUCKS & CONS. EQUIPMENT PARKED OFF (20)

Person Contacted <u>FILE</u>	Title	Discharge/Seeps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no	Samples Collected <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
Signature <u>Copy</u>		Range of Samples Collected _____ to _____	Investigator Signature & I.D. No. <u>Lanas Carpenter</u> 4506

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the Investigator. The signature does not necessarily mean he agrees with the report.