

1942430

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL PROTECTION  
BUREAU OF MINING AND RECLAMATION

Page 1 of 1  
Date 1/11/2011  
On Site Times PM

Mine Name Rock Hill Quarry  
Weather Overcast 25 F

**INSPECTION REPORT**  
**NONCOAL**

|  |  |  |  |
|--|--|--|--|
| PERMITTEE<br>Hanson Aggregates of Pa., Inc.                        | TOWNSHIP<br>East Rockhill              | COUNTY<br>Bucks  | PERMIT NO.<br>7974SM1  |
| ADDRESS<br>7660 Imperial Way<br>Allentown PA 18195<br>610-366-4828 | VIOLATION HISTORY<br>0 NOV'S<br>0 CO'S | VIOLATIONS NOTED <input type="checkbox"/> FOLLOW-UP INSP. REQUIRED <input type="checkbox"/><br>PREVIOUS VIOLATIONS: COMPLIANCE ORDER <input type="checkbox"/><br>CORRECTED <input type="checkbox"/> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/><br>UNCORRECTED <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/> | LICENSE NO. & EXP. DATE<br>24143 Pending<br>OPERATIONAL STATUS<br>Active |


**GENERAL MINING INFORMATION:** Large Noncoal  Small Noncoal  Complete  Partial or Followup   
 a. Areas-Minerals-Pit Dimensions (L/W/H) – Method: Diabase Open Pit ~ 1500' (457m) x 900' (274m) x 250' (76m)  
 b. Acreage (total): 103.3 (41.77ha) Bonded 103.2 Affected ~103 Regraded 0 Reclaimed 0  
 c. Equipment-Use & Conditions: No equipment on site  
 d. Contract Miner  yes  no e. Blasting at Site  yes  no (Explain yes answer) No recent blasting

**PERFORMANCE STANDARDS NONCOAL**

| Obs. | STANDARD                             | PC or Reg. | Viol. | Comp. Date | Obs. | STANDARD                              | PC or Reg. | Viol. | Comp. Date |
|------|--------------------------------------|------------|-------|------------|------|---------------------------------------|------------|-------|------------|
| X    | 700 Unauthorized Mining              |            |       |            | NA   | 730 Concurrent Reclamation            |            |       |            |
| X    | 701 Signs and Markers                |            |       |            | NA   | 731 Backfilling and Grading           |            |       |            |
| NA   | 702 Casing and Sealing Drilled Holes |            |       |            | NA   | 733 Covering Coal and Acid/Toxic Mat. |            |       |            |
| X    | 703 Topsoil-Rem/Sto/Hning            |            |       |            | NA   | 735 Revegetation                      |            |       |            |
| X    | 704 Effluent Standard                |            |       |            | NA   | 742 Permanent Mining Cessation        |            |       |            |
| NA   | 706 Diversions and Conveyance        |            |       |            | X    | 743 Haul Roads/Restoration            |            |       |            |
| X    | 707 Sediment Control Measures        |            |       |            | X    | 745 Support Facilities                |            |       |            |
| NA   | 708 Treatment Facilities             |            |       |            | X    | 749 General Safety                    |            |       |            |
| X    | 709 Sedimentation Ponds              |            |       |            | X    | 753 Permit Conditions                 |            |       |            |
| X    | 710 Discharge Structures             |            |       |            | NA   | 754 Temporary Mining Cessation        |            |       |            |
| NA   | 711 Acid and Toxic Forming Spoil     |            |       |            | NA   | 755 Closing Underground Mine Openings |            |       |            |
| NA   | 712 Impoundments                     |            |       |            | X    | 756 Distance Limitations-Barriers     |            |       |            |
| NA   | 713 Dams, Ponds-Design/Const./Maint. |            |       |            | X    | 757 Bench                             |            |       |            |
| NA   | 715 Water Monitoring-Ground/Surface  |            |       |            | X    | 758 Permit Line Setback               |            |       |            |
| NA   | 717 Water Rights and Replacement     |            |       |            | NA   | 759 Stability Analysis                |            |       |            |
| NA   | 718 Water Discharge-Underground Mine |            |       |            | NA   | 760 Post Mining Renovation            |            |       |            |
| X    | 723 Blasting Requirement             |            |       |            | NA   | 761 Postmining Land Use               |            |       |            |
| X    | 727 Disposal of Solid Wastes         |            |       |            | NA   | 762 Cleanup                           |            |       |            |
| X    | 728 Air Resources Protection         |            |       |            |      |                                       |            |       |            |

COMMENTS AND RECOMMENDATIONS: This complete inspection was conducted solo. The gate was locked. No activity was observed.

Violation History: None

|                          |   |  |
|--------------------------|---|--|
| Person Contacted<br>None | Title   | Discharge/Seeps <input type="checkbox"/> yes <input type="checkbox"/> no<br>Samples Collected <input type="checkbox"/> yes <input type="checkbox"/> no<br>Range of Samples Collected |
| Signature<br>Mailed      | Investigator Signature<br>Amiee Bollinger  | Sampler I.D. No. 4519<br>Employee #608058  |

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

**District File / Permittee / Inspector**