

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

OFFICIAL USE ONLY

INSPECTION REPORT

Date 7-18-89

PERMITTEE <u>The General Crushed Stone Company</u>	TOWNSHIP <u>Et. Rockhill</u>	COUNTY <u>BUCKS</u>	PERMIT NO. <u>79745MJ</u>
ADDRESS <u>P.O. BOX 231 1609 SULLIVAN TRAIL EASTON, PA. 18042 215-253-4271</u>	TYPE OF INSPECTION Partial <input type="checkbox"/> Followup <input type="checkbox"/> Complete <input checked="" type="checkbox"/>	STATUS Violation/s Noted <input type="checkbox"/> Issue Order <input type="checkbox"/> Cease Order Issued <input type="checkbox"/> Previous Violations not corrected <input type="checkbox"/>	LICENSE NO. <u>300733</u> Valid Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Expiration Date <u>12-31-89</u> Operational Status <u>ACTIVE</u>

A1. GENERAL MINING INFORMATION

- a. Seams DIABASE
- b. Highwall/s height/s: actual 750' - 5 LEVELS
bonded 104700
- c. Length & Width of cut/s 1500' x 975'
- d. Total Acres: Permitted 103.2 (103.2) Affected ALL Regraded 0 Reclaimed 0
- e. Phase/s being mined: NONE

Unauthorized Mining _____ Acres Unauthorized Mining Activities _____ Acres

2. Method of Mining: OPEN PIT QUARRIES

3. Equipment: Use & Condition FEL

4. Contract Miner yes no Name: _____ Address: _____

5. Blasting at Site: yes no Blaster's Name _____ License No. _____
Contract Blaster yes no Contractors name _____

6. Auger Permit Safety Permit No. _____
 yes no Active Inactive not started completed

7. Refuse Disposal Approved yes no Active (describe) Inactive

8. Previous Enforcement:

- a. Orders & Agreements outstanding yes no Type _____
- b. Adjudications Outstanding yes no Type _____
- c. Violations on Last Inspection yes no (If yes, explain status in remarks)

Person contacted <u>RICHARD H FRANK</u> <u>Joseph Bronigo</u> Signature <u>Richard H Frank</u>	Title <u>CONS MGR</u> <u>off mgr</u>	Discharges/Seeps: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Samples collected: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no No. of samples collected _____ ER-MR-5.2 attached.
Investigator <u>James Carpenter</u> Signature		<u>45720</u> I.D. No.

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMENTS AND RECOMMENDATIONS

Mine Name _____

Date 7-18-89

PERMITTEE <i>The General Crushed Stone Company</i>	TOWNSHIP <i>E. Rockhill</i>	COUNTY <i>BUCKS</i>	PERMIT NO. <i>1974 SM1</i>
---	------------------------------------	----------------------------	-----------------------------------

PLANT HAS NOT WORKED for years - There has been NO BLASTING AT THIS SITE

Operator Removes 500 TON of STOCKED MATERIAL A YEAR TO KEEP PERMIT ACTIVE.

F.E.L ON SITE -

IN The opinion of INSPECTOR WATER level HAS ROSE app 5' from LAST INSP. NOW IT IS app 140' deep

I FOUND NO STE PROBLEM

ID SIGN posted

Operator advised of TRAIL BIKES & HORSE BACK RIDERS ON SITE. THIS IS A DANGEROUS CONDITION -

Person Contacted	Title
------------------	-------

Signature *Richard H Frank 7/18/89*

Investigator Signature & I.D. No. *Janas Carpenter* 4 5 0 6

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.