

Commonwealth of Pennsylvania

DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF SURFACE MINE RECLAMATION
INSPECTION
REPORT

W

Mini- mit No. 956-1
Drainage Permit No. 7974 SM 1
Mine Inspection No. 54
Reinspection No. 3-82

Company <u>Bucks County Crushed Stone</u>	Mine Location: County <u>Bucks</u>	Township <u>NOCKAMICON</u>
Mining Permit Acres Affected <u>10</u>	Drainage Permit Acres Affected <u>10</u>	
Status of Operation: Active <input checked="" type="checkbox"/>	Inactive <input type="checkbox"/>	Not Started <input type="checkbox"/>

1. Is this operation in compliance with the Safety Rules and Regulations? YES NO NOTED
2. Is this mine operating in compliance with the conditions of the mining permit? YES NO NOTED
3. Is the mine operating in compliance with the conditions of the mine drainage permit? YES NO NOTED

REMARKS AND RECOMMENDATIONS:

Plant Down for repairs

PIT sump clear - NO SAMPLE TAKEN

I FOUND NO STE PROBLEMS. AT THIS TIME

OPERATOR GIVEN 30 DAYS TO FLAG Banded

Area

Company Official Contacted <u>B. Schol Pr.</u>	Title <u>Pr.</u>
Mine Inspector <u>Janas Carpenter</u>	Inspection Date <u>7-21-82</u>

INSPECTORS' RECOMMENDATIONS TO BUREAU:

with check of flagging in 30 days