

Commonwealth of Pennsylvania

DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF SURFACE MINE RECLAMATION
INSPECTION
REPORT

A
P

Mine No. 733-5
Drainage Permit No. 7974SM1
Mine Inspection No. 54
Reinspection No. 3-83

Company <u>General Crushed Stone</u>	Mine Location: County <u>BUCKS</u>	Township <u>E. Rockhill</u>
Mining Permit Acres Affected <u>95-3-5.2</u>	Drainage Permit Acres Affected	
Status of Operation: Active <u>X</u>	Inactive <u>X</u>	Not Started

1. Is this operation in compliance with the Safety Rules and Regulations? YES X NO NOTED
2. Is this mine operating in compliance with the conditions of the mining permit? YES X NO NOTED
3. Is the mine operating in compliance with the conditions of the mine drainage permit? YES X NO NOTED

REMARKS AND RECOMMENDATIONS: WATER IN PIT Sump Covers
BOTTOM level-

I FOUND NO S+E Problems

ASPHALT PLANT Removed.

STONE ON STOCKPILES

Office Mgr. only one on site

Company Official Contacted <u>Joseph P. Bunker</u>	Title <u>Office Manager</u>
Mine Inspector <u>Jonas Carpenter</u>	Inspection Date <u>6-21-83</u>

INSPECTORS' RECOMMENDATIONS TO BUREAU:

none