2583078

5600-FM-BMP0491 10/2014 pennsylvania perantment of environmental protection

COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF MINING PROGRAMS

Page 1 of <u>1</u>

Date 3/24/2017

On Site Times <u>0945 - 1000</u>

☐ Pink - Inspector

Mine Name <u>Rock Hill Quarry</u> Weather <u>Overcast</u> 34F

☐ White - District File

NPDES INSPECTION REPORT

PERMITTEE Hanson Aggregates Pennsylvania,		TOWNSHIP East Rockhill	TOWNSHIP East Rockhill			COUNTY Bucks		MINING PERMIT NO. 7974SM1		
ADDRESS 7660 Imperial Way Allentown PA 18195		PREVIOUS VI	PREVIOUS VIOLATIONS:			☐ FOLLOW-UP INSP. REQUIRED ☐ NOTICE OF VIOLATION ☐ COMPLIANCE ORDER ☐ FTC ORDER: ☐ CEASE ORDER		NPDES PERMIT NO. PA0594121 EXPIRATION DATE 7/19/2018		
				SITE R	REVIEW					
OUTFAL 001	TYPE ☐ Sediment ☐ Treatm	DISCHAR		SAMPLED?	OUTFA	☐ Sediment ☐ Trea	atment [ISCHARGIN	o Yes No	
-	☐ Sediment ☐ Treatm ☐ Sediment ☐ Treatm ☐ Sediment ☐ Treatm	ment Yes No Yes No		☐ Sediment ☐ Treatm ☐ Sediment ☐ Treatm ☐ Sediment ☐ Treatm		atment [ent Yes No Yes No ent Yes No			
	Sediment Treatm	nent Yes [Yes No Yes No		☐ Sediment ☐ Treatm☐ Sediment ☐ Sediment ☐ Treatm☐ Sediment ☐ Sedim		atment	ent ☐ Yes ☐ No ☐ Yes ☐ No		
Sediment Treatment Yes No Yes No Sediment Treatment Yes No Yes No Non-discharge alternatives required by permit? Yes No If so, have they been implemented? Yes No Are they functioning? Yes No Are stormwater BMPs required by NPDES? Yes No If so, are they installed and functioning correctly? Yes No N/A										
Discharge Monitoring Report Review										
Quarter Reviewed: 4 Self-Reported Violations? Yes No Violations not reported? Yes No										
Was a DMR included for every outfall? ☑ Yes ☐ No. If no, which outfalls were missing:										
Are any of the outfalls indicated as having no discharge? Yes No Were the DMRs signed? Yes No										
			,	DES COMPLIA			50 5		- Comp Data	
Obs.	STANDARD Treatment pond 2-year	PC or REg.	Vioi.	Comp. Date	Obs.	STANDARD	PC or RE		•	
	Effluent Characterization sampling Requirement Stormwater 2-year Effluent	40 CFR 122.21(k)(5)(vi)			⊠	NPDES Permit Requirements	92a.41(a			
	Characterization sampling Requirement	40 CFR 122.26(c)(1)(i)(G)				Failure to Report NPDES Non-Compliance Failure to Submit DMR	92a.41			
☒	Reporting Requirements	40 CFR 122.41(I)				Data	92a.61(NPDES Pe	it]	
⋈	PPC Plan	Standard Cond 4				Implementation of E & S Plan Requirements	Condition]	
COMMENTS AND RECOMMENDATIONS: Water was not discharging.										
Person Contacted Title None					│ 🔯 Cor	Inspection Done: ☐ Complete ☐ Partial ☐ Date: 3/24/2017 Employee ID No. 608058				
Invest							E-m	aniovaa II	IND BUXUSX	
""	igator Signature						L-11	ipioyee in	110. 00000	

☐ Yellow - Permittee