

2720487



COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF MINING PROGRAMS

INSPECTION REPORT
NONCOAL

Date: 3/5/2018

Mine Name Rock Hill Quarry

Weather Clear 37 F

Complete Partial

On Site Times 0902 - 1117

PERMITTEE Hanson Aggregates Pennsylvania, LLC	TOWNSHIP East Rockhill	COUNTY Bucks	PERMIT NO. 7974SM1
ADDRESS: 7660 Imperial Way Allentown PA 18195	VIOULATION HISTORY 0 NOV'S 0 CO'S	<input type="checkbox"/> VIOLATIONS NOTED PREVIOUS VIOLATIONS: <input type="checkbox"/> CORRECTED <input type="checkbox"/> UNCORRECTED	<input type="checkbox"/> FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> COMPLIANCE ORDER <input type="checkbox"/> FTC ORDER <input type="checkbox"/> CEASE ORDER
GENERAL MINING INFORMATON: Large <input checked="" type="checkbox"/> Small 10,000 <input type="checkbox"/> 2,000 <input type="checkbox"/> GP 105 <input type="checkbox"/> GP 103 <input type="checkbox"/> Expiration Date:		LICENSE NO. & EXP. DATE 24143 12/31/2018	
OPERATIONAL STATUS Active			
a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: Argillite open pit- water filled pit- ~1500' x ~900' x ~250'			
b. Equipment-Use & Conditions: portable crushers; FELs; track excavators; grader; haul trucks - good condition			
c. Contract Miner: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Name: R. E. Pierson		d. Approved Blast Plan: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Is there blasting today? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
Approved Acres	Approved Pit Volume	Progress of Reclamation	Liability
Mining Area: 103.2 Support:	yd ³	Regraded acres Topsoiled acres	Current Bond
Disturbed not planted:	Current Pit Volume	Water Impoundment : Acres Approved Acres Actual	\$ 203,400
Affected acres	yd ³	Planted, Grasses acres	Current Liability
Mining Area: 103.2 Support:	Selective Grading of Highwall	Trees Required ac. Planted ac.	\$
Disturbed not planted:	Approved: yd ³ Current:	Meeting Stage 1 criteria: acres	
Highwall Bond (Blasting to achieve reclamation) Approved/Affected			
<20 ft.:	ft.	ft.	>20<30 ft. ft. ft.
			>30<40 ft. ft. ft.
			>40<50 ft. ft. ft.
			>50 ft. ft. ft.

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	Unauthorized Mining		<input type="checkbox"/>		<input checked="" type="checkbox"/>	Air Resources Protection		<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Mining License		<input type="checkbox"/>		<input type="checkbox"/>	Concurrent Reclamation		<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Signs and Markers		<input type="checkbox"/>		<input type="checkbox"/>	Backfilling and Grading		<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Topsoil-Rem/Storage/Handling		<input type="checkbox"/>		<input type="checkbox"/>	Revegetation		<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Effluent Standard		<input type="checkbox"/>		<input checked="" type="checkbox"/>	Haul Roads		<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Diversions and Conveyance		<input type="checkbox"/>		<input checked="" type="checkbox"/>	General Safety		<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Sediment Control Measures		<input type="checkbox"/>		<input checked="" type="checkbox"/>	Permit Conditions		<input type="checkbox"/>	
<input type="checkbox"/>	Treatment Facilities		<input type="checkbox"/>		<input type="checkbox"/>	Temporary Mining Cessation		<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Sedimentation Ponds		<input type="checkbox"/>		<input checked="" type="checkbox"/>	Distance Limitations-Barriers		<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Discharge Structures		<input type="checkbox"/>		<input checked="" type="checkbox"/>	Bench Development		<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Dams, Ponds-Design/Const./Maint.		<input type="checkbox"/>		<input checked="" type="checkbox"/>	Permit Line Setback		<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Water Monitoring-Ground/Surface		<input type="checkbox"/>		<input type="checkbox"/>	Stability Analysis		<input type="checkbox"/>	
<input type="checkbox"/>	Water Discharge-Underground Mine		<input type="checkbox"/>		<input checked="" type="checkbox"/>	Blasting Requirement		<input type="checkbox"/>	

COMMENTS AND RECOMMENDATIONS:

This partial inspection was conducted to collect noise readings. The results were as follows:

Location 1- on site near the pile of railroad ties
N 40° 24' 21"
W 75° 18, 19"

Noise readings were between 38-42 dB with the crusher and other equipment running. A backup alarm was heard and registered 52 dB.

Location 2- along Rockhill Rd. near swale to NW of driveway
N 40° 24, 19"
W 75° 18, 23"

Noise readings were between 55-64 dB with the crusher and other equipment running. A car driving past this location registered 74 dB.

Person Contacted Mr. Darren Landis	Title Pierson	Discharge/Seeps: <input type="checkbox"/> yes <input type="checkbox"/> no	Samples Collected: <input type="checkbox"/> yes <input type="checkbox"/> no
Signature	Investigator Signature Amiee Bollinger	Range of Samples Collected	Collector ID No. 4519 Employee ID No. 608058

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

White - District File

Yellow - Permittee

Pink - Inspector