



COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF MINING PROGRAMS

Version: 1.2.0.1

Mining Activities Inspection Report

Inspection Type	RTPT - Routine/Partial Inspection	Permit Number	7974SM1
DEP Office	EP DMO Pottsville Dstr Mng Off	NPDES Number	PA0594121
Permittee Name	HANSON AGGREGATES PA LLC	PF Name	HANSON AGGREGATES PA ROCK HILL QUARRY
Address 1	7660 IMPERIAL WAY	Permit Type	IMMO - Industrial Mineral Mining Operation
Address 2		Permit Kind	LARGE - Surface Large
City	ALLENTOWN	License Number	24143
State/ZIP Code	PA 18195-1016	Permit Status	ACTIV - Active
Arrival Date / Time	03/07/2019 09:04 AM	Municipality	East Rockhill Township
Depart Date / Time	03/07/2019 09:27 AM	County	Bucks
Inspection ID	2849695	Enforcement ID	
CTS Number		GP12 Permit Number	

Inspector Details

Inspector Name:	(608058) - AMIEE BOLLINGER	Inspector Telephone Number:	6109160100	Inspector Email:	ambollinge@pa.gov
-----------------	----------------------------	-----------------------------	------------	------------------	-------------------

Expiration Dates

Mining License	12/31/2019	Contractor License	08/31/2019
Mining Permit	07/19/2023	NPDES Permit	07/19/2023

Person Notified

Name	Title
Method	Date --/--/----

Inspection Result

NOVIO - No Violations Noted

Findings

Operations

Mining Operation

Inspected

Remark

This Report is official notification that a representative of the Department of Environmental Protection has conducted an investigation of your operation. Violations observed by the Department have been noted on this report form.

If the Department uncovers any violations based on laboratory reports or further consideration of the conditions described in this report, the District Office will notify you of such violations in writing.

If an order was issued by the Department, you will be provided with a written confirmation of that order. You should not wait until you receive this confirmation Order before taking appropriate action.

This report does not constitute an order or other appealable action of the Department. Nothing contained herein shall be deemed to grant or imply immunity from legal actions for any violation noted herein.

General Comments

Both front and back gates locked. No activity. Large tree has fallen across the back entrance road.